

序号	报告编号	发布日期	结论	影像资料
293	GX-B1306/21-2-23005	2023/1/29	除上述问题外，其余所检项目合格。	 A photograph showing two workers in a control room. They are wearing hard hats and safety glasses. One worker is standing and looking at a large blue panel, while the other is kneeling and working on a piece of equipment. The date stamp '2023/1/29' is visible in the bottom right corner.
294	GX-B1306/21-2-23006	2023/1/29	除上述问题外，其余所检项目合格。	 A photograph showing two workers in a control room, similar to the previous image. They are wearing hard hats and safety glasses. One worker is standing and looking at a large blue panel, while the other is kneeling and working on a piece of equipment. The date stamp '2023/01/29' is visible in the bottom right corner.

295	GX-B1306/21-2-23007	2023/1/29	除上述问题外，其余所检项目合格。	
296	GX-B1306/21-2-23008	2023/1/29	除上述问题外，其余所检项目合格。	
297	GX-B1310/21-2-23006	2023/1/29	未发现超过Φ2mm当量直径的缺陷。	

298	GX-B1310/21-2-23007	2023/1/29	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
299	GX-B1310/21-2-23008	2023/1/29	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
300	GX-B1310/21-2-23009	2023/1/29	符合标准要求。	

301	GX-B1310/21-2-23010	2023/1/29	符合标准要求。			
302	GX-B1310/21-2-23011	2023/1/29	符合标准要求。			
303	GX-B1310/21-2-23012	2023/1/29	符合标准要求。			

304	GX-B1310/21-2-23013	2023/1/29	符合标准要求。	
305	GX-B1428/21-2-23006	2023/1/29	无缺陷迹痕显示。	
306	GX-B1428/21-2-23007	2023/1/29	无缺陷迹痕显示。	
307	GX-B1328/20-2-23001	2023. 1. 29	合格	

308	GX-B1328/20-2-23002	2023. 1. 29	合格	
309	GX-B1354/20-2-23001	2023. 1. 30	电网接地电容电流符合规定	
310	GX-B1352/21-2-23001~23017	2023. 1. 30	本次共检矿用防爆低压交流真空馈电开关17台, 17台所检项目合格。	
311	GX-B1352/21-2-23018~23043	2023. 1. 30	本次共检矿用防爆低压交流真空馈电开关26台, 26台所检项目合格。	

312	GX-B1352/21-2-23044~23045	2023. 1. 30	<p>本次共检矿用防爆低压交流真空馈电开关漏电保护 2台,2台所检项目合格。</p>		
313	GX-B1404/20-2-23001	2323. 1. 31	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		
314	GX-B1404/20-2-23002	2323. 1. 31	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>		

315	GX-B1517/20-2-23001	2323. 1. 31	综合判定：合格	 A photograph showing two workers in blue uniforms and red hard hats standing in a dimly lit tunnel. They appear to be inspecting or working on a piece of equipment. The date '2023/01/05' is visible in the bottom right corner of the image.
316	GX-B1517/20-2-23002	2323. 1. 31	综合判定：合格	 A close-up photograph of a worker wearing a red hard hat, safety glasses, and a white face mask. The worker is wearing orange gloves and is focused on a task, possibly handling equipment or cables. The date '2023/01/05' is visible in the bottom right corner of the image.
317	GX-B1517/20-2-23003	2323. 1. 31	综合判定：合格	 A photograph of a worker in a blue uniform and red hard hat standing in a tunnel. The worker is looking at a piece of equipment or a control panel. The date '2023/01/05' is visible in the bottom right corner of the image.

318	GX-B1517/20-2-23004	2323. 1. 31	综合判定：合格	 A photograph showing three workers in blue uniforms and red hard hats standing in a tunnel. The date '2023/01/06' is visible in the bottom right corner.
319	GX-B1517/20-2-23005	2323. 1. 31	综合判定：合格	 A photograph of a worker in a blue uniform and red hard hat standing next to a red and green piece of equipment in a tunnel. The date '2023/01/06' is visible in the bottom right corner.
320	GX-B1517/20-2-23006	2323. 1. 31	综合判定：合格	 A photograph showing workers in a tunnel. One worker is in the foreground, and another is further back. The date '2023/01/06' is visible in the bottom right corner.

321	GX-B1598/21-2-22142	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.05%，小于5%为正常。 。	
322	GX-B1598/21-2-22143	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.21%，小于5%为正常。 。	
323	GX-B1598/21-2-22144	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.17%，小于5%为正常。 。	

324	GX-B1598/21-2-22145	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.03%，小于5%为正常。 。	 2022/12/27
325	GX-B1598/21-2-22146	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为1.35%，小于5%为正常。 。	 2022/12/27
326	GX-B1598/21-2-22147	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。 。	 2022/12/27

327	GX-B1598/21-2-22146	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为1.35%，小于5%为正常。		
328	GX-B1598/21-2-22147	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。		
329	GX-B1517/20-2-23001	2023. 1. 31	综合判定：合格。		

330	GX-B1517/20-2-23002	2023. 1. 31	综合判定：合格。		
331	GX-B1517/20-2-23003	2023. 1. 31	综合判定：合格。		
332	GX-B1517/20-2-23004	2023. 1. 31	综合判定：合格。		

333	GX-B1517/20-2-23005	2023. 1. 31	综合判定：合格。		
334	GX-B1517/20-2-23006	2023. 1. 31	综合判定：合格。		
335	GX-B1598/21-2-22142	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.05%，小于5%为正常。 。		

336	GX-B1598/21-2-22143	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.21%，小于5%为正常。 。	
337	GX-B1598/21-2-22144	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.17%，小于5%为正常。 。	
338	GX-B1598/21-2-22145	2023. 1. 31	实测钢丝绳有效截面积损失百分比最大为0.03%，小于5%为正常。 。	

339	GX-B1328/20-2-23003	2023. 1. 31	本次共检绝缘手套25双，25双所检项目合格。	 A photograph showing three workers in a room. One worker is kneeling and working on a piece of equipment on the floor, while two others stand nearby. The room has a window and some equipment on the floor. A timestamp '2023.01.29' is visible in the bottom right corner of the photo.	
340	GX-B1328/20-2-23004	2023. 1. 31	本次共检绝缘鞋25双，25双所检项目合格。	 A photograph showing two workers in a room. One worker is kneeling and working on a piece of equipment on the floor, while the other stands nearby. The room has a window and some equipment on the floor. A timestamp '2023.01.29' is visible in the bottom right corner of the photo.	