





序号	报告编号	发布日期	结论	影像资料
80	GX-B1310/21-5-23049	2023/3/18	符合标准要求。	
81	GX-B1310/21-5-23050	2023/3/18	符合标准要求。	

82	GX-B1310/21-5-23038	2023/3/18	符合标准要求。	
83	GX-B1310/21-5-23039	2023/3/18	符合标准要求。	




84	GX-B1598/21-5-23005	2023/3/17	实测钢丝绳有效截面损失百分比最大3.17%，小于5%为正常。	
85	GX-B1598/21-5-23006	2023/3/17	实测钢丝绳有效截面损失百分比最大为2.98%，小于5%为正常。	

86	GX-B1598/21-5-23001	2023/3/17	实测钢丝绳有效截面损失百分比最大为1.65%，小于5%为正常。	
87	GX-B1598/21-5-23002	2023/3/17	实测钢丝绳有效截面损失百分比最大为0.54%，小于5%为正常。	

88	GX-B1598/21-5-23003	2023/3/17	实测钢丝绳有效截面损失百分比最大为1.95%，小于5%为正常。	 A photograph showing a worker in a blue uniform and red helmet operating a large industrial machine. The machine has a large spool of rope. The worker is standing next to the machine, and the date '2023/1/20' is visible in the bottom right corner of the image.
89	GX-B1598/21-5-23004	2023/3/17	实测钢丝绳有效截面损失百分比最大为4.96%，小于5%为正常。	 A photograph showing a worker in a blue uniform and red helmet operating a large industrial machine. The machine has a large spool of rope. The worker is standing next to the machine, and the date '2023/1/20' is visible in the bottom right corner of the image.

90	GX-B1306/21-5-23008	2023/3/30	所检项目合格	
91	GX-B1306/21-5-23009	2023/3/30	所检项目合格	
92	GX-B1306/21-5-23010	2023/3/30	所检项目合格	

93	GX-B1306/21-5-23011	2023/3/30	所检项目合格	
94	GX-B1306/21-5-23012	2023/3/30	所检项目合格	
95	GX-B1415/22-5-23007	2023/3/30	综合判定：合格	

96	GX-B1416/22-5-23012	2023. 3. 31	合格		
97	GX-B1416/22-5-23013	2023. 3. 31	合格		
98	GX-B1416/22-5-23014	2023. 3. 31	合格		
99	GX-B1416/22-5-23015	2023. 3. 31	合格	