

序号	报告编号	发布日期	结论	影像资料
330	GX-B1363/22-A-23230	2023/5/30	所检项目合格。	 A photograph showing two technicians in light blue work shirts inspecting a large, rusted metal boiler. One technician on the left is wearing yellow gloves and is touching the boiler's door. The technician on the right is looking into the boiler's interior. A date stamp '2023/05/24' is visible in the bottom right corner of the photo. The boiler has a vertical pipe extending upwards from its top.

序号	报告编号	发布日期	结论	影像资料
331	GX-B1363/20-A-23232	2023/5/30	所检项目合格。	 A photograph showing two workers in white uniforms inspecting a large industrial machine. One worker is wearing yellow gloves. A green trash bin is visible on the left. A date stamp '2023/05/24' is in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
332	GX-B1363/20-A-23233	2023/5/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
333	GX-B1369/22-A-23002	2023/5/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
334	GX-B1369/22-A-23003	2023/5/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
335	GX-B1364/20-A-23401	2023/5/26	成束电线电缆燃烧试验不合格;其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
336	GX-B1364/20-A-23400	2023/5/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
337	GX-B1364/20-A-23399	2023/5/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
338	GX-B1366/20-A-23052	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
339	GX-B1365/20-A-23036	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
340	GX-B1364/20-A-23362	2023/5/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
341	GX-B1366/20-A-23031	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
342	GX-B1366/20-A-23030	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
343	GX-B1366/20-A-23033	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
344	GX-B1366/20-A-23032	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
345	GX-B1366/20-A-23051	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
346	GX-B1366/20-A-23050	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1366/20-A-23049	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
348	GX-B1365/20-A-23037	2023/5/26	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
349	GX-B1365/20-A-23038	2023/5/26	所检项目全部合格。	