

序号	报告编号	发布日期	结论	影像资料
136	GX-B1598/21-6-23043	2023/10/13	实测钢丝绳有效截面积损失百分比最大为0.88%，小于5%为正常。	
137	GX-B1598/21-6-23044	2023/10/13	实测钢丝绳有效截面积损失百分比最大为1.15%，小于5%为正常。	

138	GX-B1598/21-6-23045	2023/10/13	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。	
139	GX-B1598/21-6-23046	2023/10/13	实测钢丝绳有效截面积损失百分比最大为1.56%，小于5%为正常。	
140	GX-B1598/21-6-23047	2023/10/13	实测钢丝绳有效截面积损失百分比最大为0.92%，小于5%为正常。	

141	GX-B1598/21-6-23048	2023/10/13	实测钢丝绳有效截面积损失百分比最大为1.26%，小于5%为正常。	
142	GX-B1427/21-6-23073	2023/10/13	符合标准要求	
143	GX-B1310/21-6-23129	2023/10/13	符合标准要求	

144	GX-B1310/21-6-23130	2023/10/13	符合标准要求	
145	GX-B1310/21-6-23131	2023/10/13	符合标准要求	
146	GX-B1310/21-6-23132	2023/10/13	符合标准要求	

147	GX-B1310/21-6-23133	2023/10/13	符合标准要求	
148	GX-B1310/21-6-23134	2023/10/13	符合标准要求	
149	GX-B1310/21-6-23141	2023/10/16	符合标准要求	

150	GX-B1313/21-6-23234	2023/10/16	所检项目合格	
151	GX-B1423/20-6-231026	2023/10/16	综合判定合格	
152	GX-B1423/20-6-231027	2023/10/16	综合判定合格	

153	GX-B1423/20-6-231028	2023/10/16	综合判定合格	
154	GX-B1423/20-6-231029	2023/10/17	综合判定合格	
155	GX-B1423/20-6-231030	2023/10/17	综合判定合格	

156	GX-B1423/20-6-231031	2023/10/17	综合判定合格	
157	GX-B1423/20-6-231032	2023/10/17	综合判定合格	
158	GX-B1423/20-6-231033	2023/10/17	综合判定合格	

159	GX-B1423/20-6-231034	2023/10/17	综合判定合格	 <p>2023 10 14</p>
160	GX-B1520/20-6-23101	2023/10/17	综合判定合格	 <p>2023 10 14</p>
161	GX-B1306/21-6-23015	2023/10/17	所检项目合格	 <p>2023 09 23</p>

162	GX-B1306/21-6-23016	2023/10/17	所检项目合格	
163	GX-B1306/21-6-23017	2023/10/17	所检项目合格	
164	GX-B1306/21-6-23018	2023/10/17	所检项目合格	

165	GX-B1423/20-6-231020	2023/10/18	综合判定合格	
166	GX-B1423/20-6-231021	2023/10/18	综合判定合格	
167	GX-B1423/20-6-231022	2023/10/18	综合判定合格	

168	GX-B1423/20-6-231023	2023/10/18	综合判定合格	
169	GX-B1423/20-6-231024	2023/10/18	综合判定合格	
170	GX-B1423/20-6-231025	2023/10/18	综合判定合格	

171	GX-B1499/21-6-23036	2023/10/18	所检项目合格	 A worker in a blue uniform and red helmet is working on a blue pipe in a tunnel. The worker is holding a tool and looking towards the camera. The date stamp in the bottom right corner of the image is 2023 09 19.
172	GX-B1499/21-6-23037	2023/10/18	所检项目合格	 A worker in a blue uniform and red helmet is kneeling and working on a blue pipe. The worker is holding a tool and looking towards the camera. The date stamp in the bottom right corner of the image is 2023 09 19.
173	GX-B1451/20-6-23680~23681	2023/10/13	所检项目合格	 A worker in a grey uniform and red helmet is kneeling and working on a grey electrical cabinet. The worker is holding a tool and looking towards the camera. The date stamp in the bottom right corner of the image is 2023 10 10.

174	GX-B1328/20-6-23130	2023/10/18	所检项目合格	
175	GX-B1328/20-6-23131	2023/10/18	所检项目合格	
176	GX-B1328/20-6-23132	2023/10/18	所检项目合格	

177	GX-B1328/20-6-23133	2023/10/18	所检项目合格	
178	GX-B1304/21-6-23028	2023/10/18	综合判定合格	
179	GX-B1304/21-6-23029	2023/10/18	综合判定合格	

180	GX-B1324/21-6-23047	2023.10.18	所检项目合格	
181	GX-B1313/21-6-23242~23245	2023/10/18	所检项目合格	
182	GX-B1313/21-6-23235~23240	2023/10/18	所检项目合格	

183	GX-B1423/20-6-231002	2023/10/20	综合判定合格	
184	GX-B1423/20-6-231003	2023/10/20	综合判定合格	
185	GX-B1522/20-6-23010	2023/10/20	所检项目合格	

186	GX-B1522/20-6-23011	2023/10/20	所检项目合格	
187	GX-B1350/21-6-23050	2023/10/20	所检项目合格	
188	GX-B1329/21-6-23109~23110	2023/10/20	<p>本次共检氧化锌避雷器2组，2组氧化锌避雷器所检项目合格。</p>	