






序号	报告编号	发布日期	结论	影像资料
10	GX-B1321/20-2-24082	2024/3/8	所检项目合格。	 <p>2024/02/27</p>
11	GX-B1308/23-2-24001	2024/3/12	综合判定：合格。	 <p>2024/02/26</p>

12	GX-B1499/23-2-24001	2024/3/12	除吨水百米电耗超限外，其余所检项目合格。 吨水百米电耗大于0.5 kW·h。	 <p>2024/02/25</p>
13	GX-B1499/23-2-24002	2024/3/12	除吨水百米电耗超限外，其余所检项目合格。 吨水百米电耗大于0.5 kW·h。	 <p>2024/02/25</p>

14	GX-B1499/23-2-24003	2024/3/12	除吨水百米电耗超限外，其余所检项目合格。 吨水百米电耗大于0.5 kW·h。	 <p>2024/02/25</p>
15	GX-B1499/23-2-24004	2024/3/12	除吨水百米电耗超限外，其余所检项目合格。 吨水百米电耗大于0.5 kW·h。	 <p>2024/02/25</p>

16	GX-B1499/23-2-24005	2024/3/12	除吨水百米电耗超限外，其余所检项目合格。 吨水百米电耗大于0.5 kW·h。	
17	GX-B1499/23-2-24006	2024/3/12	除吨水百米电耗超限外，其余所检项目合格。 吨水百米电耗大于0.5 kW·h。	



18	GX-B1499/23-2-24007	2024/3/12	除吨水百米电耗超限外，其余所检项目合格。 吨水百米电耗大于0.5 kW•h。			
19	GX-B1499/23-2-24008	2024/3/12	除吨水百米电耗超限外，其余所检项目合格。 吨水百米电耗大于0.5 kW•h。			

20	GX-B1329/21-2-24001~24008	2024/3/12	本次共检氧化锌避雷器8组，8组所检项目合格。	
21	GX-B1451/20-2-24001~24006	2024/3/12	本次共检高压开关柜6台，6台所检项目合格。 。	


22	GX-B1451/20-2-24007~24023	2024/3/12	本次共检高压开关柜17台，17台高压开关柜所检项目合格。	
23	GX-B1451/20-2-24024~24029	2024/3/12	本次共检高压开关柜6台，6台所检项目合格。 。	

24	GX-B1451/20-2-24030~24050	2024/3/12	本次共检高压开关柜21台，21台所检项目合格。		
25	GX-B1451/20-2-24051~24052	2024/3/12	本次共检高压开关柜2台，2台高压开关柜所检项目合格。		

26	GX-B1451/20-2-24053~24068	2024/3/12	本次共检高压开关柜16台，16台所检项目合格。	 <p>2024/03/08</p>
27	GX-B1598/21-2-24032	2024. 3. 15	实测钢丝绳有效截面积损失百分比最大为1.05%，小于5%为正常。	 <p>2024/03/15</p>

28	GX-B1598/21-2-24033	2024. 3. 15	实测钢丝绳有效截面积损失百分比最大为1.15%，小于5%为正常。 。	 <p>A photograph showing a worker in a red safety vest and white shirt standing on a metal platform inside a vertical shaft. The worker is inspecting a steel cable. The shaft is lined with concrete and has several vertical steel rods. A red safety railing is visible in the foreground. A date stamp '2024/03/07' is in the bottom right corner.</p>
29	GX-B1598/21-2-24034	2024. 3. 15	实测钢丝绳有效截面积损失百分比最大为1.32%，小于5%为正常。 。	 <p>A photograph showing a worker in a white shirt and dark pants standing on a metal platform inside a vertical shaft. The worker is inspecting a steel cable. The shaft is lined with concrete and has several vertical steel rods. A red safety railing is visible in the foreground. A date stamp '2024/03/07' is in the bottom right corner.</p>

30	GX-B1598/21-2-24035	2024. 3. 15	实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。 。	 <p>2024.03.07</p>
31	GX-B1598/21-2-24036	2024. 3. 15	实测钢丝绳有效截面积损失百分比最大为1.29%，小于5%为正常。 。	 <p>2024.03.07</p>

32	GX-B1598/21-2-24037	2024. 3. 15	实测钢丝绳有效截面积损失百分比最大为1.14%，小于5%为正常。 。	
----	---------------------	-------------	---------------------------------------	---