


序号	报告编号	发布日期	结论	影像资料
21	GX-B1310/21-5-23185	2023. 7. 6	符合标准要求。	
22	GX-B1310/21-5-23186	2023. 7. 6	符合标准要求。	

23	GX-B1310/21-5-23187	2023. 7. 6	符合标准要求。	
24	GX-B1310/21-5-23188	2023. 7. 6	符合标准要求。	

25	GX-B1310/21-5-23189	2023. 7. 6	符合标准要求。	
26	GX-B1310/21-5-23190	2023. 7. 6	符合标准要求。	

27	GX-B1310/21-5-23191	2023. 7. 6	符合标准要求。	
28	GX-B1310/21-5-23192	2023. 7. 6	符合标准要求。	

29	GX-B1310/21-5-23193	2023. 7. 6	符合标准要求。	
30	GX-B1310/21-5-23194	2023. 7. 6	符合标准要求。	

31	GX-B1310/21-5-23195	2023. 7. 6	符合标准要求。	
32	GX-B1310/21-5-23196	2023. 7. 6	符合标准要求。	

33	GX-B1310/21-5-23197	2023. 7. 6	符合标准要求。	
34	GX-B1310/21-5-23198	2023. 7. 6	符合标准要求。	

35	GX-B1310/21-5-23199	2023. 7. 6	符合标准要求。	
36	GX-B1310/21-5-23200	2023. 7. 6	符合标准要求。	

37	GX-B1310/21-5-23201	2023. 7. 6	符合标准要求。	
38	GX-B1310/21-5-23202	2023. 7. 6	符合标准要求。	

39	GX-B1310/21-5-23203	2023. 7. 6	符合标准要求。	
40	GX-B1310/21-5-23204	2023. 7. 6	符合标准要求。	

41	GX-B1310/21-5-23205	2023. 7. 6	符合标准要求。	
42	GX-B1328/20-5-23128	2023. 7. 6	本次共检绝缘手套 86只，86只绝缘手套合 格。	

43	GX-B1328/20-5-23129	2023.7.6	本次共检绝缘鞋82只， 82只绝缘鞋合格。	
44	GX-B1328/20-5-23130	2023.7.6	本次共检携带式接地和 接地短路装置32套，32 套携带式接地和接地短 路装置合格。	

45	GX-B1328/20-5-23131	2023. 7. 6	本次共检验电器32套， 32套验电器合格。	
46	GX-B1300/20-5-23015	2023. 7. 6	所检项目合格。	

47	GX-B1300/20-5-23017	2023. 7. 7	所检项目合格。	
48	GX-B1306/21-5-23051	2023. 7. 7	所检项目合格。	

49	GX-B1306/21-5-23054	2023. 7. 7	所检项目合格。	
50	GX-B1306/21-5-23052	2023. 7. 7	所检项目合格。	

51	GX-B1306/21-5-23053	2023. 7. 7	所检项目合格。	
52	GX-B1495/20-5-231619~231642	2023. 7. 7	本次共检高压防爆开关24台，24台高压防爆开关所检项目合格。	

53	GX-B1495/20-5-231643~231660	2023. 7. 7	本次共检高压防爆开关18台，18台高压防爆开关所检项目合格。	
54	GX-B1495/20-5-231661	2023. 7. 7	所检项目合格。	

55	GX-B1328/20-5-23126	2023. 7. 10	本次共检绝缘手套 26只，26只绝缘手套合 格。		
56	GX-B1328/20-5-23127	2023. 7. 10	本次共检绝缘鞋26只， 26只绝缘鞋合格。		

57	GX-B1415/22-5-23011	2023/7/11	综合判定：合格。	 <p>2023/4/11</p>
58	GX-B1310/21-5-23179	2023/7/7	符合标准要求。	 <p>2023/6/10</p>


59	GX-B1416/22-5-23073	2023/7/11	综合判定：合格。			
60	GX-B1416/22-5-23074	2023/7/11	综合判定：合格。			

61	GX-B1416/22-5-23075	2023/7/11	综合判定：合格。		 <p>2023年6月24日</p>
62	GX-B1416/22-5-23078	2023/7/11	综合判定：合格。		 <p>2023年6月24日</p>

63	GX-B1416/22-5-23079	2023/7/11	综合判定：合格。		 <p>2023年6月24日</p>	
64	GX-B1416-22-5-23072	2023. 7. 11	综合判定：合格。		 <p>2023年6月23日</p>	

65	GX-B1416-22-5-23076	2023. 7. 11	综合判定：合格。		 <p>2023年6月23日</p>
66	GX-B1416-22-5-23077	2023. 7. 11	综合判定：合格。		 <p>2023年6月23日</p>

67	GX-B1424/20-5-23029	2023. 7. 13	依据NB/T 10176-2019单 轨吊车综合判定合格； 依据MT/T 220-1990 尾 气所检项目合格。	 <p>2023/06/10</p>
68	GX-B1415/22-5-23011	2023/7/14	综合判定：合格。	 <p>2023/4/11</p>

69	GX-B1424/20-5-23030	2023. 7. 18	依据NB/T 10176-2019单轨吊车所检项目合格。	
70	GX-B1424/20-5-23031	2023. 7. 18	依据NB/T 10176-2020单轨吊车所检项目合格。	

71	GX-B1424/20-5-23032	2023. 7. 18	依据NB/T 10176-2021单轨吊车所检项目合格。	
72	GX-B1424/20-5-23033	2023. 7. 18	依据NB/T 10176-2022单轨吊车所检项目合格。	

73	GX-B1424/20-5-23034	2023. 7. 18	依据NB/T 10176-2023单轨吊车所检项目合格。	
74	GX-B1424/20-5-23035	2023. 7. 18	依据NB/T 10176-2024单轨吊车所检项目合格。	

75	GX-B1495/20-5-231449~231458	2023/7/18	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	 <p>2023/5/15</p>
76	GX-B1495/20-5-231459~231468	2023/7/18	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	 <p>2023/5/16</p>

77	GX-B1495/20-5-231436~231448	2023/7/18	本次共检高压开关柜13台，13台高压开关柜所检项目合格。	
78	GX-B1495/20-5-231469~231477	2023/7/18	本次共检高压开关柜9台，9台高压开关柜所检项目合格。	

79	GX-B1428/21-5-23029	2023. 7. 18	无缺陷迹痕显示。	
80	GX-B1428/21-5-23030	2023. 7. 18	无缺陷迹痕显示。	

81	GX-B1310/21-5-23183	2023. 7. 18	符合标准要求。	
82	GX-B1310/21-5-23184	2023. 7. 18	符合标准要求。	

83	GX-B1310/21-5-23180	2023. 7. 19	符合标准要求。	
84	GX-B1310/21-5-23181	2023. 7. 19	符合标准要求。	

85	GX-B1310/21-5-23182	2023. 7. 19	符合标准要求。	
86	GX-B1495/20-5-231708-231709	2023. 7. 19	所检项目合格	

87	GX-B1328/20-5-23132	7.20	本次共检绝缘手套 168只，168只绝缘手套 合格。	
88	GX-B1328/20-5-23133	7.20	本次共检绝缘鞋140只， 140只绝缘鞋合格。	

89	GX-B1321/20-5-23829	7.20	所检项目合格。	
90	GX-B1598/21-5-23032	2023/7/20	实测钢丝绳有效截面积 损失百分比最大为 4.96%，小于5%为正常。	

91	GX-B1598/21-5-23033	2023/7/20	实测钢丝绳有效截面积 损失百分比最大为 2.06%，小于5%为正常。	
92	GX-B1598/21-5-23034	2023/7/20	实测钢丝绳有效截面积 损失百分比最大为 1.24%，小于5%为正常。	

93	GX-B1598/21-5-23035	2023/7/20	实测钢丝绳有效截面积 损失百分比最大为 2.03%，小于5%为正常。	
94	GX-B1598/21-5-23041	2023/7/20	实测钢丝绳有效截面积 损失百分比最大为 3.03%，小于5%为正常。	

95	GX-B1598/21-5-23042	2023/7/20	实测钢丝绳有效截面积 损失百分比最大3.21%， 小于5%为正常。	
96	GX-B1310/21-5-23176	2023. 7. 21	符合标准要求。	

97	GX-B1427/21-5-23016	2023. 7. 21	符合标准要求。	
98	GX-B1312/20-5-22469	2023. 7. 21	所检项目合格	