







序号	报告编号	发布日期	结论	影像资料
99	GX-B1598/24-6-24071	2024/8/20	实测钢丝绳有效截面积损失百分比最大为0.80%，小于5%为正常。 。	
100	GX-B1598/24-6-24072	2024/8/20	实测钢丝绳有效截面积损失百分比最大为0.75%，小于5%为正常。 。	

101	GX-B1598/24-6-24073	2024/8/20	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。 。	 2024 07 07	
102	GX-B1598/24-6-24074	2024/8/20	实测钢丝绳有效截面积损失百分比最大为0.72%，小于5%为正常。 。	 2024 07 07	
103	GX-B1598/24-6-24075	2024/8/20	实测钢丝绳有效截面积损失百分比最大为0.61%，小于5%为正常。 。	 2024 07 08	

104	GX-B1598/24-6-24076	2024/8/20	实测钢丝绳有效截面积损失百分比最大为0.66%，小于5%为正常。 。	 <p>2024 07 08</p>
105	GX-B1515/22-6-24002	2024/8/23	所检项目合格	 <p>2024 08 03</p>
106	GX-B1515/22-6-24003	2024/8/23	所检项目合格	 <p>2024 08 03</p>

107	GX-B1324/21-6-24054~24055	2024/8/23	所检项目合格		
108	报告编号:GX-B1305/21-6-24022 替换报告编号:GX-B1305/21-6-24017	8月23日	综合判定:合格。		
109	GX-B1310/21-6-24237	2024/8/23	符合标准要求		

110	GX-B1310/21-6-24238	2024/8/23	符合标准要求	
111	GX-B1310/21-6-24239	2024/8/23	符合标准要求	
112	GX-B1427/21-6-24071	2024/8/23	符合标准要求	

113	GX-B1427/21-6-24072	2024/8/23	符合标准要求		
114	GX-B1427/21-6-24073	2024/8/23	符合标准要求		
115	GX-B1303/21-6-24027	2024/8/23	综合判定合格		









116	GX-B1303/21-6-24028	2024/8/23	综合判定合格		
117	GX-B1598/24-6-24065	2024/8/20	实测钢丝绳有效截面积损失百分比最大为2.05%，小于5%为正常。 。		
118	GX-B1598/24-6-24066	2024/8/20	实测钢丝绳有效截面积损失百分比最大为1.92%，小于5%为正常。 。		

119	GX-B1598/24-6-24067	2024/8/20	实测钢丝绳有效截面积损失百分比最大为2.15%，小于5%为正常。 。		
120	GX-B1598/24-6-24068	2024/8/20	实测钢丝绳有效截面积损失百分比最大为2.10%，小于5%为正常。 。		
121	GX-B1598/24-6-24069	2024/8/20	实测钢丝绳有效截面积损失百分比最大为2.03%，小于5%为正常。 。		





122	GX-B1598/24-6-24070	2024/8/20	实测钢丝绳有效截面积损失百分比最大为2.01%，小于5%为正常。 。		
123	GX-B1310/21-6-24236	2024/8/23	符合标准要求		
124	GX-B1427/21-6-24070	2024/8/23	符合标准要求		

125	GX-B1598/24-6-24083	2024/8/25	实测钢丝绳有效截面积损失百分比最大为0.88%，小于5%为正常。 。	
126	GX-B1598/24-6-24084	2024/8/25	实测钢丝绳有效截面积损失百分比最大为0.99%，小于5%为正常。 。	
127	GX-B1598/24-6-24085	2024/8/25	实测钢丝绳有效截面积损失百分比最大为0.95%，小于5%为正常。 。	

128	GX-B1598/24-6-24086	2024/8/25	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。 。	 2024 07 08
129	GX-B1598/24-6-24099	2024/8/25	实测钢丝绳有效截面积损失百分比最大为4.11%，小于5%为正常。 。	 2024 07 22
130	GX-B1598/24-6-24100	2024/8/25	实测钢丝绳有效截面积损失百分比最大为4.29%，小于5%为正常。 。	 2024 07

131	GX-B1427/21-6-24067	2024/8/25	符合标准要求		
132	GX-B1427/21-6-24068	2024/8/25	符合标准要求		
133	GX-B1427/21-6-24069	2024/8/25	符合标准要求		

134	GX-B1598/24-6-24077	2024/8/23	实测钢丝绳有效截面积损失百分比最大为1.09%，小于5%为正常。 。	
135	GX-B1598/24-6-24078	2024/8/23	实测钢丝绳有效截面积损失百分比最大为1.16%，小于5%为正常。 。	
136	GX-B1598/24-6-24079	2024/8/23	实测钢丝绳有效截面积损失百分比最大为1.01%，小于5%为正常。 。	



137	GX-B1598/24-6-24080	2024/8/23	<p>实测钢丝绳有效截面积损失百分比最大为1.01%，小于5%为正常。</p> <p>。</p>	 <p>2024 07 07</p>
138	GX-B1598/24-6-24081	2024/8/23	<p>实测钢丝绳有效截面积损失百分比最大为1.14%，小于5%为正常。</p> <p>。</p>	 <p>2024 07 07</p>
139	GX-B1598/24-6-24082	2024/8/23	<p>实测钢丝绳有效截面积损失百分比最大为1.30%，小于5%为正常。</p> <p>。</p>	 <p>2024 07 07</p>



140	GX-B1328/20-6-24097	2024/8/25	所检项目合格	
141	GX-B1328/20-6-24098	2024/8/25	所检项目合格	
142	GX-B1328/20-6-24099	2024/8/25	所检项目合格	

143	GX-B1310/21-6-24227	2024/8/25	符合标准要求		
144	GX-B1310/21-6-24230	2024/8/25	符合标准要求		
145	GX-B1310/21-6-24233	2024/8/25	符合标准要求		

146	GX-B1310/21-6-24228	2024/8/25	符合标准要求		
147	GX-B1310/21-6-24229	2024/8/25	符合标准要求		
148	GX-B1310/21-6-24231	2024/8/25	符合标准要求		

149	GX-B1310/21-6-24232	2024/8/25	符合标准要求	
150	GX-B1310/21-6-24234	2024/8/25	符合标准要求	
151	GX-B1310/21-6-24235	2024/8/25	符合标准要求	

152	GX-B1310/21-6-24240	2024/8/25	符合标准要求	
153	GX-B1310/21-6-24241	2024/8/25	符合标准要求	
154	GX-B1598/24-6-24095	2024/8/25	实测钢丝绳有效截面积损失百分比最大为0.38%，小于5%为正常。	



155	GX-B1598/24-6-24096	2024/8/25	<p>实测钢丝绳有效截面积损失百分比最大为0.34%，小于5%为正常。</p> <p>。</p>	
156	GX-B1598/24-6-24097	2024/8/25	<p>实测钢丝绳有效截面积损失百分比最大为0.30%，小于5%为正常。</p> <p>。</p>	
157	GX-B1598/24-6-24098	2024/8/25	<p>实测钢丝绳有效截面积损失百分比最大为0.33%，小于5%为正常。</p> <p>。</p>	



158	GX-B1598/24-6-24101	2024/8/25	实测钢丝绳有效截面积损失百分比最大为2.13%，小于5%为正常。	
159	GX-B1598/24-6-24102	2024/8/25	实测钢丝绳有效截面积损失百分比最大为2.67%，小于5%为正常。 。	
160	GX-B1598/24-6-24103	2024/8/25	实测钢丝绳有效截面积损失百分比最大为4.35%，小于5%为正常。 。	

161	GX-B1598/24-6-24104	2024/8/25	<p>实测钢丝绳有效截面积损失百分比最大为4.43%，小于5%为正常。</p>	
162	GX-B1404/20-6-24019	2024/8/27	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	
163	GX-B1404/20-6-24020	2024/8/27	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	

164	GX-B1404/20-6-24021	2024/8/27	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	
165	GX-B1404/20-6-24022	2024/8/27	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	
166	GX-B1405/21-6-24001	2024/8/27	所检电能质量 供电电压偏差符合GB/T 12325-2008《电能质量 供电电压偏差》标准要求。	




167	GX-B1405/21-6-24002	2024/8/27	所检电能质量 供电电压偏差符合GB/T 12325-2008《电能质量 供电电压偏差》标准要求。	
168	GX-B1405/21-6-24003	2024/8/27	所检电能质量 供电电压偏差符合GB/T 12325-2008《电能质量 供电电压偏差》标准要求。	
169	GX-B1408/21-6-24001	2024/8/28	所检电能质量电力系统频率偏差符合GB/T 15945-2008《电能质量 电力系统频率偏差》标准要求。	

170	GX-B1408/21-6-24002	2024/8/28	<p>所检电能质量电力系统频率偏差符合GB/T 15945-2008 《电能质量 电力系统频率偏差》标准要求。</p>	
171	GX-B1408/21-6-24003	2024/8/28	<p>所检电能质量电力系统频率偏差符合GB/T 15945-2008 《电能质量 电力系统频率偏差》标准要求。</p>	
172	GX-B1598/24-6-24087	2024/8/27	<p>实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。</p>	



173	GX-B1598/24-6-24088	2024/8/27	实测钢丝绳有效截面积损失百分比最大为1.44%，小于5%为正常。 。	
174	GX-B1598/24-6-24089	2024/8/27	实测钢丝绳有效截面积损失百分比最大为1.76%，小于5%为正常。 。	
175	GX-B1598/24-6-24090	2024/8/27	实测钢丝绳有效截面积损失百分比最大为1.79%，小于5%为正常。 。	



176	GX-B1598/24-6-24091	2024/8/27	实测钢丝绳有效截面积损失百分比最大为1.64%，小于5%为正常。 。	
177	GX-B1598/24-6-24092	2024/8/27	实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常。 。	
178	GX-B1598/24-6-24093	2024/8/27	实测钢丝绳有效截面积损失百分比最大为1.60%，小于5%为正常。 。	

179	GX-B1598/24-6-24094	2024/8/27	实测钢丝绳有效截面积损失百分比最大为1.68%，小于5%为正常。 。	 2024 07 21
180	GX-1310/21-6-24223	2024/8/28	符合标准要求	 2024 06 23
181	GX-1310/21-6-24224	2024/8/28	符合标准要求	 2024 06 23

182	GX-1310/21-6-24225	2024/8/28	符合标准要求	 <p>2024 06 23</p>	
183	GX-1310/21-6-24226	2024/8/28	符合标准要求	 <p>2024 06 23</p>	
184	GX-B1534/20-6-24056	2024/8/29	所检项目合格。	 <p>2024 07 09</p>	