

序号	报告编号	发布日期	结论	影像资料
11	GX-B1341/21-9-22015	2022.6.2	合格	
12	GX-B1341/21-9-22016	2022.6.2	合格	
13	GX-B1341/21-9-22017	2022.6.2	合格	

14	GX-B1343/21-9-22008	2022.6.2	/			
15	GX-B1347/21-9-22004	2022.6.2	/			
16	GX-B1370/21-9-22010	2022年6月6日	合格			
						

17	GX-B1370/21-9-22012	2022. 6. 8	除上述问题外，其余所检项目合格。		
18	GX-B1525/21-9-22001	2022.6.10	所检项目合格		

19	GX-B1525/21-9-22002	2022.6.10	所检项目合格			
20	GX-B1525/21-9-22003	2022.6.10	所检项目合格			
21	GX-B1525/21-9-22004	2022.6.10	所检项目合格			

22	GX-B1371/21-9-22002	2022年6月10日	合格	
				
23	GX-B1371/21-9-22003	2022年6月10日	合格	
				

24	GX-B1340/21-9-22023	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
25	GX-B1340/21-9-22024	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
26	GX-B1340/21-9-22025	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	

27	GX-B1340/21-9-22026	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
28	GX-B1340/21-9-22037	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	
29	GX-B1340/21-9-22038	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。	

30	GX-B1340/21-9-22039	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。		
31	GX-B1340/21-9-22040	6.10	依据AQ1011-2005《煤矿在用主通风机系统安全检测检验规范》进行检验，该通风机合格。		