

序号	报告编号	发布日期	结论	影像资料
95	GX-B1416/22-P-23114	2023. 11. 14	综合判定：合格	 <p>2023.10.10</p>
96	GX-B1416/22-P-23115	2023. 11. 14	综合判定：合格	 <p>2023.10.10</p>

97	GX-B1417/22-P-231747	2023. 11. 15	综合判定：合格	
98	GX-B1523/20-P-23004	2023. 11. 15	所检项目合格	
99	GX-B1310/21-P-23148	2023. 11. 15	符合标准要求	

100	GX-B1310/21-P-23149	2023. 11. 15	符合标准要求	 2023.10.9
101	GX-B1427/21-P-23023	2023. 11. 15	符合标准要求	 2023.10.8
102	GX-B1427/21-P-23024	2023. 11. 15	符合标准要求	 2023.10.9

103	GX-B1310/21-P-23150	2023. 11. 15	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
104	GX-B1428/21-P-23037	2023. 11. 15	无缺陷迹痕显示。	
105	GX-B1300/23-P-23021	2023. 11. 20	综合判定：合格。	

106	GX-B1328/20-P-23077	2023. 11. 20	本次共检绝缘手套24只，24只绝缘手套合格。	 2023.11.10
107	GX-B1328/20-P-23078	2023. 11. 20	本次共检绝缘鞋18只，18只绝缘鞋合格。	 2023.11.10
108	GX-B1301/21-P-23011	2023. 11. 21	综合判定:合格。	 2023.10.5

109	GX-B1301/21-P-23012	2023. 11. 21	综合判定:合格。	
110	GX-B1310/21-P-23153	2023. 11. 21	符合标准要求	
111	GX-B1310/21-P-23154	2023. 11. 21	符合标准要求	

112	GX-B1495/20-P-231107~231123	2023. 11. 22	<p>本次共检高压防爆开关17台，17台高压防爆开关所检项目合格。</p>		
113	GX-B1499/21-P-23109	2023. 11. 23	<p>综合判定：合格。</p>		
114	GX-B1499/21-P-23110	2023. 11. 23	<p>综合判定：合格。</p>		

115	GX-B1499/21-P-23111	2023. 11. 23	综合判定:合格。	
116	GX-B1499/21-P-23113	2023. 11. 23	综合判定:合格。	
117	GX-B1499/21-P-23114	2023. 11. 23	综合判定:合格。	

118	GX-B1328/20-P-23066	2023. 11. 23	<p>本次共检绝缘手套8只，8只绝缘手套合格。</p>	
119	GX-B1328/20-P-23067	2023. 11. 23	<p>本次共检绝缘鞋4只，4只绝缘鞋合格。</p>	