




序号	报告编号	发布日期	结论	影像资料
161	GX-B1312/20-5-22187	2022/5/30	合格	
162	GX-B1323/21-5-22099~22102	2022/5/30	合格	




163	GX-B1321/20-5-22314~22323	2022/5/30	合格		
164	GX-B1321/20-5-22325~22328	2022/5/30	合格		

165	GX-B1321/20-5-22278~22287	2022/5/30	合格	
166	GX-B1321/20-5-22307~22313	2022/5/30	合格	



167	GX-B1328/20-5-22055~22058	2022/5/30	合格	 <p>2022. 4. 16</p>
168	GX-B1321/20-5-22263~22268	2022/5/30	合格	 <p>2022. 4. 17</p>


169	GX-B1321/20-5-22329~22339	2022/5/30	合格	
170	GX-B1354/20-5-22008	2022. 6. 8	电网接地电容 电流符合规定	
171	GX-B499/21-5-22079	2022/6/8	除吨水百米电耗	

172	GX-B499/21-5-22080	2022/6/8	除吨水百米电耗	
173	GX-B499/21-5-22081	2022/6/8	除吨水百米电耗	
174	GX-B1404/20-5-22019	2022. 6. 8	合格	

175	GX-B1404/20-5-22020	2022. 6. 8	合格	
176	GX-B1404/20-5-22021	2022. 6. 8	合格	
177	GX-B1404/20-5-22022	2022. 6. 8	合格	

178	GX-B1404/20-5-22023	2022. 6. 8	合格	
179	GX-B1310/21-5-22132	2022/6/7	符合标准要求	
180	GX-B1427/21-5-22007	2022/6/7	符合标准要求	

181	GX-B1310/21-5-22133	2022/6/7	符合标准要求	 <p>A worker wearing a red protective suit and a red helmet is working on a large, blue industrial machine. The machine has several circular openings and a complex structure. The worker is focused on a task, possibly inspecting or adjusting a component. A red date stamp '2022/4/28' is visible in the bottom right corner of the image.</p>
182	GX-B1427/21-5-22008	2022/6/7	符合标准要求	 <p>A worker in a red protective suit is working in a large industrial facility. The worker is positioned in the center of the frame, surrounded by blue structural elements and machinery. The floor is marked with yellow and black safety stripes. A red date stamp '2022/4/28' is visible in the bottom right corner of the image.</p>

183	GX-B1310/21-5-22134	2022/6/7	符合标准要求	
184	GX-B1428/21-5-22017	2022/6/7	符合标准要求	