

序号	报告编号	发布日期	结论	影像资料
122	GX-B1310/21-5-22160	2022/7/12	符合标准要求	 A photograph showing three workers in a factory setting. One worker in a blue shirt and red helmet is leaning over a large blue industrial machine, possibly a turbine or generator. Two other workers, one in an orange jumpsuit and one in a grey shirt, are standing nearby observing. The date '2022/6/14' is visible in the bottom right corner of the photo.
123	GX-B1310/21-5-22161	2022/7/12	符合标准要求	 A close-up photograph of a worker in a blue shirt and red helmet inspecting a large red and green industrial machine. The worker is leaning over the machine, which has a prominent red section and a green section. The date '2022/6/14' is visible in the bottom right corner of the photo.

124	GX-B1310/21-5-22162	2022/7/12	符合标准要求	
125	GX-B1310/21-5-22163	2022/7/12	符合标准要求	

126	GX-B1310/21-5-22164	2022/7/12	符合标准要求	
127	GX-B1310/21-5-22165	2022/7/12	符合标准要求	

128	GX-B1310/21-5-22166	2022/7/12	符合标准要求	
129	GX-B1310/21-5-22167	2022/7/12	符合标准要求	

130	GX-B1310/21-5-22168	2022/7/12	符合标准要求		
131	GX-B1310/21-5-22169	2022/7/12	符合标准要求		

132	GX-B1310/21-5-22170	2022/7/12	符合标准要求	
133	GX-B1310/21-5-22171	2022/7/12	符合标准要求	

134	GX-B1310/21-5-22172	2022/7/12	符合标准要求	 <p>2022/6/18</p>
135	GX-B1310/21-5-22173	2022/7/12	符合标准要求	 <p>2022/6/18</p>

136	GX-B1427/21-5-22010	2022/7/12	符合标准要求	
137	GX-B1427/21-5-22011	2022/7/12	符合标准要求	

138	GX-B1310/21-5-22191	2022/7/13	符合标准要求	
139	GX-B1310/21-5-22174	2022/7/8	符合标准要求	

140	GX-B1310/21-5-22175	2022/7/8	符合标准要求	 <p>A worker wearing a blue uniform and a red hard hat is inspecting a large, green industrial machine. The machine has a curved, cylindrical shape with various pipes and components. The worker is leaning over the machine, looking at something. The background shows an industrial setting with concrete walls and a metal railing. A red date stamp '2022/6/21' is visible in the bottom right corner of the image.</p>
141	GX-B1310/21-5-22178	2022/7/8	符合标准要求	 <p>A worker wearing a blue uniform and a red hard hat is inspecting a large, blue industrial machine. The machine has a curved, cylindrical shape with various pipes and components. The worker is leaning over the machine, looking at something. The background shows an industrial setting with concrete walls and a metal railing. A red date stamp '2022/6/21' is visible in the bottom right corner of the image.</p>

142	GX-B1310/21-5-22182	2022/7/8	符合标准要求	 <p>2022/6/22</p>
143	GX-B1310/21-5-22185	2022/7/8	符合标准要求	 <p>2022/6/23</p>

144	GX-B1427/21-5-22012	2022/7/8	符合标准要求	
145	GX-B1427/21-5-22013	2022/7/8	符合标准要求	

146 GX-B1310/21-5-22192

2022/7/15 符合标准要求



147	GX-B1310/21-5-22192	2022/7/15	符合标准要求	 <p>2022/6/24</p>
148	GX-B1354/20-5-22010	2022-7-12	电网接地电容电流符合规定。	 <p>2022/7/2</p>

149	GX-B1310/21-5-22188	2022/7/15	符合标准要求	
150	GX-B1310/21-5-22189	2022/7/15	符合标准要求	

151	GX-B1310/21-5-22190	2022/7/15	符合标准要求	
152	GX-B1310/21-5-22159	2022/7/15	符合标准要求	

153	GX-B1310/21-5-22150	2022/7/15	符合标准要求	
154	GX-B1428/21-5-22026	2022/7/11	符合标准要求	

155	GX-B1428/21-5-22027	2022/7/11	符合标准要求	
156	GX-B1424/20-5-22011	2022/7/18	合格	

157	GX-B1312/20-5-22437	2022. 7. 18	合格		
-----	---------------------	-------------	----	---	--