

序号	报告编号	发布日期	结论	影像资料
714	GX-B1561/20-Y-22005	2022年7月22日	合格	
715	GX-B1521/20-Y-22226	2022年7月22日	合格	


716	GX-B1423/20-Y-222908	2022年7月22日	合格	 <p>A yellow dump truck is parked on a gravel surface. Two workers, one in a green uniform and red helmet, and another in a blue shirt, stand in front of the truck. The truck has '11' on its side. A date stamp '2022/7/15' is visible in the bottom right corner of the photo.</p>
717	GX-B1423/20-Y-222909	2022年7月22日	合格	 <p>A yellow dump truck is parked on a gravel surface. Two workers, one in a green uniform and red helmet, and another in a blue shirt, stand in front of the truck. The truck has '10' on its side. A date stamp '2022/7/15' is visible in the bottom right corner of the photo.</p>

718	GX-B1423/20-Y-222910	2022年7月22日	合格	
719	GX-B1561/20-Y-22006	2022年7月22日	合格	

720	GX-B1521/20-Y-22224	2022年7月22日	合格	 A photograph showing a person wearing a red hard hat and a light-colored uniform operating a Doosan excavator. The person is seated in the cab, looking down at a device or document. The excavator's orange arm is visible on the left. A yellow timestamp '2022/7/15' is in the bottom right corner of the photo.
721	GX-B1521/20-Y-22225	2022年7月22日	合格	 A photograph showing a person wearing a red hard hat and a light-colored uniform operating a Doosan excavator. The person is seated in the cab, looking down at a device or document. The excavator's orange arm is visible on the left. A yellow timestamp '2022/7/15' is in the bottom right corner of the photo.

722	GX-B1423/20-Y-222906	2022年7月22日	合格	 A yellow dump truck with the number '09' on its side is parked on a gravel surface. Two men are standing next to it: one in a dark uniform and another in a white t-shirt. A yellow date stamp '2022/7/15' is visible in the bottom right corner of the photo.
723	GX-B1423/20-Y-222907	2022年7月22日	合格	 A yellow dump truck with the number '08' on its side is parked on a gravel surface. Two men are standing next to it: one in a dark uniform and another in a white t-shirt. A yellow date stamp '2022/7/15' is visible in the bottom right corner of the photo.

724	GX-B1415/22-Y-22017	2022年7月22日	合格	
725	GX-B1310/21-Y-22110	2022年7月22日	合格	

726	GX-B1310/21-Y-22111	2022年7月22日	合格	 <p>A photograph showing a large industrial spool of wire being processed by a machine in a factory setting. The machine is green and red, and the spool is dark grey. The date stamp '2022/7/13' is visible in the bottom right corner.</p>
727	GX-B1310/21-Y-22112	2022年7月22日	合格	 <p>A photograph showing a worker in a red hard hat and dark uniform inspecting a large industrial component. The worker is holding a device, possibly a scanner or camera, and is looking at the component. The date stamp '2022/7/14' is visible in the bottom right corner.</p>

728	GX-B1310/21-Y-22113	2022年7月22日	合格	
-----	---------------------	------------	----	---

729	GX-B1328/20-Y-22057	2022年7月20日	合格	 A photograph showing a person kneeling on a concrete floor in a room. The person is wearing a grey jacket and dark pants. To the left of the person is a dark wooden chair. In the foreground, there is a white bucket with a red label and a red container. A yellow bag is on the floor near the person. The wall behind the person has a blue frame around a window or door. A yellow timestamp '2022/6/3' is visible in the bottom right corner of the photo.
730	GX-B1328/20-Y-22058	2022年7月20日	合格	 A photograph showing a person kneeling on a concrete floor in a room, similar to the one above. The person is wearing a grey jacket and dark pants. To the left of the person is a dark wooden chair. In the foreground, there is a white bucket with a red label and a red container. A yellow bag is on the floor near the person. The wall behind the person has a blue frame around a window or door. A yellow timestamp '2022/6/3' is visible in the bottom right corner of the photo.

731	GX-B1328/20-Y-22060	2022年7月20日	合格	 A photograph showing a worker sitting on the floor in a room with blue window frames. A red fire extinguisher is visible on the floor. The date 2022/8/3 is printed in the bottom right corner.
732	GX-B1328/20-Y-22061	2022年7月20日	合格	 A photograph showing a worker sitting on the floor in a room with blue window frames. A red fire extinguisher is visible on the floor. The date 2022/8/3 is printed in the bottom right corner.

733	GX-B1328/20-Y-22066	2022年7月25日	合格	
734	GX-B1300/20-Y-22011	2022年7月24日	合格	

735	GX-B1515/20-Y-22003	2022年7月24日	合格	
736	GX-B1312/20-Y-22286~22287	2022年7月25日	合格	

737	GX-B1321/20-Y-22367~22368	2022年7月25日	合格	 A photograph showing a worker in a blue uniform and a dark helmet with a headlamp, kneeling and operating a large, red industrial machine. The machine has a prominent cylindrical component. A yellow timestamp '2022/7/14' is visible in the bottom right corner of the image.
738	GX-B1495/20-Y-22896~22903	2022年7月25日	合格	 A photograph showing a worker in a blue uniform and a dark helmet with a headlamp, kneeling and working on a large, red industrial machine. The worker is holding a tool or component. A yellow timestamp '2022/7/13' is visible in the bottom right corner of the image.

739	GX-B1350/21-Y-22043	2022年7月25日	合格	
-----	---------------------	------------	----	---