

序号	报告编号	发布日期	结论	影像资料
1	GX-B1522/20-C-22001	2022/8/1	所检项目合格	
2	GX-B1522/20-C-22002	2022/8/1	所检项目合格	
3	GX-B1522/20-C-22003	2022/8/1	所检项目合格	

4	GX-B1522/20-C-22004	2022/8/1	所检项目合格	
5	GX-B1522/20-C-22005	2022/8/1	所检项目合格	
6	GX-B1522/20-C-22006	2022/8/1	所检项目合格	
7	GX-B1522/20-C-22007	2022/8/1	所检项目合格	

8	GX-B1423/20-C-22260	2022/8/1	所检项目合格	
9	GX-B1517/20-C-22021	2022/8/1	综合判定：合格	
10	GX-B1423/20-C-22261	2022/8/2	综合判定：合格	
11	GX-B1423/20-C-22262	2022/8/2	综合判定：合格	

12	GX-B1423/20-C-22263	2022/8/2	综合判定：合格	
13	GX-B1423/20-C-22264	2022/8/2	综合判定：合格	
14	GX-B1423/20-C-22265	2022/8/2	综合判定：合格	

15	GX-B1423/20-C-22266	2022/8/2	综合判定：合格	 A yellow dump truck with a red number '3' on the front. Two men in work clothes stand in front of it. A date stamp '2022/7/16' is in the bottom right corner.
16	GX-B1423/20-C-22267	2022/8/2	综合判定：合格	 A yellow dump truck with a red number '2' on the front. Two men in work clothes stand in front of it. A date stamp '2022/7/16' is in the bottom right corner.
17	GX-B1423/20-C-22268	2022/8/2	综合判定：合格	 A yellow dump truck with a red number '1' on the front. Two men in work clothes stand in front of it. A date stamp '2022/7/16' is in the bottom right corner.

18	GX-B1423/20-C-22269	2022/8/2	综合判定：合格	
19	GX-B1561/20-C-22001	2022/8/3	所检项目合格	
20	GX-B1561/20-C-22002	2022/8/3	所检项目合格	

21	GX-B1383/21-C-22001	2022. 8. 3	所检项目合格。	 A photograph showing two workers wearing red hard hats and dark clothing standing in an industrial facility. They are positioned in front of some machinery and a wall with a blue and white banner. A yellow timestamp '2022/7/15' is visible in the bottom right corner of the image.
22	GX-B1383/21-C-22002	2022. 8. 3	所检项目合格。	 A photograph showing two workers wearing red hard hats and dark clothing standing in an industrial facility. They are positioned in front of some machinery and a wall with a blue and white banner. A yellow timestamp '2022/7/15' is visible in the bottom right corner of the image.
23	GX-B1500/21-C-22001	2022/8/5	合格	 A photograph showing a worker in a light-colored uniform and a red hard hat kneeling on a dirt or concrete surface. The worker is using a handheld electronic device, possibly a detector or a data logger, which is connected to a cable. A yellow timestamp '2022/7/15' is visible in the bottom left corner of the image.

24	GX-B1500/21-C-22002	2022/8/5	合格	
25	GX-B1520/20-C-22001	2022/8/5	综合判定：合格。	
26	GX-B1307/20-C-22002	2022/8/5	综合判定：合格。	

27	GX-B1350/21-C-22001	2022/8/5	所检项目合格	
28	GX-B1313/21-C-22001~ 22002	2022/8/5	所检项目合格	
29	GX-B1329/21-C-22001~ 22002	2022/8/5	共检2组，2组所检项目	

30	GX-B1328/20-C-22005	2022/8/5	所检项目合格	 A photograph showing a person in a white shirt sitting on a paved surface, operating a testing device. The device is connected to a red power source and a yellow stand. A date stamp '2022/7/15' is visible in the bottom left corner of the image.
31	GX-B1561/20-C-22001	2022/8/3	所检项目合格	 A photograph showing a person in a grey shirt working in a confined space, possibly a tunnel or a large pipe. The person is wearing a red hard hat and is surrounded by machinery and structural elements. A date stamp '2022/7/15' is visible in the bottom right corner of the image.
32	GX-B1561/20-C-22002	2022/8/3	所检项目合格	 A photograph showing a person in a grey shirt and a red hard hat working with large rocks or debris. The person is wearing a blue shirt with a logo and is surrounded by a large pile of rocks. A date stamp '2022/7/15' is visible in the bottom right corner of the image.

33	GX-B1539/22-C-22012	2022/8/5	所检项目合格		
34	GX-B1539/22-C-22013	2022/8/5	所检项目合格		
35	GX-B1539/22-C-22014	2022/8/5	所检项目合格		
36	GX-B1539/22-C-22015	2022/8/5	所检项目合格		

37	GX-B1539/22-C-22001	2022/8/5	所检项目合格	
38	GX-B1539/22-C-22002	2022/8/5	所检项目合格	
39	GX-B1539/22-C-22006	2022/8/5	所检项目合格	
40	GX-B1539/22-C-22007	2022/8/5	所检项目合格	

41	GX-B1539/22-C-22008	2022/8/5	所检项目合格	
42	GX-B1539/22-C-22009	2022/8/5	所检项目合格	
43	GX-B1539/22-C-22010	2022/8/5	所检项目合格	
44	GX-B1539/22-C-22011	2022/8/5	所检项目合格	