

序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-Z-22011	2022. 8. 2	符合标准要求	
2	GX-B1310/21-Z-22012	2022. 8. 2	符合标准要求	

3	GX-B1310/21-Z-22013	2022. 8. 2	符合标准要求	
4	GX-B1310/21-Z-22014	2022. 8. 2	符合标准要求	
5	GX-B1310/21-Z-22015	2022. 8. 2	符合标准要求	

6	GX-B1310/21-Z-22016	2022. 8. 2	符合标准要求	 <p>2022 07 16</p>
7	GX-B1310/21-Z-22017	2022. 8. 2	符合标准要求	 <p>2022 07 16</p>
8	GX-B1324 / 21-Z-22003-22004	2022. 8. 2	所检项目合格	 <p>2022 07 16</p>  <p>2022 07 16</p>

9	GX-B1548 / 20-Z-22012	2022. 8. 2	所检项目合格	 <p>2022 08 19</p>
10	GX-B1548 / 20-Z-22013	2022. 8. 2	所检项目合格	 <p>2022 06 19</p>
11	GX-B1548 / 20-Z-22014	2022. 8. 2	所检项目合格	 <p>2022 06 20</p>

12	GX-B1548 / 20-Z-22015	2022. 8. 2	所检项目合格	 A photograph showing a worker wearing a red hard hat and a blue denim jacket operating a green vehicle, possibly a forklift or a small truck. The worker is seen from the side, looking towards the vehicle's controls. A yellow timestamp "2022 06 20" is visible in the bottom right corner of the image.
13	GX-B1517 / 20-Z-22012	2022. 8. 3	综合判定：合格	 A photograph showing a worker in a white t-shirt and blue pants inspecting a red structure, possibly a piece of machinery or a container. The worker is bent over, looking at the ground or the base of the structure. A yellow timestamp "2022 07 26" is visible in the bottom right corner of the image.

14	GX-B1517 / 20-Z-22013	2022. 8. 3	综合判定：合格	 <p>A photograph showing a worker in a grey uniform and red helmet inspecting a red structure. The worker is bent over, looking at the ground. The date '2022.07.26' is visible in the bottom right corner of the image.</p>
15	GX-B1517 / 20-Z-22014	2022. 8. 3	综合判定：合格	 <p>A photograph showing a worker in a white uniform and red helmet inspecting a red structure. The worker is bent over, looking at the ground. The date '2022.07.26' is visible in the bottom right corner of the image.</p>