

序号	报告编号	发布日期	结论	影像资料
38	GX-B1363/22-A-22325	2022/8/4	合格	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1363/22-A-22324	2022/8/5	合格	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1363/22-A-22332	2022/8/5	合格	 <p>The photograph shows two men in light blue work shirts inspecting a large, dark-colored industrial machine, possibly a furnace or boiler, in a room with large windows. The man in the foreground has a logo on his back that reads '中检公信' (China Inspection and Certification). A date stamp '2022/08/02' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
41	GX-B1363/22-A-22336	2022/8/5	合格	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1363/22-A-22338	2022/8/5	合格	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1363/22-A-22337	2022/8/5	合格	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1363/22-A-22335	2022/8/5	合格	

序号	报告编号	发布日期	结论	影像资料
45	GX-B1363/20-A-22330	2022/8/5	合格	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1363/20-A-22331	2022/8/5	合格	