

序号	报告编号	发布日期	结论	影像资料
125	GX-B1561/20-Y-22007	2022. 8. 19	合格	

126	GX-B1521/20-Y-22252	2022. 8. 19	合格	
-----	---------------------	-------------	----	---

127	GX-B1521/20-Y-22253	2022. 8. 19	合格	
128	GX-B1539/22-Y-22173		合格	

129	GX-B1521/20-Y-22254	2022. 8. 22	合格	 A yellow Sdlg excavator is shown in a quarry or construction site. The excavator is positioned on a dirt surface, and its bucket is raised. The background features large, rocky cliffs under a clear sky. A yellow timestamp "2022/8/8" is visible in the bottom right corner of the image.
130	GX-B1539/22-Y-22174	2022. 8. 22	合格	 A yellow Lovol wheel loader is parked on a gravel surface. Two workers in light-colored uniforms and hard hats are standing next to the loader. The background shows a rocky, hilly landscape. A yellow timestamp "2022/8/8" is visible in the bottom right corner of the image.

131	GX-B1306/21-Y-22107	2022年8月23日	合格	
132	GX-B1306/21-Y-22108	2022年8月23日	合格	

133	GX-B1522/20-Y-22062	2022年8月23日	合格	
134	GX-B1522/20-Y-22063	2022年8月23日	合格	
135				

136	GX-B1499/21-Y-22130	2022年8月23日	合格	
137	GX-B1423/20-Y-223090	2022年8月23日	合格	

138	GX-B1423/20-Y-223091	2022年8月23日	合格	
139	GX-B1423/20-Y-223092	2022年8月23日	合格	

140	GX-B1423/20-Y-223093	2022年8月23日	合格	
141	GX-B1423/20-Y-223082	2022年8月23日	合格	

142	GX-B1423/20-Y-223083	2022年8月23日	合格	
143	GX-B1423/20-Y-223084	2022年8月23日	合格	

144	GX-B1423/20-Y-223085	2022年8月23日	合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing red hard hats and light-colored work clothes are standing in front of the truck. The truck has a large dump body and a prominent front grille. A date stamp '2022/8/7' is visible in the bottom right corner of the photo.
145	GX-B1423/20-Y-223086	2022年8月23日	合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing red hard hats and light-colored work clothes are standing in front of the truck. The truck has a large dump body and a prominent front grille. A date stamp '2022/8/7' is visible in the bottom right corner of the photo.

146	GX-B1423/20-Y-223087	2022年8月23日	合格	
147	GX-B1563/21-Y-22002	2022. 8. 23	合格	

148	GX-B1563/21-Y-22001	2022. 8. 23	合格	
149	GX-B1423/20-Y-223088	2022. 8. 23	合格	

150	GX-B1423/20-Y-223089	2022. 8. 23	合格	 A photograph of a yellow dump truck parked in a quarry. Two workers, one in a grey uniform and one in a red shirt, are standing in front of the truck. The background shows rocky terrain and a clear sky. A yellow timestamp '2022/8/23' is visible in the bottom right corner of the photo.
-----	----------------------	-------------	----	---

151	GX-B1306/21-Y-22078	2022年8月25日	合格	
-----	---------------------	------------	----	---

152	GX-B1306/21-Y-22079	2022年8月25日	合格	
-----	---------------------	------------	----	---

153	GX-B1306/21-Y-22080	2022年8月25日	合格	
-----	---------------------	------------	----	---

154	GX-B1354/20-Y-22013	2022年8月26日			
-----	---------------------	------------	--	---	--

155

GX-B1404/20-Y-22017

2022年8月26日



156	GX-B1404/20-Y-22018	2022年8月26日		
-----	---------------------	------------	--	---

157	GX-B1547/20-Y-22045~22046	2022年8月23日	合格	
-----	---------------------------	------------	----	---

158	GX-B1547/20-Y-22047~22055	2022年8月23日	合格	
-----	---------------------------	------------	----	---

159	GX-B1547/20-Y-22056~22061	2022年8月23日	合格	
-----	---------------------------	------------	----	---

160	GX-B1547/20-Y-22062~22066	2022年8月23日	合格	
-----	---------------------------	------------	----	---

161	GX-B1547/20-Y-22045~22046	2022年8月23日	合格	
-----	---------------------------	------------	----	---