

序号	报告编号	发布日期	结论	影像资料
160	GX-B1322/21-2-22131	2022. 8. 24	合格	
161	GX-B1322/21-2-22133~22139	2022. 8. 24	合格	
162	GX-B1380/20-2-22006	2022. 8. 24	合格	

163	GX-B1380/20-2-22007	2022. 8. 24	合格		
164	GX-B1380/20-2-22008	2022. 8. 24	合格		
165	GX-B1313/21-2-22078~22080	2022. 8. 25	合格		

166	GX-B1313/21-2-22081	2022. 8. 25	合格	
167	GX-B1382/21-2-22014	2022. 8. 25	合格	

168	GX-B1451-20-2-22201~22203	2022. 8. 29	合格	
169	GX-B1451-20-2-22204~22210	2022. 8. 29	合格	
170	GX-B1548/20-3-22037	2022年8月29日	所检项目合格	

171	GX-B1548/20-3-22038	2022年8月29日	所检项目合格	 <p>A person in a grey shirt and black shorts is leaning into the open rear door of a yellow vehicle, inspecting the interior. A date stamp '2022.8.24' is visible in the bottom right corner of the photo.</p>
172	GX-B1548/20-3-22039	2022年8月29日	所检项目合格	 <p>A yellow vehicle with red and white reflective stripes is parked on a paved area. A person in a grey shirt and black shorts stands next to the vehicle. A date stamp '2022.8.24' is visible in the bottom right corner of the photo.</p>
173	GX-B1548/20-3-22040	2022年8月29日	所检项目合格	 <p>A person in a grey shirt and black shorts is kneeling on the ground, inspecting the rear of a yellow vehicle. A date stamp '2022.8.24' is visible in the bottom right corner of the photo.</p>

174	GX-B1548/20-3-22041	2022年8月29日	所检项目合格	 A photograph showing a person in a light blue shirt and dark shorts inspecting the interior of a yellow van. The van's rear door is open, and the person is leaning inside. A timestamp '2022.8.24' is visible at the bottom right of the image.
175	GX-B1548/20-3-22042	2022年8月29日	所检项目合格	 A photograph showing a person in a light blue shirt and dark shorts inspecting the side of a yellow van. The person is standing next to the van, looking at the side panel. A timestamp '2022.8.24' is visible at the bottom right of the image.
176	GX-B1548/20-3-22043	2022年8月29日	所检项目合格	 A photograph showing a person in a light blue shirt and dark shorts inspecting the front of a yellow van. The person is standing in front of the van, looking at the front panel. A timestamp '2022.8.24' is visible at the bottom right of the image.

177	GX-B1548/20-3-22044	2022年8月29日	所检项目合格	 A photograph showing a person in a grey shirt and white shorts inspecting the rear of an orange vehicle. The rear door is open, and the person is looking inside. A date stamp '2022.8.25' is visible in the bottom right corner of the image.
178	GX-B1548/20-3-22045	2022年8月29日	所检项目合格	 A photograph showing a person in a grey shirt and black shorts inspecting the side of an orange vehicle. The person is holding a clipboard and looking at it. A date stamp '2022.8.25' is visible in the bottom right corner of the image.
179	GX-B1548/20-3-22046	2022年8月29日	所检项目合格	 A photograph showing a person in a grey shirt and black shorts inspecting the interior of an orange vehicle. The person is leaning over a seat or dashboard area. A date stamp '2022.8.25' is visible in the bottom right corner of the image.

180	GX-B1548/20-3-22047	2022年8月29日	所检项目合格	 A photograph showing two men standing next to a black SUV. One man is wearing a blue work jacket and the other is wearing a light blue t-shirt and a white hard hat. The date '2022.8.25' is visible in the bottom right corner of the image.
181	GX-B1548/20-3-22048	2022年8月29日	所检项目合格	 A photograph showing the interior of a vehicle, likely a truck or bus, with a person sitting in the driver's seat. The date '2022.8.25' is visible in the bottom right corner of the image.
182	GX-B1548/20-3-22049	2022年8月29日	所检项目合格	 A photograph showing a man wearing a white hard hat and a light blue t-shirt standing next to a red truck. The date '2022.8.25' is visible in the bottom right corner of the image.