

序号	报告编号	发布日期	结论	影像资料
208	GX-B1500/21-6-22099	2022/8/10	合格	
209	GX-B1313/21-6-22160	2022/8/18	所检项目合格	
210	GX-B1307/20-6-22046	2022/8/18	综合判定：合格	

211	GX-B1307/20-6-22047	2022/8/18	综合判定：合格			
212	GX-B1307/20-6-22048	2022/8/18	综合判定：合格			
213	GX-B1451/20-6-22525	2022/8/18	所检项目合格			
214	GX-B1322/21-6-22116	2022/8/18	所检项目合格			

215	GX-B1350/21-6-22084	2022/8/18	所检项目合格	
216	GX-B1423/20-6-22718	2022/8/18	合格	
217	GX-B1423/20-6-22719	2022/8/18	合格	
218	GX-B1423/20-6-22720	2022/8/18	合格	

219	GX-B1423/20-6-22721	2022/8/18	合格	
220	GX-B1423/20-6-22722	2022/8/17	合格	
221	GX-B1310/21-6-22102	2022/8/19	符合标准要求	
222	GX-B1310/21-6-22103	2022/8/19	符合标准要求	

223	GX-B1515/22-6-22004	2022/8/19	所检项目合格	
224	GX-B1515/22-6-22005	2022/8/19	所检项目合格	
225	GX-B1404/20-6-22015	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要	
226	GX-B1404/20-6-22016	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要	

227	GX-B1404/20-6-22017	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要			
228	GX-B1404/20-6-22018	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要			
229	GX-B1404/20-6-22019	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要			
230	GX-B1404/20-6-22020	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要			


231	GX-B1404/20-6-22021	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要			
232	GX-B1404/20-6-22022	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要			
233	GX-B1404/20-6-22023	2022/8/22	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要			
234	GX-B1404/20-6-22024	2022/8/22	除 3 次、5 次、7 次和 11 次谐波电流不符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求，其余所检项目符合			

235	GX-B1404/20-6-22025	2022/8/22	除 5 次、7 次和 11 次谐波电流不符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求，其余所检项目符合 GB/T			
236	GX-B1405/21-6-22001	2022/8/22	所检电能质量供电电压偏差符合 GB/T 12325-2008 《电能质量 供电电压偏差》标准要求。			
237	GX-B1405/21-6-22002	2022/8/22	所检电能质量供电电压偏差符合 GB/T 12325-2008 《电能质量 供电电压偏差》标准要求。			
238	GX-B1408/21-6-22001	2022/8/22	所检电能质量电力系统频率偏差符合 GB/T 15945-2008 《电能质量 电力系统频率偏差》标准要求。			

239	GX-B1408/21-6-22002	2022/8/22	所检电能质量 电力系统频率 偏差符合 GB/T 15945-2008 《 电能质量 电 力系统频率偏 差》标准要求 。	
240	GX-B1323/21-6-22224~22227	2022/8/5	合格	
241	GX-B1521/20-6-22011	2022/8/19	合格	

242	GX-B1521/20-6-22012	2022/8/19	合格	 A yellow excavator is shown in operation on a construction site. The excavator's arm is raised, and it appears to be working on a pile of earth or debris. A person in a white shirt and blue pants is visible near the base of the excavator. The background shows a blue sky with some clouds and a fence.
243	GX-B1521/20-6-22013	2022/8/19	合格	 A yellow excavator is shown on a construction site. The excavator is positioned on a dirt mound, and its arm is raised. A person in a red hard hat and white shirt is standing near the excavator. The background shows a blue sky with clouds and a hillside.
244	GX-B1521/20-6-22014	2022/8/19	合格	 A yellow excavator is shown on a construction site. The excavator is positioned on a dirt mound, and its arm is raised. A person in a red hard hat and white shirt is standing near the excavator. The background shows a blue sky with clouds and a hillside.

245	GX-B1521/20-6-22015	2022/8/19	合格	 A worker in a grey uniform and red cap is seated on a piece of machinery, possibly a lathe or mill, in a factory setting. The worker is looking down at something in their hands. The machinery is blue and grey. A date stamp '2022.07.15' is visible in the bottom right corner of the image.
246	GX-B1304/21-6-22018	2022/8/19	合格	 A large industrial machine, possibly a lathe, is shown in a factory setting. The machine is blue and green. The factory has a high ceiling with steel beams and windows. A date stamp '2022.05.20' is visible in the bottom right corner of the image.
247	GX-B1304/21-6-22017	2022/8/19	合格	 Two workers in blue uniforms and red caps are operating a large industrial machine in a factory. The machine is blue and has various components and pipes. The workers are standing next to the machine. A date stamp '2022.07.22' is visible in the bottom right corner of the image.

248	GX-B1300/20-6-22005	2022/8/19	合格	 <p>2022 07 11</p>
249	GX-B1300/20-6-22004	2022/8/19	合格	 <p>2022 07 11</p>
250	GX-B1380/20-6-22033	2022/8/24	合格	 <p>2022 08 23</p>

251	GX-B1303/21-6-22010	2022/8/24	合格	
252	GX-B1307/20-6-22049	2022/8/24	合格	
253	GX-B1307/20-6-22050	2022/8/24	合格	

254	GX-B1310/21-6-22108	2022/8/24	合格		 <p>2022 08 23</p>	
255	GX-B1382/21-6-22017	2022/8/24	合格		 <p>2022 08 23</p>	
256	GX-B1339/21-6-22005	2022/8/22	合格		 <p>2022 08 15</p>	

257	GX-B1339/21-6-22006	2022/8/22	合格	
258	GX-B1423/20-6-22723	2022/8/25	合格	
259	GX-B1423/20-6-22724	2022/8/25	合格	

260	GX-B1423/20-6-22725	2022/8/25	合格	
261	GX-B1423/20-6-22726	2022/8/25	合格	



