

序号	报告编号	发布日期	结论	影像资料
15	GX-B1594/21-9-22025	8.12	该局部通风机共检5项，除风量（流量）、风压（全压）不判定外，其他所检项目均合格。	
16	GX-B1340/21-9-22067	8.16	所检项目合格	
17	GX-B1340/21-9-22066	8.16	所检项目合格	

18	GX-B1341/21-9-22135	2022.8.23	合格	
19	GX-B1341/21-9-22136	2022.8.23	合格	
20	GX-B1341/21-9-22137	2022.8.23	合格	
21	GX-B1341/21-9-22138	2022.8.23	合格	

22	GX-B1341/21-9-22133	2022.8.24	合格	 A photograph showing three workers in red hard hats and safety glasses inspecting a large, grey, cylindrical industrial component. One worker on the left is using a tool to check the surface. A date stamp '2022.8.18' is visible in the bottom right corner of the image.
23	GX-B1341/21-9-22134	2022.8.24	合格	 A photograph showing three workers in red hard hats inspecting a large, grey, cylindrical industrial component. One worker on the left is using a tool to check the surface. A date stamp '2022.8.18' is visible in the bottom right corner of the image.
24	GX-B1343/21-9-22027	2022.8.24	/	 A photograph showing two workers in blue uniforms and red hard hats standing near a large, grey, cylindrical industrial component. The component is mounted on a track system. A date stamp '2022.8.18' is visible in the bottom right corner of the image.

25	GX-B1347/21-9-22012	2022.8.24	/	
26	GX-B1343/21-9-22028	2022.8.26	/	
27	GX-B1347/21-9-22013	2022.8.26	/	