

序号	报告编号	发布日期	结论	影像资料
183	GX-B1350/21-2-22061	2022/8/29	所检项目合格	
184	GX-B1350/21-2-22062	2022/8/29	所检项目合格	

185	GX-B1350/21-2-22063	2022/8/29	所检项目合格			
186	GX-B1350/21-2-22064	2022/8/29	所检项目合格			



187	GX-B1350/21-2-22065	2022/8/29	所检项目合格			
188	1495/20-2-222153~222172	2022/8/29	所检项目合格			

189	1495/20-2-222173~222198	2022/8/29	所检项目合格			
190	1495/20-2-222199~222212	2022/8/29	所检项目合格			

191	1495/20-2-22213~222236	2022/8/29	所检项目合格			
192	1495/20-2-22237~222254	2022/8/29	所检项目合格			

193	GX-B1350/21-2-22066	2022. 8. 29	合格	
194	GX-B1350/21-2-22067	2022. 8. 29	合格	

195	GX-B1350/21-2-22068	2022. 8. 29	合格	
196	GX-B1350/21-2-22069	2022. 8. 29	合格	

197	GX-B1350/21-2-22070	2022. 8. 29	合格	 <p>A photograph showing a worker in a blue uniform and red helmet standing on a metal grate in a dark tunnel. The worker is holding a device. The background is dark with some structural elements. A timestamp '2022/08/01' is visible in the bottom right corner of the image.</p>
198	GX-B1350/21-2-22071	2022. 8. 29	合格	 <p>A photograph showing a worker in a blue uniform and red helmet using a yellow tool in a tunnel. The worker is wearing a white bag and is standing on a concrete floor. The background shows other workers and equipment in the distance. A timestamp '2022/08/02' is visible in the bottom right corner of the image.</p>

199	GX-B1350/21-2-22072	2022. 8. 29	合格	
200	GX-B1350/21-2-22073	2022. 8. 29	合格	

201	GX-B1350/21-2-22074	2022. 8. 29	合格	 <p>2022/08/05</p>
202	GX-B1350/21-2-22075	2022. 8. 29	合格	 <p>2022/08/07</p>

203	GX-B1350/21-2-22076	2022. 8. 29	合格	
204	GX-B1350/21-2-22077	2022. 8. 29	合格	

205	GX-B1350/21-2-22078	2022. 8. 29	合格	 <p>A worker wearing a red hard hat and a blue uniform is using a handheld electronic device. The worker is standing on a ship's deck, with a white railing and a blue structure in the background. A date stamp '2022/08/11' is visible in the bottom right corner of the image.</p>
206	GX-B1350/21-2-22079	2022. 8. 29	合格	 <p>A worker wearing a red hard hat and a blue uniform is working on a piece of equipment on a ship's deck. The worker is wearing a headlamp and is focused on the task. The equipment is a large, white, rectangular unit with various controls and labels. A date stamp '2022/08/12' is visible in the bottom right corner of the image.</p>

207	GX-B1350/21-2-22080	2022. 8. 29	合格	
208	GX-B1350/21-2-22081	2022. 8. 29	合格	

209	GX-B1381/21-2-22019	2022. 8. 31	合格			
210	GX-B1381/21-2-22020	2022. 8. 31	存在问题：驱动轮和尾轮与钢丝绳直径之比为58.3, 不符合要求。 结论：除上述问题外，其余所检项目合格。			

211	GX-B1381/21-2-22021	2022. 8. 31	合格		 <p>2022/08/05</p>	
212	GX-B1381/21-2-22022	2022. 8. 31	合格		 <p>2022/08/05</p>	

213	GX-B1381/21-2-22023	2022. 8. 31	合格		 A photograph showing a worker in a dark, confined space, likely inside a ship's hull. The worker is wearing a red helmet with a bright headlamp and a grey safety suit. They are positioned near some equipment and pipes. The date '2022/08/06' is visible in the bottom right corner of the image.	
214	GX-B1381/21-2-22024	2022. 8. 31	合格		 A photograph showing a worker in a dark, confined space, similar to the one above. The worker is wearing a red helmet with a headlamp and a grey safety suit. They are standing near a metal railing and some equipment. The date '2022/08/06' is visible in the bottom right corner of the image.	

215	GX-B1495/21-2-22184-22186	2022. 8. 19	合格	
-----	---------------------------	-------------	----	---