

序号	报告编号	发布日期	结论	影像资料
33	GX-B1415/22-3-22035	2022. 9. 7	所检项目合格	 A photograph showing two workers in red hard hats and dark clothing in a tunnel-like environment. They appear to be inspecting or working on equipment. A yellow date stamp '2022年8月16日' is visible at the bottom of the image.
34	GX-B1415/22-3-22036	2022. 9. 7	所检项目合格	 A photograph showing workers in a control room or office. One worker is standing near a desk with a computer monitor, while others are visible in the background. A white date stamp '2022.7.23' is visible at the bottom of the image.

35	GX-B1321/20-3-221407~221409	2022. 9. 9	所检项目合格	
36	GX-B1321/20-3-221410~221412	2022. 9. 9	所检项目合格	