

序号	报告编号	发布日期	结论	影像资料
133	GX-B1363/22-A-22441	2022/10/21	合格	 A photograph showing two men inspecting a large, industrial-grade metal cabinet or machine. The man on the left is wearing a red jacket and is looking into the open door of the machine. The man on the right is wearing a blue jacket and yellow gloves, and is also looking into the machine. The machine has a large, conical top section and a smaller, rectangular section below it. A date stamp '2022/10/17' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
134	GX-B1363/22-A-22442	2022/10/21	合格	

序号	报告编号	发布日期	结论	影像资料
135	GX-B1363/22-A-22424	2022/10/21	合格	 <p>A photograph showing two technicians inspecting a metal stove. One technician in a blue jacket and safety glasses is using a bright light source to inspect the interior of the stove. The other technician in a red jacket is assisting. A green trash bin is visible in the background. The date 2022/10/12 is printed in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
136	GX-B1365/20-A-22095	2022/10/21	合格	

序号	报告编号	发布日期	结论	影像资料
137	GX-B1366/20-A-22126	2022/10/21	合格	

序号	报告编号	发布日期	结论	影像资料
138	GX-B1509/20-A-22014	2022/10/21	合格	

序号	报告编号	发布日期	结论	影像资料
139	GX-B1366/20-A-22127	2022/10/21	合格	

序号	报告编号	发布日期	结论	影像资料
140	GX-B1365/20-A-22096	2022/10/21	合格	

序号	报告编号	发布日期	结论	影像资料
141	GX-B1365/20-A-22097	2022/10/25	合格	

序号	报告编号	发布日期	结论	影像资料
142	GX-B1366/20-A-22129	2022/10/25	合格	

序号	报告编号	发布日期	结论	影像资料
143	GX-B1366/20-A-22130	2022/10/25	合格	

序号	报告编号	发布日期	结论	影像资料
144	GX-B1364/20-A-22831	2022/10/21	合格	

序号	报告编号	发布日期	结论	影像资料
145	GX-B1364/20-A-22832	2022/10/21	不合格	

序号	报告编号	发布日期	结论	影像资料
146	GX-B1364/20-A-22833	2022/10/21	不合格	

序号	报告编号	发布日期	结论	影像资料
147	GX-B1364/20-A-22834	2022/10/21	合格	