




序号	报告编号	发布日期	结论	影像资料
103	GX-B1312/20-1-22463~22464	2022/10/24	合格	
104	GX-B1312/20-1-22460~22462	2022/10/24	合格	
105	GX-B1495/20-1-221634~221641	2022/10/24	合格	

106	GX-B1321/20-1-22882~22883	2022/10/25	合格		
107	GX-B1306/21-1-22059	2022/10/24	合格		
108	GX-B1306/21-1-22060	2022/10/24	合格		

109	GX-B1308/21-1-22030	2022/10/24	合格			
110	GX-B1499/21-1-22164	2022/10/24	合格			
111	GX-B1499/21-1-22165	2022/10/24	合格			

112	GX-B1499/21-1-22166	2022/10/24	合格			
113	GX-B1306/21-1-22057	2022/10/26	合格			
114	GX-B1306/21-1-22058	2022/10/26	合格			


115	GX-B1313/21-1-22096~22097	2022/10/21	合格	
116	GX-B1322/21-1-22145~22147	2022/10/24	合格	
117	GX-B1305/21-1-22019	2022/10/24	合格	

118	GX-B1451/20-1-22485~22487	2022/10/24	合格	 A worker wearing a red hard hat and a pink long-sleeved shirt is kneeling on a dark floor, working on a piece of electrical equipment. The equipment has a red and white striped warning sign. A yellow date stamp '2022/09/24' is visible in the bottom left corner of the photo.
119	GX-B1328/20-1-22126	2022/10/24	合格	 A worker wearing a red hard hat and a brown jacket is sitting on the floor, working on a white bucket. There are various tools and materials around. A yellow and red striped safety barrier is visible in the background. A yellow date stamp '2022/09/24' is visible in the bottom left corner of the photo.
120	GX-B1328/20-1-22127	2022/10/24	合格	 A worker wearing a red hard hat and a brown jacket is sitting on the floor, working on a white bucket. There are various tools and materials around. A yellow and red striped safety barrier is visible in the background. A yellow date stamp '2022/09/24' is visible in the bottom left corner of the photo.

121	GX-B1328/20-1-22128	2022/10/24	合格	
122	GX-B1328/20-1-22129	2022/10/24	合格	
123	GX-B1307/20-1-22078	2022/10/20	合格	





124	GX-B1307/20-1-22079	2022/10/20	合格	
125	GX-B1350/21-1-22120	2022/10/20	合格	
126	GX-B1350/21-1-22121	2022/10/20	合格	











127	GX-B1303/21-1-22016	2022/10/24	合格	
128	GX-B1300/20-1-22013	2022/10/24	合格	
129	GX-B1520/20-1-22044	2022/10/12	合格	

130	GX-B1423/20-1-22348	2022/10/26	合格	
131	GX-B1423/20-1-22349	2022/10/26	合格	
132	GX-B1423/20-1-22350	2022/10/26	合格	

133	GX-B1423/20-1-22351	2022/10/26	合格	
134	GX-B1423/20-1-22352	2022/10/26	合格	
135	GX-B1423/20-1-22353	2022/10/26	合格	

136	GX-B1423/20-1-22354	2022/10/26	合格	
137	GX-B1423/20-1-22355	2022/10/26	合格	
138	GX-B1423/20-1-22356	2022/10/26	合格	
139	GX-B1423/20-1-22357	2022/10/26	合格	

140	GX-B1423/20-1-22358	2022/10/26	合格	
141	GX-B1423/20-1-22359	2022/10/26	合格	
142	GX-B1423/20-1-22360	2022/10/26	合格	
143	GX-B1423/20-1-22361	2022/10/26	合格	

144	GX-B1423/20-1-22362	2022/10/26	合格	
145	GX-B1423/20-1-22363	2022/10/26	合格	
146	GX-B1423/20-1-22364	2022/10/26	合格	
147	GX-B1423/20-1-22365	2022/10/26	合格	

148	GX-B1423/20-1-22366	2022/10/26	合格	 A photograph showing three workers wearing hard hats and safety jackets standing in front of a green truck. The date '2022.10.22' is visible in the bottom right corner of the image.
149	GX-B1423/20-1-22367	2022/10/26	合格	 A photograph showing three workers wearing hard hats and safety jackets standing in front of a blue truck. The date '2022.10.22' is visible in the bottom right corner of the image.
150	GX-B1310/21-1-22153	2022. 10. 27	合格	 A photograph showing a worker in a grey uniform and a red hard hat inside a large, dark pipe or tunnel. The worker is holding a long metal rod. The date '2022.10.14' is visible in the bottom right corner of the image.

151	GX-B1428/21-1-22153	2022. 10. 27	合格	
152	GX-B1520/20-1-22045	2022. 10. 27	合格	
153	GX-B1423/20-1-22368	2022/10/29	合格	




154	GX-B1423/20-1-22369	2022/10/29	合格	
155	GX-B1423/20-1-22370	2022/10/29	合格	
156	GX-B1423/20-1-22371	2022/10/29	合格	

157	GX-B1423/20-1-22372	2022/10/29	合格	
158	GX-B1423/20-1-22373	2022/10/29	合格	
159	GX-B1423/20-1-22374	2022/10/29	合格	

160	GX-B1423/20-1-22375	2022/10/29	合格	
161	GX-B1423/20-1-22376	2022/10/29	合格	
162	GX-B1423/20-1-22377	2022/10/29	合格	

163	GX-B1423/20-1-22378	2022/10/29	合格	
164	GX-B1423/20-1-22379	2022/10/29	合格	
165	GX-B1423/20-1-22380	2022/10/29	合格	

166	GX-B1423/20-1-22381	2022/10/29	合格	 A photograph showing a yellow truck, possibly a dump truck, parked on a dirt surface. Two workers in safety gear (one in red, one in blue) are standing next to the truck. A date stamp '2022.10.28' is visible in the bottom right corner of the image.
167	GX-B1380/20-1-22024	2022/10/28	合格	 A photograph showing a worker in a red hard hat and safety vest working on a yellow metal structure, possibly a piece of machinery or a platform. A date stamp '2022/10/28' is visible in the bottom left corner of the image.
168	GX-B1307/20-1-22080	2022/10/29	合格	 A photograph showing a worker in a blue shirt and safety glasses working on a piece of machinery, possibly a control panel or a component of a larger machine. A date stamp '2022/10/29' is visible in the bottom left corner of the image.

169	GX-B1307/20-1-22081	2022/10/29	合格	
170	GX-B1307/20-1-22082	2022/10/29	合格	
171	GX-B1307/20-1-22083	2022/10/29	合格	

172	GX-B1500/21-1-22086	2022/10/29	合格	
173	GX-B1500/21-1-22087	2022/10/29	合格	
174	GX-B1500/21-1-22088	2022/10/29	合格	

175	GX-B1500/21-1-22089	2022/10/29	合格	
176	GX-B1500/21-1-22090	2022/10/29	合格	
177	GX-B1500/21-1-22091	2022/10/29	合格	



178	GX-B1309/21-1-22025	2022/10/29	合格	
179	GX-B1309/21-1-22026	2022/10/29	合格	
180	GX-B1313/21-1-22098~22099	2022/10/29	合格	

181	GX-B1329/21-1-22083	2022/10/29	合格	
182	GX-B1328/20-1-22111	2022/10/29	合格	
183	GX-B1328/20-1-22112	2022/10/29	合格	

184	GX-B1328/20-1-22113	2022/10/29	合格	
-----	---------------------	------------	----	---