

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|--------------|----------|---|
| 1 | GX-B1417/22-P-22713 | 2022. 10. 14 | 综合判定：合格。 |  |
| 2 | GX-B1417/22-P-22714 | 2022. 10. 14 | 综合判定：合格。 |  |
| 3 | GX-B1417/22-P-22715 | 2022. 10. 14 | 综合判定：合格。 |  |

| | | | | |
|---|---------------------|--------------|----------|--|
| 4 | GX-B1417/22-P-22716 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/13</p> |
| 5 | GX-B1417/22-P-22717 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/13</p> |
| 6 | GX-B1417/22-P-22718 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/16</p> |



| | | | | |
|---|---------------------|--------------|----------|--|
| 7 | GX-B1417/22-P-22719 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/13</p> |
| 8 | GX-B1417/22-P-22720 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/15</p> |
| 9 | GX-B1417/22-P-22726 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/15</p> |

| | | | | |
|----|---------------------|--------------|----------|--|
| 10 | GX-B1417/22-P-22727 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/16</p> |
| 11 | GX-B1417/22-P-22728 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/16</p> |

| | | | | |
|----|---------------------|--------------|----------|--|
| 12 | GX-B1417/22-P-22729 | 2022. 10. 14 | 综合判定：合格。 |  |
| 13 | GX-B1417/22-P-22730 | 2022. 10. 14 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|--------------|----------|--|
| 14 | GX-B1417/22-P-22731 | 2022. 10. 14 | 综合判定：合格。 |  |
| 15 | GX-B1417/22-P-22732 | 2022. 10. 14 | 综合判定：合格。 |  |


| | | | | |
|----|---------------------|--------------|----------|--|
| 16 | GX-B1417/22-P-22740 | 2022. 10. 13 | 综合判定：合格。 |  |
| 17 | GX-B1417/22-P-22741 | 2022. 10. 13 | 综合判定：合格。 |  |



| | | | | |
|----|---------------------|--------------|----------|--|
| 18 | GX-B1417/22-P-22742 | 2022. 10. 13 | 综合判定：合格。 |  |
| 19 | GX-B1417/22-P-22678 | 2022. 10. 13 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|--------------|----------|--|
| 20 | GX-B1417/22-P-22744 | 2022. 10. 13 | 综合判定：合格。 |  |
| 21 | GX-B1417/22-P-22680 | 2022. 10. 13 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|--------------|----------|--|
| 22 | GX-B1417/22-P-22681 | 2022. 10. 13 | 综合判定：合格。 |  |
| 23 | GX-B1417/22-P-22682 | 2022. 10. 13 | 综合判定：合格。 |  |



| | | | | |
|----|---------------------|--------------|----------|--|
| 24 | GX-B1417/22-P-22683 | 2022. 10. 13 | 综合判定：合格。 |  |
| 25 | GX-B1417/22-P-22684 | 2022. 10. 13 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|--------------|----------|--|
| 26 | GX-B1417/22-P-22685 | 2022. 10. 13 | 综合判定：合格。 |  |
| 27 | GX-B1417/22-P-22686 | 2022. 10. 13 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|--------------|----------|--|
| 28 | GX-B1417/22-P-22687 | 2022. 10. 13 | 综合判定：合格。 |  |
| 29 | GX-B1417/22-P-22688 | 2022. 10. 13 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|--------------|----------|--|
| 30 | GX-B1417/22-P-22689 | 2022. 10. 13 | 综合判定：合格。 |  |
| 31 | GX-B1417/22-P-22690 | 2022. 10. 13 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|--------------|----------|--|
| 32 | GX-B1417/22-P-22701 | 2022. 10. 14 | 综合判定：合格。 |  |
| 33 | GX-B1417/22-P-22702 | 2022. 10. 14 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|--------------|----------|--|
| 34 | GX-B1417/22-P-22703 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/14</p> |
| 35 | GX-B1417/22-P-22704 | 2022. 10. 14 | 综合判定：合格。 |  <p>2022/08/14</p> |

| | | | | |
|----|---------------------|--------------|----------|---|
| 36 | GX-B1417/22-P-22705 | 2022. 10. 14 | 综合判定：合格。 |  |
| 37 | GX-B1417/22-P-22603 | 2022. 11. 7 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 38 | GX-B1417/22-P-22604 | 2022. 11. 7 | 综合判定：合格。 |  A person wearing a red helmet and a blue uniform with "中检公信" (China Inspection and Certification) and "2022/09/24" is working inside the driver's side of a vehicle. The person is holding a device, possibly a camera or a diagnostic tool, and is looking towards the front of the vehicle. The background shows some greenery and a bright sky. |
| 39 | GX-B1417/22-P-22605 | 2022. 11. 7 | 综合判定：合格。 |  A person wearing a red helmet and a grey uniform is working inside the driver's side of a vehicle. The person is holding a device, possibly a camera or a diagnostic tool, and is looking towards the front of the vehicle. The background shows some greenery and a bright sky. The text "2022/09/24" is visible in the bottom left corner of the image. |

| | | | | |
|----|---------------------|-------------|----------|---|
| 40 | GX-B1417/22-P-22606 | 2022. 11. 7 | 综合判定：合格。 |  <p>2022/09/24</p> |
| 41 | GX-B1417/22-P-22607 | 2022. 11. 7 | 综合判定：合格。 |  <p>2022/09/24</p> |

| | | | | |
|----|---------------------|-------------|----------|---|
| 42 | GX-B1417/22-P-22608 | 2022. 11. 7 | 综合判定：合格。 |  <p>A worker wearing a red hard hat and a green jacket is operating a piece of equipment on the side of a white van. The van has 'MEIZU' written on it. A timestamp '2022/09/25' is visible in the bottom left corner of the photo.</p> |
| 43 | GX-B1417/22-P-22609 | 2022. 11. 7 | 综合判定：合格。 |  <p>A worker wearing a red hard hat and a grey shirt with '中检公信' (Zhongjian Gongxin) on the back is operating a piece of equipment on the rear of a white van. The van has '0598' and '核定载17人' (Rated load 17 people) written on it. A timestamp '2022/09/25' is visible in the bottom left corner of the photo.</p> |

| | | | | |
|----|---------------------|-------------|----------|---|
| 44 | GX-B1417/22-P-22610 | 2022. 11. 7 | 综合判定：合格。 |  |
| 45 | GX-B1417/22-P-22611 | 2022. 11. 7 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 46 | GX-B1417/22-P-22612 | 2022. 11. 7 | 综合判定：合格。 |  |
| 47 | GX-B1417/22-P-22613 | 2022. 11. 7 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 48 | GX-B1417/22-P-22623 | 2022. 11. 8 | 综合判定：合格。 |  |
| 49 | GX-B1417/22-P-22624 | 2022. 11. 8 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 50 | GX-B1417/22-P-22625 | 2022. 11. 8 | 综合判定：合格。 |  |
| 51 | GX-B1417/22-P-22626 | 2022. 11. 8 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 52 | GX-B1417/22-P-22627 | 2022. 11. 8 | 综合判定：合格。 |  |
| 53 | GX-B1417/22-P-22628 | 2022. 11. 8 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 54 | GX-B1417/22-P-22629 | 2022. 11. 8 | 综合判定：合格。 |  <p>2022/09/29</p> |
| 55 | GX-B1417/22-P-22623 | 2022. 11. 8 | 综合判定：合格。 |  <p>2022/09/28</p> |

| | | | | |
|----|---------------------|-------------|----------|---|
| 56 | GX-B1417/22-P-22624 | 2022. 11. 8 | 综合判定：合格。 |  |
| 57 | GX-B1417/22-P-22625 | 2022. 11. 8 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 58 | GX-B1417/22-P-22626 | 2022. 11. 8 | 综合判定：合格。 |  |
| 59 | GX-B1417/22-P-22627 | 2022. 11. 8 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------|---|
| 60 | GX-B1417/22-P-22628 | 2022. 11. 8 | 综合判定：合格。 |  A photograph showing a worker wearing a red safety helmet and a blue face mask. The worker is seated inside a vehicle, possibly a truck or bus, and is holding a red tool or device near the windshield. The date '2022/09/29' is visible in the bottom left corner of the image. |
| 61 | GX-B1417/22-P-22629 | 2022. 11. 8 | 综合判定：合格。 |  A photograph showing a worker wearing a red safety helmet and a blue face mask. The worker is seated inside a vehicle, possibly a truck or bus, and is operating a control panel or steering wheel. The date '2022/09/29' is visible in the bottom left corner of the image. |

| | | | | |
|----|---------------------|-------------|--|---|
| 62 | GX-B1521/20-P-22001 | 2022. 11. 7 | <p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘机 试验方法》，所 检项目合格</p> |  <p>2022/10/10</p> |
| 63 | GX-B1521/20-P-22002 | 2022. 11. 7 | <p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘机 试验方法》，所 检项目合格</p> |  <p>2022/10/10</p> |

| | | | | |
|----|---------------------|-------------|--|---|
| 64 | GX-B1521/20-P-22003 | 2022. 11. 7 | <p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘机 试验方法》，所 检项目合格</p> |  |
| 65 | GX-B1521/20-P-22004 | 2022. 11. 7 | <p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘机 试验方法》，所 检项目合格</p> |  |

| | | | | |
|----|---------------------|-------------|---|---|
| 66 | GX-B1521/20-P-22005 | 2022. 11. 7 | 依据GB/T 9139-2018 《土方机械 液压挖 掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘 机 试验方法》，所 检项目合格 |  |
| 67 | GX-B1521/20-P-22006 | 2022. 11. 7 | 依据GB/T 9139-2018 《土方机械 液压挖 掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘 机 试验方法》，所 检项目合格 |  |

| | | | | |
|----|---------------------|-------------|---|---|
| 68 | GX-B1521/20-P-22007 | 2022. 11. 7 | 依据GB/T 9139-2018 《土方机械 液压挖 掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘 机 试验方法》，所 检项目合格 |  <p>2022/10/11</p> |
| 69 | GX-B1521/20-P-22008 | 2022. 11. 7 | 依据GB/T 9139-2018 《土方机械 液压挖 掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘 机 试验方法》，所 检项目合格 |  <p>2022/10/10</p> |

| | | | | |
|----|---------------------|-------------|---|---|
| 70 | GX-B1521/20-P-22009 | 2022. 11. 7 | 依据GB/T 9139-2018 《土方机械 液压挖 掘机 技术条件》 GB/ T7586-2018《 土方机械 液压挖掘 机 试验方法》，所 检项目合格 |  |
|----|---------------------|-------------|---|---|