











序号	报告编号	发布日期	结论	影像资料
1	GX-B1343/21-8-22028	2022. 11. 8	/	
2	GX-B1347/21-8-22022	2022. 11. 8	/	
3	GX-B1341/21-8-22096	2022. 11. 8	综合判定：合格	
4	GX-B1341/21-8-22097	2022. 11. 8	综合判定：合格	

5	GX-B1341/21-8-22110	2022. 11. 8	综合判定：合格		
6	GX-B1343/21-8-22032	2022. 11. 8	/		
7	GX-B1341/21-8-22111	2022. 11. 8	综合判定：合格		
8	GX-B1341/21-8-22112	2022. 11. 8	综合判定：合格		



9	GX-B1341/21-8-22113	2022. 11. 8	综合判定：合格		 A photograph showing several workers in blue uniforms and red hard hats working in a tunnel. They are illuminated by headlamps. A date stamp '2022-10-16' is visible in the bottom right corner of the image.	
10	GX-B1341/21-8-22114	2022. 11. 8	综合判定：合格		 A photograph showing workers in a tunnel, similar to the previous image. The scene is dimly lit with headlamps. A date stamp '2022-10-16' is visible in the bottom right corner.	
11	GX-B1341/21-8-22115	2022. 11. 8	综合判定：合格		 A photograph showing workers in a tunnel, similar to the previous images. A date stamp '2022-10-16' is visible in the bottom right corner.	
12	GX-B1343/21-8-22033	2022. 11. 8	/		 A photograph showing four workers in blue uniforms and red hard hats standing in a hallway. They are holding bags. A banner with Chinese text is visible in the background. A date stamp '2022-10-16' is visible in the bottom right corner.	

13	GX-B1343/21-8-22034	2022. 11. 8	/	
14	GX-B1347/21-8-22026	2022. 11. 8	/	
15	GX-B1347/21-8-22027	2022. 11. 8	/	
16	GX-B1594/21-8-22014	2022. 11. 8	除流量、全压不判定外	

17	GX-B1594/21-8-22015	2022. 11. 8	除流量、全压不判定外	
18	GX-B1569/22-8-22022	2022年11月8日	合格	
19	GX-B1464/22-8-22001	2022. 11. 14	/	
20	GX-B1343/21-8-22035	2022年11月16日	/	
				

21	GX-B1343/21-8-22030	2022. 11. 14	/	
22	GX-B1347/21-8-22024	2022. 11. 14	/	
23	GX-B1341/21-8-22098	2022年11月17日	综合判定：合格。	井下禁止拍照
24	GX-B1341/21-8-22099	2022年11月17日	综合判定：合格。	井下禁止拍照
25	GX-B1341/21-8-22100	2022年11月17日	综合判定：合格。	井下禁止拍照
26	GX-B1341/21-8-22101	2022年11月17日	综合判定：合格。	井下禁止拍照
27	GX-B1341/21-8-22102	2022年11月17日	综合判定：合格。	井下禁止拍照

28	GX-B1341/21-8-22103	2022年11月17日	综合判定：合格。	井下禁止拍照
29	GX-B1341/21-8-22104	2022年11月17日	综合判定：合格。	井下禁止拍照
30	GX-B1341/21-8-22105	2022年11月17日	综合判定：合格。	井下禁止拍照
31	GX-B1341/21-8-22106	2022年11月17日	综合判定：合格。	井下禁止拍照
32	GX-B1341/21-8-22107	2022年11月17日	综合判定：合格。	井下禁止拍照
33	GX-B1341/21-8-22108	2022年11月17日	综合判定：合格。	井下禁止拍照
34	GX-B1341/21-8-22109	2022年11月17日	综合判定：合格。	井下禁止拍照
35	GX-B1343/21-8-22029	2022. 11. 14	/	

36	GX-B1347/21-8-22023	2022. 11. 14	/	
37	GX-B1343/21-8-22031	2022. 11. 14	/	
38	GX-B1347/21-8-22025	2022. 11. 14	/	