

序号	报告编号	发布日期	结论	影像资料
66	GX-B1380/20-1-22025	2022/11/29	所检项目合格	 A photograph showing two workers in orange safety jackets and hard hats (one yellow, one white) standing in an industrial environment, possibly a power plant or substation. They are looking at a document held by one of the workers. A red timestamp '2022.10.1' is visible in the bottom right corner of the image.
67	GX-B1382/21-1-22037	2022/11/30	合格	 A photograph showing two workers in white shirts and red hard hats inspecting equipment outdoors. One worker is standing and looking at a piece of equipment, while the other is kneeling down. A yellow timestamp '2022/09/18' is visible on the left side of the image.