

序号	报告编号	发布日期	结论	影像资料
21	GX-B1303/21-Z-22008	2022/12/8	综合判定：合格。	
22	GX-B1500/21-Z-22048	2022.12.16	综合判定：合格	
23	GX-B1500/21-Z-22049	2022.12.16	综合判定：合格	

24	GX-B1428/21-Z-22015	2022/12/16	无缺陷迹痕显示。	
25	GX-B1307 / 20-Z-22061	12. 28	综合判定：合格	
26	GX-B1307 / 20-Z-22062	12. 28	综合判定：合格	
27	GX-B1307 / 20-Z-22063	12. 28	综合判定：合格	

28	GX-B1307 / 20-Z-22064	12. 28	综合判定：合格	 A worker in a blue uniform and red helmet is kneeling and inspecting a piece of machinery. The date stamp '2022 12 21' is visible in the bottom right corner of the photo.
29	GX-B1307 / 20-Z-22065	12. 28	综合判定：合格	 A worker in a blue uniform and red helmet is working on a red machine. The date stamp '2022 12 21' is visible in the bottom right corner of the photo.
30	GX-B1307 / 20-Z-22066	12. 28	综合判定：合格	 A worker in a blue uniform and red helmet is working on a machine. The date stamp '2022 12 21' is visible in the bottom right corner of the photo.
31	GX-B1310 / 21-Z-22074	12. 28	符合标准要求	 A worker in a grey uniform and yellow helmet is working on a machine outdoors. The date stamp '2022 12 10' is visible in the bottom right corner of the photo.

32	GX-B1310 / 21-Z-22075	12. 28	符合标准要求	 <p>2022 12 10</p>
33	GX-B1310 / 21-Z-22076	12. 28	符合标准要求	 <p>2022 12 10</p>
34	GX-B1310 / 21-Z-22077	12. 28	符合标准要求	 <p>2022 12 10</p>
35	GX-B1310 / 21-Z-22078	12. 28	符合标准要求	 <p>2022 12 10</p>

36	GX-B1310 / 21-Z-22079	12. 28	符合标准要求	
37	GX-B1310 / 21-Z-22080	12. 28	符合标准要求	
38	GX-B1310 / 21-Z-22081	12. 28	符合标准要求	
39	GX-B1310 / 21-Z-22082	12. 28	符合标准要求	