

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 182 | GX-B1509/20-A-22015 | 2022/12/20 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 183 | GX-B1509/20-A-22016 | 2022/12/20 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 184 | GX-B1363/22-A-22500 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 185 | GX-B1367/22-A-22124 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 186 | GX-B1367/22-A-22122 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 187 | GX-B1367/22-A-22121 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 188 | GX-B1367/22-A-22123 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 189 | GX-B1363/22-A-22476 | 2022/12/16 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 190 | GX-B1363/22-A-22477 | 2022/12/16 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 191 | GX-B1363/22-A-22478 | 2022/12/16 | 所检项目合格 |  A photograph showing two men in work clothes inspecting a large, complex industrial machine. The machine has a large cylindrical component on top and a rectangular panel with a viewing window. One man is wearing a grey jacket and safety glasses, and the other is wearing a light blue shirt. The machine has yellow warning labels. The scene is indoors, near a window with a view of trees. A date stamp '2022/12/05' is visible in the bottom right corner of the photo. |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 192 | GX-B1363/22-A-22479 | 2022/12/16 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 193 | GX-B1363/22-A-22487 | 2022/12/26 | 所检项目合格 |  <p>The photograph shows two men in light-colored work jackets inspecting a large, white industrial furnace or boiler. The furnace has a large, dark metal door that is open, and a white chimney pipe extends from the top. The man on the right is wearing a face mask and gloves, and is looking into the furnace. The man on the left is also looking at the furnace. The furnace has yellow warning labels on it. The date '2022/12/13' is visible in the bottom right corner of the photo.</p> |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 194 | GX-B1363/22-A-22488 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 195 | GX-B1363/22-A-22489 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 196 | GX-B1363/22-A-22490 | 2022/12/26 | 所检项目合格 |  <p>The photograph shows two individuals in white lab coats with a logo on the back, inspecting a large, white industrial furnace or oven. The furnace has a large, dark, cylindrical chimney pipe extending from the top. The individuals are standing on either side of the furnace, looking into the open front door. The date '2022/12/14' is printed in the bottom right corner of the image.</p> |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 197 | GX-B1363/22-A-22491 | 2022/12/26 | 所检项目合格 |  <p>The image shows two men in work clothes inspecting a large, white industrial machine with a metal hood. One man is wearing a red jacket and a blue face mask, while the other is wearing a blue jacket and glasses. They are both looking into the machine's open compartments. A date stamp '2022/12/15' is visible in the bottom right corner of the photo.</p> |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 198 | GX-B1363/22-A-22493 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 199 | GX-B1363/22-A-22492 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 200 | GX-B1363/22-A-22503 | 2022/12/26 | 所检项目合格 |  <p>The photograph shows two men in work clothes inspecting a large, white industrial machine. One man is wearing a red jacket and a blue face mask, while the other is wearing a blue jacket and glasses. They are looking into the open front panel of the machine. A date stamp '2022/12/15' is visible in the bottom right corner of the image.</p> |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 201 | GX-B1363/22-A-22494 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 202 | GX-B1363/22-A-22495 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 203 | GX-B1363/22-A-22496 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 204 | GX-B1363/22-A-22497 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 205 | GX-B1363/22-A-22498 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 206 | GX-B1363/22-A-22499 | 2022/12/26 | 所检项目合格 |  <p>2022/12/18</p> |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 207 | GX-B1363/22-A-22501 | 2022/12/26 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 208 | GX-B1365/20-A-22111 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 209 | GX-B1365/20-A-22112 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 210 | GX-B1364/22-A-22965 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 211 | GX-B1364/22-A-22964 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 212 | GX-B1364/22-A-22963 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 213 | GX-B1364/22-A-22966 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 214 | GX-B1364/22-A-22974 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 215 | GX-B1364/22-A-22971 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 216 | GX-B1364/22-A-22970 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 217 | GX-B1364/22-A-22969 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 218 | GX-B1364/22-A-22968 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 219 | GX-B1364/22-A-22967 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|--|
| 220 | GX-B1364/22-A-22979 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 221 | GX-B1364/22-A-22980 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 222 | GX-B1364/22-A-22978 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 223 | GX-B1364/22-A-22977 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 224 | GX-B1364/22-A-22976 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 225 | GX-B1364/22-A-22975 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 226 | GX-B1364/22-A-22972 | 2022/12/30 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 227 | GX-B1364/22-A-22973 | 2022/12/29 | 所检项目合格 |  |

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|--------|---|
| 228 | GX-B1363/22-A-22513 | 2022/12/30 | 所检项目合格 |  <p>2022/12/27</p> |