


序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-5-22302	2023/1/5	符合标准要求。	
2	GX-B1310/21-5-22304	2023/1/5	符合标准要求。	
3	GX-B1321/20-5-22672~22680	2023.1.4	所检项目合格	

4	GX-B1312/20-5-22555~22562	2023. 1. 4	所检项目合格	 <p>The images show close-up views of electrical components, possibly transformers or switchgear, with cables and metal enclosures. The photos are taken in a dark environment, likely indoors, and show the intricate details of the equipment.</p>
5	GX-B1328/20-5-22171~22174	2023. 1. 4	所检项目合格	 <p>The images show workers in safety gear (hard hats, high-visibility vests) performing tasks outdoors. They are using tools and equipment on a paved surface, possibly a road or a large outdoor facility. The photos are taken from various angles, showing the workers' activities and the surrounding environment.</p>
6	GX-B1495/20-5-221936~221955	2023. 1. 4	所检项目合格	 <p>The images show workers in safety gear inspecting electrical cabinets or control panels. The workers are wearing hard hats and high-visibility vests. The photos are taken from different perspectives, showing the workers' actions and the details of the electrical equipment.</p>

7	GX-B1350/21-5-22107	2023. 1. 5	所检项目合格	
8	GX-B1382/21-5-22020	2022年1月3日	合格	

9	GX-B1304/21-5-22013	2022年1月3日	合格	
10	GX-B1384/16-5-22005	2022年1月3日	合格	
11	GX-B1517/20-5-22034	2023. 1. 4	合格	

12	GX-B1517/20-5-22035	2023. 1. 4	合格			
----	---------------------	------------	----	--	---	--