

序号	报告编号	发布日期	结论	影像资料
1	GX-B1343/21-9-22065	1.3	/	
2	GX-B1343/21-9-22066	1.3	/	
3	GX-B1343/21-9-22068	1.3	/	

4	GX-B1371/21-9-22008	2023.1.3	述问题外，其余所检项目合	 <p>丰源磷矿 2022.11.16</p>	 <p>丰源磷矿 2022.11.16</p>  <p>丰源磷矿 2022.11.16</p>
5	GX-B1370/21-9-22028	2023/1/3	合格	 <p>2022.12.5</p>	
6	GX-B1346/21-9-22014	1.4	低瓦斯矿井		
7	GX-B1346/21-9-22015	1.4	低瓦斯矿井		
8	GX-B1346/21-9-22012	1.4	突出矿井		

9	GX-B1340/21-9-22089	1.9	运行、叶片角度0° /0° 、	
10	GX-B1340/21-9-22090	1.9	该通风机共测试1个运行状态（双级运行、叶片角度0° /0° 、运行频率：50Hz），所检项目合格。	
11	GX-B1346/21-9-22013	1.9	低瓦斯矿井	
12	GX-B1346/21-9-22010	1.9	低瓦斯矿井	
13	GX-B1346/21-9-22008	1.9	低瓦斯矿井	
14	GX-B1343/21-9-22063	1.9	/	

15	GX-B1345/21-9-22006	2023.1.9	/	
----	---------------------	----------	---	---