


| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|-------------|---------|---|
| 13 | GX-B1310/21-5-22329 | 2023/1/11 | 符合标准要求。 |  |
| 14 | GX-B1310/21-5-22330 | 2023/1/11 | 符合标准要求。 |  |
| 15 | GX-B1310/21-5-22329 | 2023. 1. 12 | 符合标准要求。 |  |
| 16 | GX-B1310/21-5-22330 | 2023. 1. 12 | 符合标准要求。 |  |



| | | | | |
|----|---------------------|-------------|---------|---|
| 17 | GX-B1427/21-5-22040 | 2023. 1. 12 | 符合标准要求。 |  <p>2022-12-28</p> |
| 18 | GX-B1427/21-5-22041 | 2023. 1. 12 | 符合标准要求。 |  <p>2022-12-28</p> |
| 19 | GX-B1310/21-5-22295 | 2023/1/10 | 符合标准要求 |  <p>2022年12月11日</p> |

| | | | | |
|----|---------------------|-----------|--------|--|
| 20 | GX-B1310/21-5-22296 | 2023/1/10 | 符合标准要求 |  |
| 21 | GX-B1310/21-5-22297 | 2023/1/10 | 符合标准要求 |  |

| | | | | |
|----|---------------------|-----------|--------|--|
| 22 | GX-B1310/21-5-22298 | 2023/1/10 | 符合标准要求 |  |
| 23 | GX-B1310/21-5-22299 | 2023/1/10 | 符合标准要求 |  |

| | | | | |
|----|---------------------|-----------|--------------------------|--|
| 24 | GX-B1310/21-5-22300 | 2023/1/10 | 未发现超过 Φ 3mm当量直径的缺陷。 |   |
| 25 | GX-B1310/21-5-22301 | 2023/1/10 | 未发现超过 Φ 3mm当量直径的缺陷。 |   |

| | | | | |
|----|---------------------|-----------|---------|--|
| 26 | GX-B1427/21-5-22034 | 2023/1/11 | 无缺陷磁痕显示 |  |
| 27 | GX-B1427/21-5-22035 | 2023/1/11 | 无缺陷磁痕显示 |  |

| | | | | |
|----|---------------------|-----------|---------|--|
| 28 | GX-B1428/21-5-22040 | 2023/1/11 | 无缺陷显示迹痕 |  |
| 29 | GX-B1428/21-5-22041 | 2023/1/11 | 无缺陷显示迹痕 |  |