

序号	报告编号	发布日期	结论	影像资料
1	GX-B1598/21-2-22188	2023. 2. 2	实测钢丝绳有效截面积损失百分比最大为1.39%，小于5%为正常。	 <p>2022/12/12</p>
2	GX-B1598/21-2-22189	2023. 2. 2	实测钢丝绳有效截面积损失百分比最大为0.79%，小于5%为正常。	 <p>2022/12/12</p>
3	GX-B1598/21-2-22190	2023. 2. 2	实测钢丝绳有效截面积损失百分比最大为1.02%，小于5%为正常。	 <p>2022/12/12</p>

4	GX-B1598/21-2-22191	2023. 2. 2	实测钢丝绳有效截面积损失百分比最大为0.92%，小于5%为正常。	 <p>2022/12/12</p>
5	GX-B1359/21-2-23001~23010	2023. 2. 3	本次共检矿用隔爆型照明信号综合保护装置10台, 10台所检项目合格。	 <p>2023/01/05</p>
6	GX-B1359/21-2-23011~23022	2023. 2. 3	本次共检矿用隔爆型照明信号综合保护装置12台, 12台所检项目合格。	 <p>2023/01/06</p>

7	GX-B1521/20-2-23001	2023. 2. 8	所检项目合格。	
8	GX-B1521/20-2-23002	2023. 2. 8	所检项目合格。	
9	GX-B1521/20-2-23003	2023. 2. 8	所检项目合格。	

10	GX-B1521/20-2-23004	2023. 2. 8	所检项目合格。	
11	GX-B1521/20-2-23005	2023. 2. 8	所检项目合格。	
12	GX-B1521/20-2-23006	2023. 2. 8	所检项目合格。	

13	GX-B1521/20-2-23007	2023. 2. 8	所检项目合格。	
14	GX-B1539/22-2-23001	2023. 2. 8	所检项目合格。	 2023/02/01
15	GX-B1310/21-2-23001	2023. 2. 9	符合标准要求。	 2023/01/10

16	GX-B1427/21-2-23001	2023. 2. 9	符合标准要求。	 <p>2023/01/10</p>
17	GX-B1310/21-2-23002	2023. 2. 9	符合标准要求。	 <p>2023/01/11</p>
18	GX-B1427/21-2-23002	2023. 2. 9	符合标准要求。	 <p>2023/01/11</p>

19	GX-B1428/21-2-23003	2023. 2. 9	无缺陷迹痕显示。	
20	GX-B1428/21-2-23004	2023. 2. 9	无缺陷迹痕显示。	
21	GX-B1428/21-2-23005	2023. 2. 9	无缺陷迹痕显示。	

22	GX-B1563/21-2-23001	2023. 2. 10	所检项目合格。	 
23	GX-B1563/21-2-23002	2023. 2. 10	所检项目合格。	 
24	GX-B1310/21-2-23017	2023. 2. 10	合格	

25	GX-B1310/21-2-23018	2023. 2. 10	合格	
26	GX-B1310/21-2-23019	2023. 2. 10	合格	
27	GX-B1310/21-2-23020	2023. 2. 10	合格	

28	GX-B1310/21-2-23021	2023. 2. 10	合格	 <p>2023/01/30</p>
29	GX-B1310/21-2-23022	2023. 2. 10	合格	 <p>2023/01/30</p>
30	GX-B1598/21-2-23001	2023. 2. 9	合格	 <p>2023-01-30</p>

31	GX-B1598/21-2-23002	2023. 2. 9	合格	
32	GX-B1598/21-2-23003	2023. 2. 9	合格	
33	GX-B1598/21-2-23004	2023. 2. 9	合格	

34	GX-B1534/20-2-23001	2023. 2. 13	所检项目合格		
35	GX-B1534/20-2-23002	2023. 2. 13	所检项目合格		
36	GX-B1534/20-2-23003	2023. 2. 13	所检项目合格		

37	GX-B1534/20-2-23004	2023. 2. 13	所检项目合格	
38	GX-B1534/20-2-23005	2023. 2. 13	所检项目合格	
39	GX-B1322/21-2-23001	2023/2/13	所检项目合格	

40	GX-B1313/21-2-23001	2023/2/13	所检项目合格	
----	---------------------	-----------	--------	---