



序号	报告编号	发布日期	结论	影像资料
101	GX-B1423/20-Y-23071	2023年2月11日	综合判定：合格	 <p>A photograph showing a yellow dump truck with the number '1098' on its side. Two workers wearing safety vests and hard hats are standing in front of the truck on a dirt surface. A timestamp '2023/1/9' is visible in the bottom right corner of the image.</p>
102	GX-B1423/20-Y-23072	2023年2月11日	综合判定：合格	 <p>A photograph showing a yellow dump truck with the number '99' on its front. Two workers wearing safety vests and hard hats are standing in front of the truck on a dirt surface. A timestamp '2023/1/9' is visible in the bottom right corner of the image.</p>

103	GX-B1423/20-Y-23073	2023年2月11日	综合判定：合格	
104	GX-B1423/20-Y-23074	2023年2月11日	综合判定：合格	

105	GX-B1423/20-Y-23075	2023年2月11日	综合判定：合格	
106	GX-B1423/20-Y-23076	2023年2月11日	综合判定：合格	

107	GX-B1423/20-Y-23077	2023年2月11日	综合判定：合格	
108	GX-B1423/20-Y-23078	2023年2月11日	综合判定：合格	

109	GX-B1423/20-Y-23079	2023年2月11日	综合判定：合格	
110	GX-B1423/20-Y-23080	2023年2月11日	综合判定：合格	

111	GX-B1423/20-Y-23081	2023年2月11日	综合判定：合格	
112	GX-B1423/20-Y-23082	2023年2月11日	综合判定：合格	

113	GX-B1423/20-Y-23083	2023年2月11日	综合判定：合格	
114	GX-B1423/20-Y-23084	2023年2月11日	综合判定：合格	

115	GX-B1423/20-Y-23085	2023年2月11日	综合判定：合格	
116	GX-B1423/20-Y-23086	2023年2月11日	综合判定：合格	

117	GX-B1423/20-Y-23087	2023年2月11日	综合判定：合格	
118	GX-B1423/20-Y-23088	2023年2月11日	综合判定：合格	

119	GX-B1423/20-Y-23089	2023年2月11日	综合判定：合格	 A large orange SANY mining truck with the number '4' on its side. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.
120	GX-B1423/20-Y-23090	2023年2月11日	综合判定：合格	 A large orange SANY mining truck with the number '3' on its side. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.

121	GX-B1423/20-Y-23091	2023年2月11日	综合判定：合格	
122	GX-B1423/20-Y-23092	2023年2月11日	综合判定：合格	

123	GX-B1423/20-Y-23093	2023年2月11日	综合判定：合格	
124	GX-B1423/20-Y-23094	2023年2月11日	综合判定：合格	

125	GX-B1423/20-Y-23095	2023年2月11日	综合判定：合格	
126	GX-B1423/20-Y-23096	2023年2月11日	综合判定：合格	

127	GX-B1423/20-Y-23097	2023年2月11日	综合判定：合格	
128	GX-B1423/20-Y-23098	2023年2月11日	综合判定：合格	

129	GX-B1423/20-Y-23099	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in red and grey work clothes are standing next to it, inspecting the vehicle. A yellow timestamp '2023/1/9' is visible in the bottom right corner of the photo.
130	GX-B1423/20-Y-23100	2023年2月11日	综合判定：合格	 A green dump truck is parked on a dirt surface. Two workers in brown work clothes and hard hats are standing next to it, inspecting the vehicle. A yellow timestamp '2023/1/9' is visible in the bottom right corner of the photo.

131	GX-B1423/20-Y-23101	2023年2月11日	综合判定：合格	
132	GX-B1423/20-Y-23102	2023年2月11日	综合判定：合格	

133	GX-B1423/20-Y-23103	2023年2月11日	综合判定：合格	 A yellow dump truck with the number 2183 on its side. Two workers in safety gear are standing next to it. The date 2023/1/10 is visible in the bottom right corner of the photo.
134	GX-B1423/20-Y-23104	2023年2月11日	综合判定：合格	 A yellow dump truck with the number 2177 on its side. Two workers in safety gear are standing next to it. The date 2023/1/10 is visible in the bottom right corner of the photo.

135	GX-B1423/20-Y-23105	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '2190' on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.
136	GX-B1423/20-Y-23106	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has the number '2165' on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.

137	GX-B1423/20-Y-23107	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the number '2179' on its side. A date stamp '2023/1/10' is visible in the bottom right corner of the photo.
138	GX-B1423/20-Y-23108	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the number '87' on its side. A date stamp '2023/1/10' is visible in the bottom right corner of the photo.

139	GX-B1423/20-Y-23109	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck's bed is slightly raised. A date stamp '2023/1/10' is visible in the bottom right corner of the image.
140	GX-B1423/20-Y-23110	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck's bed is slightly raised. A date stamp '2023/1/10' is visible in the bottom right corner of the image.

141	GX-B1423/20-Y-23111	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with license plate number 211 is parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/1/10 is visible in the bottom right corner of the photo.</p>
142	GX-B1423/20-Y-23112	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with license plate number 2120 is parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/1/11 is visible in the bottom right corner of the photo.</p>

143	GX-B1423/20-Y-23113	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the identification number 2166 on its side. Two workers in safety gear are standing next to it. The date 2023/1/11 is visible in the bottom right corner of the photo.</p>
144	GX-B1423/20-Y-23114	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the identification number 2103 on its side. Two workers in safety gear are standing next to it. The date 2023/1/11 is visible in the bottom right corner of the photo.</p>

145	GX-B1423/20-Y-23115	2023年2月11日	综合判定：合格	
-----	---------------------	------------	---------	---

146	GX-B1423/20-Y-23116	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number 2057 on its side. Two workers in high-visibility vests are standing next to it. The date 2023/1/11 is visible in the bottom right corner of the photo.</p>
147	GX-B1423/20-Y-23117	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number 2058 on its side. Two workers in high-visibility vests are standing next to it. The date 2023/1/11 is visible in the bottom right corner of the photo.</p>

148	GX-B1423/20-Y-23118	2023年2月11日	综合判定：合格	
-----	---------------------	------------	---------	---

149	GX-B1423/20-Y-23119	2023年2月11日	综合判定：合格	 A yellow dump truck with the number 2109 on its side is parked on a dirt surface. Two workers in safety vests are standing near the front wheel. A traffic cone is visible. The date 2023/1/11 is printed in the bottom right corner of the photo.
150	GX-B1423/20-Y-23120	2023年2月11日	综合判定：合格	 A yellow dump truck with the number 2003 on its side is parked on a dirt surface. Two workers in safety vests are standing near the front wheel. A traffic cone is visible. The date 2023/1/11 is printed in the bottom right corner of the photo.

151	GX-B1423/20-Y-23121	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '2187' on its side. A date stamp '2023/1/11' is visible in the bottom right corner of the image.
152	GX-B1423/20-Y-23122	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '2176' on its side. A date stamp '2023/1/11' is visible in the bottom right corner of the image.

153	GX-B1423/20-Y-23123	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number '2106' on its side. Two workers in safety gear stand in front of it. A traffic cone is visible on the ground. The date '2023/1/11' is printed in the bottom right corner of the photo.</p>
154	GX-B1423/20-Y-23124	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number '2051' on its side. Two workers in safety gear stand in front of it. A traffic cone is visible on the ground. The date '2023/1/12' is printed in the bottom right corner of the photo.</p>

155	GX-B1423/20-Y-23125	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in blue and grey uniforms are standing next to it. The truck has the license plate GX-B1423 and the numbers 2128 on its side. A date stamp '2023/1/12' is visible in the bottom right corner of the photo.
156	GX-B1423/20-Y-23126	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in blue and grey uniforms are standing next to it. The truck has the license plate GX-B1423 and the numbers 20011 on its side. A date stamp '2023/1/12' is visible in the bottom right corner of the photo.

157	GX-B1423/20-Y-23127	2023年2月11日	综合判定：合格	
158	GX-B1423/20-Y-23128	2023年2月11日	综合判定：合格	

159	GX-B1423/20-Y-23129	2023年2月11日	综合判定：合格	
160	GX-B1423/20-Y-23130	2023年2月11日	综合判定：合格	

161	GX-B1423/20-Y-23131	2023年2月11日	综合判定：合格	 <p>A yellow XCMG 711 dump truck is shown from a side-rear perspective. The truck has the identification number '2292' on its side. Two workers in safety gear are standing next to the truck. A traffic cone is visible in the foreground. The date '2023/1/12' is printed in the bottom right corner of the image.</p>
162	GX-B1423/20-Y-23132	2023年2月11日	综合判定：合格	 <p>A yellow XCMG 711 dump truck is shown from a side-rear perspective. The truck has the identification number '2276' on its side. Two workers in safety gear are standing next to the truck. Traffic cones are visible in the foreground. The date '2023/1/12' is printed in the bottom right corner of the image.</p>


163	GX-B1423/20-Y-23133	2023年2月11日	综合判定：合格	 A yellow dump truck with the license plate M-2272 and the number 2272 on the side. Two workers in blue and grey uniforms are standing near the front wheel. The truck is parked on a dirt surface with orange traffic cones. A date stamp '2023/1/12' is visible in the bottom right corner of the image.
164	GX-B1423/20-Y-23134	2023年2月11日	综合判定：合格	 A yellow dump truck with the license plate M-2286 and the number 2286 on the side. Two workers in blue and grey uniforms are standing near the front wheel. The truck is parked on a dirt surface with orange traffic cones. A date stamp '2023/1/12' is visible in the bottom right corner of the image.

165	GX-B1423/20-Y-23135	2023年2月11日	综合判定：合格	 <p>A yellow XCMG XG105 dump truck is shown from a side-rear perspective. The license plate reads 'M-2105'. The side of the truck has the numbers '2 2 9 5'. Two workers in safety gear are standing near the front of the truck. The date '2023/1/13' is visible in the bottom right corner of the photo.</p>
166	GX-B1423/20-Y-23136	2023年2月11日	综合判定：合格	 <p>A yellow XCMG dump truck is shown from a side-rear perspective. The license plate reads 'M-2178'. The side of the truck has the numbers '2 2 7 8'. Two workers in safety gear are standing near the front of the truck. The date '2023/1/13' is visible in the bottom right corner of the photo.</p>

167	GX-B1423/20-Y-23137	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with license plate M-277 is parked on a dirt surface. Two workers in safety gear are standing near the front. The truck has the number '2277' on its side. A date stamp '2023/1/13' is visible in the bottom right corner of the photo.</p>
168	GX-B1423/20-Y-23138	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with license plate M-275 is parked on a dirt surface. Two workers in safety gear are standing near the front. The truck has the number '2275' on its side. A date stamp '2023/1/13' is visible in the bottom right corner of the photo.</p>

169	GX-B1423/20-Y-23139	2023年2月11日	综合判定：合格	 A photograph showing a person sitting inside the cab of a yellow truck, looking at a mobile device. The truck is yellow and has a date stamp '2023/1/13' in the bottom right corner.
170	GX-B1423/20-Y-23140	2023年2月11日	综合判定：合格	 A photograph of a yellow truck with the number '2293' on its side. Two people are standing near the front of the truck. The truck is yellow and has a date stamp '2023/1/13' in the bottom right corner.

171	GX-B1423/20-Y-23141	2023年2月11日	综合判定：合格	
172	GX-B1423/20-Y-23142	2023年2月11日	综合判定：合格	

173	GX-B1423/20-Y-23143	2023年2月11日	综合判定：合格	
174	GX-B1423/20-Y-23144	2023年2月11日	综合判定：合格	

175	GX-B1423/20-Y-23145	2023年2月11日	综合判定：合格	 A yellow dump truck with the number 2296 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/1/13 is visible in the bottom right corner of the photo.
176	GX-B1423/20-Y-23146	2023年2月11日	综合判定：合格	 A yellow dump truck with the number 2270 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/1/13 is visible in the bottom right corner of the photo.

177	GX-B1423/20-Y-23147	2023年2月11日	综合判定：合格	
178	GX-B1423/20-Y-23148	2023年2月11日	综合判定：合格	

179	GX-B1423/20-Y-23149	2023年2月11日	综合判定：合格	 A yellow dump truck with license plate M-228 is parked on a dirt surface. Two people are standing near the front of the truck. The truck has the number '2226' on its side. A yellow timestamp '2023/2/11' is visible in the bottom right corner of the photo.
180	GX-B1423/20-Y-23150	2023年2月11日	综合判定：合格	 A yellow dump truck with license plate M-227 is parked on a dirt surface. Two people are standing near the front of the truck. The truck has the number '2217' on its side. A yellow timestamp '2023/2/11' is visible in the bottom right corner of the photo.

181	GX-B1423/20-Y-23151	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front wheel. The truck has the license plate GX-B1423 and the number 2260 on its side. A date stamp '2023/1/14' is visible in the bottom right corner of the photo.
182	GX-B1423/20-Y-23152	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people are standing near the front wheel. The truck has the license plate GX-B1423 and the number 2246 on its side. A date stamp '2023/1/14' is visible in the bottom right corner of the photo.

183	GX-B1423/20-Y-23153	2023年2月11日	综合判定：合格	
184	GX-B1423/20-Y-23154	2023年2月11日	综合判定：合格	

185	GX-B1423/20-Y-23155	2023年2月11日	综合判定：合格	 A yellow dump truck with the license plate GX-B1423 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '2' on its side and '同力重工' (Tongli Heavy Industry) on the top of the dump body. A date stamp '2023/1/14' is visible in the bottom right corner of the photo.
186	GX-B1423/20-Y-23156	2023年2月11日	综合判定：合格	 A yellow dump truck with the license plate GX-B1423 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has the number '2' on its side and '同力重工' (Tongli Heavy Industry) on the top of the dump body. A date stamp '2023/1/14' is visible in the bottom right corner of the photo.

187	GX-B1423/20-Y-23157	2023年2月11日	综合判定：合格	
188	GX-B1423/20-Y-23158	2023年2月11日	综合判定：合格	

189	GX-B1423/20-Y-23159	2023年2月11日	综合判定：合格	
190	GX-B1423/20-Y-23160	2023年2月11日	综合判定：合格	

191	GX-B1423/20-Y-23161	2023年2月11日	综合判定：合格	
192	GX-B1423/20-Y-23162	2023年2月11日	综合判定：合格	

193	GX-B1423/20-Y-23163	2023年2月11日	综合判定：合格	
194	GX-B1423/20-Y-23164	2023年2月11日	综合判定：合格	

195	GX-B1423/20-Y-23165	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers are standing in front of it. One worker is wearing a yellow safety vest and a hard hat, while the other is wearing a white uniform and a white cap. The truck has the number '2' on its side. A timestamp '2023/2/10' is visible in the bottom right corner of the photo.
196	GX-B1423/20-Y-23166	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers are standing in front of it. One worker is wearing a red safety vest and a hard hat, while the other is wearing a white uniform and a white cap. The truck has the number '2' on its side. A timestamp '2023/2/10' is visible in the bottom right corner of the photo.

197	GX-B1423/20-Y-23167	2023年2月11日	综合判定：合格	
198	GX-B1423/20-Y-23168	2023年2月11日	综合判定：合格	

199	GX-B1423/20-Y-23169	2023年2月11日	综合判定：合格	
200	GX-B1423/20-Y-23170	2023年2月11日	综合判定：合格	

201	GX-B1423/20-Y-23171	2023年2月11日	综合判定：合格	
202	GX-B1423/20-Y-23172	2023年2月11日	综合判定：合格	

203	GX-B1423/20-Y-23173	2023年2月11日	综合判定：合格	 A yellow MT980 dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The truck has the number '2148' on its side and 'MT980' on the front. A date stamp '2023/1/10' is visible in the bottom right corner of the photo.
204	GX-B1423/20-Y-23174	2023年2月11日	综合判定：合格	 A yellow MT980 dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The truck has 'MT980' on the front. A date stamp '2023/1/11' is visible in the bottom right corner of the photo.

205	GX-B1423/20-Y-23175	2023年2月11日	综合判定：合格	
206	GX-B1423/20-Y-23176	2023年2月11日	综合判定：合格	

207	GX-B1423/20-Y-23177	2023年2月11日	综合判定：合格	
208	GX-B1423/20-Y-23178	2023年2月11日	综合判定：合格	

209	GX-B1423/20-Y-23179	2023年2月11日	综合判定：合格	
210	GX-B1423/20-Y-23180	2023年2月11日	综合判定：合格	


211	GX-B1423/20-Y-23181	2023年2月11日	综合判定：合格	
212	GX-B1423/20-Y-23182	2023年2月11日	综合判定：合格	

213	GX-B1423/20-Y-23183	2023年2月11日	综合判定：合格	
214	GX-B1423/20-Y-23184	2023年2月11日	综合判定：合格	

215	GX-B1423/20-Y-23185	2023年2月11日	综合判定：合格	
216	GX-B1423/20-Y-23186	2023年2月11日	综合判定：合格	

217	GX-B1423/20-Y-23187	2023年2月11日	综合判定：合格	
218	GX-B1423/20-Y-23188	2023年2月11日	综合判定：合格	

219	GX-B1423/20-Y-23189	2023年2月11日	综合判定：合格	
220	GX-B1423/20-Y-23190	2023年2月11日	综合判定：合格	

221	GX-B1423/20-Y-23191	2023年2月11日	综合判定：合格	
222	GX-B1423/20-Y-23192	2023年2月11日	综合判定：合格	

223	GX-B1423/20-Y-23193	2023年2月11日	综合判定：合格	
224	GX-B1423/20-Y-23194	2023年2月11日	综合判定：合格	

225	GX-B1423/20-Y-23195	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is shown from a side-rear perspective. The truck has the license plate 'GX-B1423' and the number '222' on its side. Two workers in safety gear are standing near the front wheel. The date '2023/1/12' is visible in the bottom right corner of the photo.</p>
226	GX-B1423/20-Y-23196	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is shown from a side-rear perspective. The truck has the license plate 'GX-B1423' and the number '2231' on its side. Two workers in safety gear are standing near the front wheel. The date '2023/1/12' is visible in the bottom right corner of the photo.</p>

227	GX-B1423/20-Y-23197	2023年2月11日	综合判定：合格	
228	GX-B1423/20-Y-23198	2023年2月11日	综合判定：合格	

229	GX-B1423/20-Y-23199	2023年2月11日	综合判定：合格	
230	GX-B1423/20-Y-23200	2023年2月11日	综合判定：合格	

231	GX-B1423/20-Y-23201	2023年2月11日	综合判定：合格	
232	GX-B1423/20-Y-23202	2023年2月11日	综合判定：合格	

233	GX-B1423/20-Y-23203	2023年2月11日	综合判定：合格	
234	GX-B1423/20-Y-23204	2023年2月11日	综合判定：合格	

235	GX-B1423/20-Y-23205	2023年2月11日	综合判定：合格	
236	GX-B1423/20-Y-23206	2023年2月11日	综合判定：合格	

237	GX-B1423/20-Y-23207	2023年2月11日	综合判定：合格	
238	GX-B1423/20-Y-23208	2023年2月11日	综合判定：合格	

239	GX-B1423/20-Y-23209	2023年2月11日	综合判定：合格	
240	GX-B1423/20-Y-23210	2023年2月11日	综合判定：合格	

241	GX-B1423/20-Y-23211	2023年2月11日	综合判定：合格	
242	GX-B1423/20-Y-23212	2023年2月11日	综合判定：合格	

243	GX-B1423/20-Y-23213	2023年2月11日	综合判定：合格	
244	GX-B1423/20-Y-23214	2023年2月11日	综合判定：合格	

245	GX-B1423/20-Y-23215	2023年2月11日	综合判定：合格	
246	GX-B1423/20-Y-23216	2023年2月11日	综合判定：合格	

247	GX-B1423/20-Y-23217	2023年2月11日	综合判定：合格	 A yellow XG105 truck is parked on a dirt surface. Two workers wearing safety gear are standing next to the truck. The truck has 'XG105' and 'M-3020' visible on its side. A yellow timestamp '2023/2/15' is in the bottom right corner.
248	GX-B1423/20-Y-23218	2023年2月11日	综合判定：合格	 A yellow XG105 truck is parked on a dirt surface. Two workers wearing safety gear are standing next to the truck. Some equipment is on the ground in front of the truck. The truck has 'XG105' and 'M-3020' visible on its side. A yellow timestamp '2023/2/15' is in the bottom right corner.

249	GX-B1423/20-Y-23219	2023年2月11日	综合判定：合格	 A photograph showing a person wearing a light-colored jacket and a dark cap sitting in the driver's seat of a yellow vehicle. The person is looking down at something in their hands. The vehicle's door is open, and the interior is visible. A yellow timestamp '2023/1/15' is in the bottom right corner.
250	GX-B1423/20-Y-23220	2023年2月11日	综合判定：合格	 A photograph of a yellow dump truck with its bed raised. A person in a light-colored uniform and a high-visibility vest is standing next to the truck. The truck has 'XG10E' and 'M-2321' visible on its side. A yellow timestamp '2023/1/15' is in the bottom right corner.

251	GX-B1423/20-Y-23221	2023年2月11日	综合判定：合格	 A photograph showing a person from a side profile, seated in the driver's seat of a vehicle. The person is wearing a light-colored jacket and is looking forward, with their hands on the steering wheel. The interior of the vehicle, including the dashboard and steering column, is visible. A yellow timestamp '2023/1/15' is located in the bottom right corner of the image.
252	GX-B1423/20-Y-23222	2023年2月11日	综合判定：合格	 A photograph of a large yellow dump truck parked on a dirt surface. The truck has 'M-3330' on the front and '924' on the side. Two people wearing safety gear are standing next to the truck. In the foreground, there are some pieces of equipment on the ground. A yellow timestamp '2023/1/15' is located in the bottom right corner of the image.

253	GX-B1423/20-Y-23223	2023年2月11日	综合判定：合格	
254	GX-B1423/20-Y-23224	2023年2月11日	综合判定：合格	

255	GX-B1423/20-Y-23225	2023年2月11日	综合判定：合格	 <p>A photograph showing a person wearing a white safety jacket, a black helmet, and a face mask sitting in the driver's seat of a yellow mining truck. The truck's door is open, and the person is looking towards the camera. A yellow timestamp '2023/1/15' is visible in the bottom right corner of the image.</p>
256	GX-B1423/20-Y-23226	2023年2月11日	综合判定：合格	 <p>A photograph of a yellow mining truck parked on a flat, sandy or dirt surface. A person in a blue uniform is standing to the left of the truck, looking towards it. The truck has 'M-3517' and 'DW' visible on its side. A yellow timestamp '2023/1/15' is visible in the bottom right corner of the image.</p>

257	GX-B1423/20-Y-23227	2023年2月11日	综合判定：合格	
258	GX-B1423/20-Y-23228	2023年2月11日	综合判定：合格	

259	GX-B1423/20-Y-23229	2023年2月11日	综合判定：合格	 A close-up photograph of a person wearing a dark winter hat and a light-colored jacket, sitting in the driver's seat of a yellow vehicle. The person is holding a small object in their hands. The background shows a clear blue sky. A yellow timestamp "2023/1/15" is visible in the bottom right corner of the image.
260	GX-B1423/20-Y-23230	2023年2月11日	综合判定：合格	 A photograph of a yellow dump truck (DW105A) parked in a desert-like environment. The truck is facing left, and its bed is raised. A person is standing near the front of the truck. The background shows a clear blue sky and a sandy ground. A yellow timestamp "2023/1/16" is visible in the bottom right corner of the image.

261	GX-B1423/20-Y-23231	2023年2月11日	综合判定：合格	
262	GX-B1423/20-Y-23232	2023年2月11日	综合判定：合格	

263	GX-B1423/20-Y-23233	2023年2月11日	综合判定：合格	
264	GX-B1423/20-Y-23234	2023年2月11日	综合判定：合格	

265	GX-B1423/20-Y-23235	2023年2月11日	综合判定：合格	 A yellow dump truck, model DW10GA, is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a license plate that reads 'M-3916'. A yellow timestamp '2023/2/11' is visible in the bottom right corner of the image.
266	GX-B1423/20-Y-23236	2023年2月11日	综合判定：合格	 A yellow dump truck, model DW10GA, is parked on a dirt surface. Two people are standing near the front of the truck. The truck has a license plate that reads 'M-3916'. A yellow timestamp '2023/2/11' is visible in the bottom right corner of the image.

267	GX-B1423/20-Y-23237	2023年2月11日	综合判定：合格	
268	GX-B1423/20-Y-23238	2023年2月11日	综合判定：合格	

269	GX-B1423/20-Y-23239	2023年2月11日	综合判定：合格	 A yellow dump truck with license plate M-3282 is parked on a dirt surface. Two workers in brown uniforms and hard hats are standing next to it. A toolbox is on the ground. A yellow timestamp '2023/2/14' is in the bottom right corner.
270	GX-B1423/20-Y-23240	2023年2月11日	综合判定：合格	 A yellow dump truck with license plate M-3283 is parked on a dirt surface. Two workers in brown uniforms and hard hats are standing next to it. A toolbox is on the ground. A yellow timestamp '2023/2/14' is in the bottom right corner.

271	GX-B1423/20-Y-23241	2023年2月11日	综合判定：合格	 <p>A photograph showing a yellow dump truck at a construction site. A worker in a brown uniform and cap stands in the foreground, looking towards the truck. The truck is parked on a dirt surface with a large pile of rocks or debris in the background. A yellow timestamp '2023/2/14' is visible in the bottom right corner of the image.</p>
272	GX-B1423/20-Y-23242	2023年2月11日	综合判定：合格	 <p>A photograph of a yellow dump truck with its bed raised. Two workers, one in a brown uniform and one in a high-visibility vest, stand next to the truck. The truck has 'M-8271' and '西子重工' (Xizi Heavy Industry) written on it. A yellow timestamp '2023/2/14' is visible in the bottom right corner of the image.</p>

273	GX-B1423/20-Y-23243	2023年2月11日	综合判定：合格	
274	GX-B1423/20-Y-23244	2023年2月11日	综合判定：合格	

275	GX-B1423/20-Y-23245	2023年2月11日	综合判定：合格	
276	GX-B1423/20-Y-23246	2023年2月11日	综合判定：合格	

277	GX-B1423/20-Y-23247	2023年2月11日	综合判定：合格	
278	GX-B1423/20-Y-23248	2023年2月11日	综合判定：合格	

279	GX-B1423/20-Y-23249	2023年2月11日	综合判定：合格	 A person wearing a white protective suit and a black helmet is seated in the operator's seat of a yellow vehicle, likely a truck or excavator. The person is looking forward, and their hands are on the controls. The interior of the vehicle is visible, showing a steering wheel and various instruments. A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.
280	GX-B1423/20-Y-23250	2023年2月11日	综合判定：合格	 A large yellow dump truck is parked on a dirt surface. Two people are standing in front of the truck. One person is wearing a red protective suit and a white helmet, while the other is wearing a brown uniform. The truck has "M-2271" written on its side. A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.

281	GX-B1423/20-Y-23251	2023年2月11日	综合判定：合格	
282	GX-B1423/20-Y-23252	2023年2月11日	综合判定：合格	

283	GX-B1423/20-Y-23253	2023年2月11日	综合判定：合格	
284	GX-B1423/20-Y-23254	2023年2月11日	综合判定：合格	

285	GX-B1423/20-Y-23255	2023年2月11日	综合判定：合格	 A photograph showing a person wearing a dark helmet and a light-colored jacket sitting in the driver's seat of a yellow vehicle, possibly a truck or a specialized machine. The person is looking forward, and the interior of the vehicle is visible. A timestamp '2023/2/11' is visible in the bottom right corner of the image.
286	GX-B1423/20-Y-23256	2023年2月11日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two people are standing in front of the truck. One person is wearing a blue hard hat and a high-visibility vest, while the other is wearing a light-colored uniform. The truck has 'M-4025' written on its side. The background is a clear blue sky.

287	GX-B1423/20-Y-23257	2023年2月11日	综合判定：合格	 A yellow dump truck with the identification number M-4025 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck's bed is raised.
288	GX-B1423/20-Y-23258	2023年2月11日	综合判定：合格	 A yellow dump truck with the identification number M-4032 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck's bed is raised.



289	GX-B1423/20-Y-23259	2023年2月11日	综合判定：合格	 A yellow dump truck with the identification number M-4022 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck's bed is raised.
290	GX-B1423/20-Y-23260	2023年2月11日	综合判定：合格	 A yellow dump truck with the identification number M-4011 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck's bed is raised. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the image.

291	GX-B1423/20-Y-23261	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck's license plate reads 'M-4002'. A date stamp '2023/1/17' is visible in the bottom right corner of the photo.
292	GX-B1423/20-Y-23262	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck's license plate reads 'M-4019'. A date stamp '2023/1/17' is visible in the bottom right corner of the photo.

293	GX-B1423/20-Y-23263	2023年2月11日	综合判定：合格	
294	GX-B1423/20-Y-23264	2023年2月11日	综合判定：合格	

295	GX-B1423/20-Y-23265	2023年2月11日	综合判定：合格	 A photograph of a yellow truck with license plate M-4001. Two workers in safety gear (hard hats and high-visibility vests) are standing in front of the truck. The date 2023/1/17 is visible in the bottom right corner of the image.
296	GX-B1423/20-Y-23266	2023年2月11日	综合判定：合格	 A photograph of a yellow dump truck with license plate M-4001. Two workers in safety gear (hard hats and high-visibility vests) are standing in front of the truck. The date 2023/1/17 is visible in the bottom right corner of the image.

297	GX-B1423/20-Y-23267	2023年2月11日	综合判定：合格	 A photograph showing a person wearing a white protective suit and a black hood, sitting in the driver's seat of a yellow vehicle. The person is looking down at something in their hands. The date '2023/1/17' is visible in the bottom right corner of the image.
298	GX-B1423/20-Y-23268	2023年2月11日	综合判定：合格	 A photograph of a yellow truck parked in a desert environment. A person in a white protective suit and a blue helmet is standing next to the truck, looking at something in their hands. The truck has 'SANY 951' written on its side.

299	GX-B1423/20-Y-23269	2023年2月11日	综合判定：合格	 A photograph showing three workers in safety gear (hard hats, high-visibility vests) standing in front of a yellow truck. The truck has a license plate that reads 'M-4035'. The scene is outdoors on a dirt surface under a clear sky.
300	GX-B1423/20-Y-23270	2023年2月11日	综合判定：合格	 A photograph showing a worker in a grey jacket and a dark hood operating a yellow excavator. The worker is seated in the operator's cab, looking towards the camera. The background is a bright, outdoor setting.

301	GX-B1423/20-Y-23271	2023年2月11日	综合判定：合格	 A photograph showing a yellow truck with the number 'M-4023' on its front. Two workers wearing hard hats and safety vests are standing in front of the truck. The background is a quarry or construction site. A yellow timestamp '2023/1/15' is visible in the bottom right corner of the image.
302	GX-B1423/20-Y-23272	2023年2月11日	综合判定：合格	 A photograph showing a yellow truck with the number 'M-4013' on its front. Two workers wearing hard hats and safety vests are standing in front of the truck. The background is a quarry or construction site. A yellow timestamp '2023/1/15' is visible in the bottom right corner of the image.

303	GX-B1423/20-Y-23273	2023年2月11日	综合判定：合格	
304	GX-B1423/20-Y-23274	2023年2月11日	综合判定：合格	

305	GX-B1423/20-Y-23275	2023年2月11日	综合判定：合格	
306	GX-B1423/20-Y-23276	2023年2月11日	综合判定：合格	

307	GX-B1423/20-Y-23277	2023年2月11日	综合判定：合格	 A yellow dump truck with the identification number M-4012 is parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/1/15 is visible in the bottom right corner of the photo.
308	GX-B1423/20-Y-23278	2023年2月11日	综合判定：合格	 A yellow dump truck with the identification number M-4021 is parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/1/15 is visible in the bottom right corner of the photo.

309	GX-B1423/20-Y-23279	2023年2月11日	综合判定：合格	 A yellow truck with the license plate M-4008 is shown from a front-three-quarter view. Two workers in safety gear stand in front of it. The date 2023/1/15 is visible in the bottom right corner of the photo.
310	GX-B1423/20-Y-23280	2023年2月11日	综合判定：合格	 A yellow truck with the license plate M-4009 is shown from a side view. Two workers in safety gear stand next to it. The date 2023/1/15 is visible in the bottom right corner of the photo.

311	GX-B1423/20-Y-23281	2023年2月11日	综合判定：合格	
312	GX-B1423/20-Y-23282	2023年2月11日	综合判定：合格	

313	GX-B1423/20-Y-23283	2023年2月11日	综合判定：合格	
314	GX-B1423/20-Y-23284	2023年2月11日	综合判定：合格	