

序号	报告编号	发布日期	结论	影像资料
305	GX-B1423/20-Y-23293	2022年2月3日	综合判定：合格	
306	GX-B1423/20-Y-23294	2022年2月3日	综合判定：合格	

307	GX-B1423/20-Y-23295	2022年2月3日	综合判定：合格	
308	GX-B1423/20-Y-23296	2022年2月3日	综合判定：合格	

309	GX-B1423/20-Y-23297	2022年2月3日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people in work clothes are standing near the front of the truck. A red and white traffic cone is visible on the ground to the left. The date '2023/1/5' is printed in the bottom right corner of the photo.
310	GX-B1423/20-Y-23298	2022年2月3日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people in work clothes are standing near the front of the truck. The date '2023/1/5' is printed in the bottom right corner of the photo.

311	GX-B1423/20-Y-23299	2022年2月3日	综合判定：合格	
312	GX-B1423/20-Y-23300	2022年2月3日	综合判定：合格	

313	GX-B1423/20-Y-23301	2022年2月3日	综合判定：合格	 <p>A photograph showing a yellow truck parked on a dirt road at a construction site. Several people are standing near the truck. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/1/5' is visible in the bottom right corner of the image.</p>
314	GX-B1423/20-Y-23302	2022年2月3日	综合判定：合格	 <p>A photograph showing a grey truck parked on a dirt road at a construction site. A person is standing near the truck. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/1/5' is visible in the bottom right corner of the image.</p>

315	GX-B1423/20-Y-23303	2022年2月3日	综合判定：合格	
316	GX-B1423/20-Y-23304	2022年2月3日	综合判定：合格	

317	GX-B1423/20-Y-23305	2022年2月3日	综合判定：合格	
318	GX-B1423/20-Y-23306	2022年2月3日	综合判定：合格	

319	GX-B1423/20-Y-23307	2022年2月2日	综合判定：合格	
320	GX-B1423/20-Y-23308	2022年2月2日	综合判定：合格	

321	GX-B1423/20-Y-23309	2022年2月2日	综合判定：合格	 A yellow truck is parked on a dirt road under a clear blue sky. Two people in winter clothing are standing in front of the truck. The license plate area shows the number '570'. A yellow timestamp '2023/1/6' is visible in the bottom right corner of the photo.
322	GX-B1423/20-Y-23310	2022年2月2日	综合判定：合格	 A dark-colored truck is parked on a dirt road under a clear blue sky. Two people in winter clothing are standing in front of the truck. The license plate area shows the number '135'. A yellow timestamp '2023/1/6' is visible in the bottom right corner of the photo.

323	GX-B1423/20-Y-23311	2022年2月2日	综合判定：合格	
324	GX-B1423/20-Y-23312	2022年2月2日	综合判定：合格	

325	GX-B1423/20-Y-23313	2022年2月3日	综合判定：合格	 A photograph of a white truck with a raised bed, likely used for spreading material, at a construction site. The truck is parked on a dirt surface. A person is visible near the front of the truck. The date '2023/1/6' is visible in the bottom right corner of the image.
326	GX-B1423/20-Y-23314	2022年2月3日	综合判定：合格	 A photograph of a white truck with a raised bed, similar to the one in the first row, at a construction site. The truck is parked on a dirt surface. A person is visible near the front of the truck. The date '2023/1/6' is visible in the bottom right corner of the image.

327	GX-B1423/20-Y-23315	2022年2月3日	综合判定：合格	
328	GX-B1423/20-Y-23316	2022年2月3日	综合判定：合格	

329	GX-B1423/20-Y-23317	2022年2月3日	综合判定：合格	
330	GX-B1423/20-Y-23318	2022年2月3日	综合判定：合格	

331	GX-B1423/20-Y-23319	2022年2月3日	综合判定：合格	
332	GX-B1423/20-Y-23320	2022年2月3日	综合判定：合格	

333	GX-B1423/20-Y-23321	2022年2月3日	综合判定：合格	
334	GX-B1423/20-Y-23322	2022年2月3日	综合判定：合格	

335	GX-B1423/20-Y-23323	2022年2月3日	综合判定：合格	
336	GX-B1423/20-Y-23324	2022年2月3日	综合判定：合格	

337	GX-B1423/20-Y-23325	2022年2月3日	综合判定：合格	
338	GX-B1423/20-Y-23326	2023年2月2日	综合判定：合格	

339	GX-B1423/20-Y-23327	2023年2月2日	综合判定：合格	
340	GX-B1423/20-Y-23328	2023年2月2日	综合判定：合格	




341	GX-B1423/20-Y-23329	2023年2月2日	综合判定：合格	
342	GX-B1423/20-Y-23330	2023年2月2日	综合判定：合格	

343	GX-B1423/20-Y-23331	2023年2月2日	综合判定：合格	
344	GX-B1423/20-Y-23332	2023年2月2日	综合判定：合格	

345	GX-B1423/20-Y-23333	2023年2月2日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two people are standing near the front of the truck. A yellow timestamp '2023/1/7' is visible in the bottom right corner of the image.
346	GX-B1423/20-Y-23334	2023年2月2日	综合判定：合格	 A blue dump truck is parked on a dirt surface under a clear blue sky. A person is standing near the front of the truck. A yellow timestamp '2023/1/7' is visible in the bottom right corner of the image.

347	GX-B1423/20-Y-23335	2023年2月2日	综合判定：合格	
348	GX-B1423/20-Y-23336	2023年2月2日	综合判定：合格	



349	GX-B1423/20-Y-23337	2023年2月2日	综合判定：合格	
350	GX-B1423/20-Y-23338	2023年2月2日	综合判定：合格	

351	GX-B1423/20-Y-23339	2023年2月2日	综合判定：合格	
352	GX-B1312/20-Y-23031	2023年2月7日	所检项目合格	
353	GX-B1312/20-Y-23028~23030	2023年2月7日	所检项目合格	

354	GX-B1416/22-Y-23001	2023年2月7日	合格	 A worker in a blue uniform and red helmet is working on a large blue industrial machine. The worker is using a tool to adjust or inspect a component of the machine. The date stamp '2023/1/8' is visible in the bottom right corner of the image.
355	GX-B1416/22-Y-23002	2023年2月7日	合格	 A worker in an orange uniform and helmet is standing on a metal walkway or platform. The worker is looking down at something in their hands. The date stamp '2023/1/8' is visible in the bottom right corner of the image.
356	GX-B1416/22-Y-23003	2023年2月7日	合格	 A worker in an orange uniform and helmet is working in a dark environment. The worker is standing near a metal railing or structure. The date stamp '2023/1/8' is visible in the bottom right corner of the image.

357	GX-B1352/21-Y-23001~23010	2023年2月7日	所检项目合格	
358	GX-B1352/21-Y-23011~23019	2023年2月7日	所检项目合格	

359	GX-B1359/21-Y-23001~23002	2023年2月7日	所检项目合格	
360	GX-B1359/21-Y-23003~230010	2023年2月7日	所检项目合格	

361	GX-B1310/21-Y-22146	2023年2月7日	符合标准要求	 <p>A worker in a blue uniform is operating a large red hand-cranked wheel on a piece of industrial machinery. The date stamp in the bottom right corner of the image is 2022/12/26.</p>
362	GX-B1310/21-Y-22147	2023年2月7日	符合标准要求	 <p>A worker in a yellow safety vest is working on a large green industrial machine. The date stamp in the bottom right corner of the image is 2022/12/26.</p>
363	GX-B1310/21-Y-22154	2023年2月7日	符合标准要求	 <p>A worker in a grey jacket and black helmet is kneeling and working on a piece of machinery on the ground. The date stamp in the bottom right corner of the image is 2022/12/26.</p>

364	GX-B1310/21-Y-22155	2023年2月7日	符合标准要求	 A worker wearing a white protective suit and a black helmet is kneeling on a metal platform, working on a piece of machinery. The worker is holding a tool and appears to be adjusting or inspecting a component. A yellow date stamp '2022/12/26' is visible in the bottom right corner of the image.
365	GX-B1310/21-Y-22148	2023年2月7日	符合标准要求	 A worker in a white protective suit and helmet is standing on a metal platform, working on a large piece of machinery. The worker is holding a tool and appears to be adjusting or inspecting a component. A yellow date stamp '2022/12/26' is visible in the bottom right corner of the image.
366	GX-B1310/21-Y-22149	2023年2月7日	符合标准要求	 A worker in a white protective suit and helmet is standing on a metal platform, working on a large piece of machinery. The worker is holding a tool and appears to be adjusting or inspecting a component. A yellow date stamp '2022/12/26' is visible in the bottom right corner of the image.

367	GX-B1310/21-Y-22150	2023年2月7日	符合标准要求	
368	GX-B1310/21-Y-22151	2023年2月7日	符合标准要求	
369	GX-B1310/21-Y-22152	2023年2月7日	符合标准要求	

370	GX-B1310/21-Y-22153	2023年2月7日	符合标准要求	
371	GX-B1495/20-Y-23068~23080	2023年2月3日	所检项目合格	

372	GX-B1495/20-Y-23081~23090	2023年2月3日	所检项目合格	
373	GX-B1321/20-Y-23004~23005	2023年2月7日	所检项目合格	
374	GX-B1312/20-Y-23022~23025	2023年2月7日	所检项目合格	

375	GX-B1312/20-Y-23026~23027	2023年2月7日	所检项目合格	
-----	---------------------------	-----------	--------	---