

序号	报告编号	发布日期	结论	影像资料
529	GX-B1423/20-Y-23071	2023年2月11日	综合判定：合格	
530	GX-B1423/20-Y-23072	2023年2月11日	综合判定：合格	

531	GX-B1423/20-Y-23073	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people, one in a blue jacket and one in a grey uniform, are standing in front of the truck. The truck has '同力重工' (Tongli Heavy Industry) written on its side. A yellow timestamp '2023/1/9' is visible in the bottom right corner of the photo.
532	GX-B1423/20-Y-23074	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two people, one in a blue jacket and one in a grey uniform, are standing in front of the truck. The truck has '同力重工' (Tongli Heavy Industry) written on its side. A yellow timestamp '2023/1/9' is visible in the bottom right corner of the photo.

533	GX-B1423/20-Y-23075	2023年2月11日	综合判定：合格	
534	GX-B1423/20-Y-23076	2023年2月11日	综合判定：合格	

535	GX-B1423/20-Y-23077	2023年2月11日	综合判定：合格	
536	GX-B1423/20-Y-23078	2023年2月11日	综合判定：合格	

537	GX-B1423/20-Y-23079	2023年2月11日	综合判定：合格	
538	GX-B1423/20-Y-23080	2023年2月11日	综合判定：合格	

539	GX-B1423/20-Y-23081	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of it. The truck has a date stamp '2023/1/9' in the bottom right corner.
540	GX-B1423/20-Y-23082	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of it. The truck has a date stamp '2023/1/9' in the bottom right corner.

541	GX-B1423/20-Y-23083	2023年2月11日	综合判定：合格	
542	GX-B1423/20-Y-23084	2023年2月11日	综合判定：合格	

543	GX-B1423/20-Y-23085	2023年2月11日	综合判定：合格	
544	GX-B1423/20-Y-23086	2023年2月11日	综合判定：合格	



545	GX-B1423/20-Y-23087	2023年2月11日	综合判定：合格	
546	GX-B1423/20-Y-23088	2023年2月11日	综合判定：合格	

547	GX-B1423/20-Y-23089	2023年2月11日	综合判定：合格	 A photograph of a large orange SANYI SRT620 truck. Two workers in safety gear are standing in front of the truck, one holding a clipboard. The truck has the number '4' on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.
548	GX-B1423/20-Y-23090	2023年2月11日	综合判定：合格	 A photograph of a large orange SANYI SRT620 truck from a different angle. Two workers in safety gear are standing in front of the truck, one holding a clipboard. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.

549	GX-B1423/20-Y-23091	2023年2月11日	综合判定：合格	
550	GX-B1423/20-Y-23092	2023年2月11日	综合判定：合格	

551	GX-B1423/20-Y-23093	2023年2月11日	综合判定：合格	
552	GX-B1423/20-Y-23094	2023年2月11日	综合判定：合格	

553	GX-B1423/20-Y-23095	2023年2月11日	综合判定：合格	
554	GX-B1423/20-Y-23096	2023年2月11日	综合判定：合格	

555	GX-B1423/20-Y-23097	2023年2月11日	综合判定：合格	
556	GX-B1423/20-Y-23098	2023年2月11日	综合判定：合格	

557	GX-B1423/20-Y-23099	2023年2月11日	综合判定：合格	
558	GX-B1423/20-Y-23100	2023年2月11日	综合判定：合格	

559	GX-B1423/20-Y-23101	2023年2月11日	综合判定：合格	
560	GX-B1423/20-Y-23102	2023年2月11日	综合判定：合格	



561	GX-B1423/20-Y-23103	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number 2183 on its side. Two workers in safety gear are standing next to it. The date 2023/1/10 is visible in the bottom right corner of the photo.</p>
562	GX-B1423/20-Y-23104	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number 2177 on its side. Two workers in safety gear are standing next to it. The date 2023/1/10 is visible in the bottom right corner of the photo.</p>

563	GX-B1423/20-Y-23105	2023年2月11日	综合判定：合格	
564	GX-B1423/20-Y-23106	2023年2月11日	综合判定：合格	

565	GX-B1423/20-Y-23107	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. The license plate number '2179' is visible on the side of the truck. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/1/10' is in the bottom right corner.</p>
566	GX-B1423/20-Y-23108	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. The license plate number '2178' is visible on the side of the truck. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/1/10' is in the bottom right corner.</p>

567	GX-B1423/20-Y-23109	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/1/10' is visible in the bottom right corner of the image.
568	GX-B1423/20-Y-23110	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/1/10' is visible in the bottom right corner of the image.

569	GX-B1423/20-Y-23111	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with license plate number 2111 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/1/10' is visible in the bottom right corner of the photo.</p>
570	GX-B1423/20-Y-23112	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with license plate number 2120 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/1/11' is visible in the bottom right corner of the photo.</p>

571	GX-B1423/20-Y-23113	2023年2月11日	综合判定：合格	
572	GX-B1423/20-Y-23114	2023年2月11日	综合判定：合格	

573	GX-B1423/20-Y-23115	2023年2月11日	综合判定：合格	
-----	---------------------	------------	---------	---

574	GX-B1423/20-Y-23116	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number '5' on its side. Two workers in safety gear stand in front of it. The date '2023/1/11' is visible in the bottom right corner of the photo.</p>
575	GX-B1423/20-Y-23117	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number '2058' on its side. Two workers in safety gear stand in front of it. The date '2023/1/11' is visible in the bottom right corner of the photo.</p>



576	GX-B1423/20-Y-23118	2023年2月11日	综合判定：合格	
-----	---------------------	------------	---------	---

577	GX-B1423/20-Y-23119	2023年2月11日	综合判定：合格	
578	GX-B1423/20-Y-23120	2023年2月11日	综合判定：合格	

579	GX-B1423/20-Y-23121	2023年2月11日	综合判定：合格	
580	GX-B1423/20-Y-23122	2023年2月11日	综合判定：合格	

581	GX-B1423/20-Y-23123	2023年2月11日	综合判定：合格	
582	GX-B1423/20-Y-23124	2023年2月11日	综合判定：合格	

583	GX-B1423/20-Y-23125	2023年2月11日	综合判定：合格	 A yellow dump truck with the number 2128 on its side. Two workers in blue and grey uniforms are standing next to it. A date stamp '2023/1/12' is visible in the bottom right corner of the photo.
584	GX-B1423/20-Y-23126	2023年2月11日	综合判定：合格	 A yellow dump truck with the number 2001 on its side. Two workers in blue and grey uniforms are standing next to it. A date stamp '2023/1/12' is visible in the bottom right corner of the photo.

585	GX-B1423/20-Y-23127	2023年2月11日	综合判定：合格	
586	GX-B1423/20-Y-23128	2023年2月11日	综合判定：合格	

587	GX-B1423/20-Y-23129	2023年2月11日	综合判定：合格	
588	GX-B1423/20-Y-23130	2023年2月11日	综合判定：合格	

589	GX-B1423/20-Y-23131	2023年2月11日	综合判定：合格	 <p>A yellow XCMG XG106 dump truck is parked on a paved surface. Two workers in safety gear are standing next to it. The license plate number 2292 is visible on the side of the truck. A date stamp '2023/1/12' is in the bottom right corner.</p>
590	GX-B1423/20-Y-23132	2023年2月11日	综合判定：合格	 <p>A yellow XCMG XG106 dump truck is parked on a paved surface. Two workers in safety gear are standing next to it. The license plate number 2276 is visible on the side of the truck. A date stamp '2023/1/12' is in the bottom right corner.</p>



591	GX-B1423/20-Y-23133	2023年2月11日	综合判定：合格	 A yellow dump truck with the identification number M-272 on the side of the cab. The truck is parked on a dirt surface. Two workers in blue and grey uniforms are standing near the front wheel. The truck's body has the numbers 2 2 7 2 on it. A date stamp '2023/1/12' is visible in the bottom right corner of the photo.
592	GX-B1423/20-Y-23134	2023年2月11日	综合判定：合格	 A yellow dump truck with the identification number M-286 on the side of the cab. The truck is parked on a dirt surface. Two workers in blue and grey uniforms are standing near the front wheel. The truck's body has the numbers 2 2 8 6 on it. A date stamp '2023/1/12' is visible in the bottom right corner of the photo.

593	GX-B1423/20-Y-23135	2023年2月11日	综合判定：合格	 <p>A yellow XG106 dump truck is parked on a dirt surface. The license plate number '2295' is visible on the side of the truck. Two workers in safety gear are standing near the front of the truck. A timestamp '2023/1/13' is visible in the bottom right corner of the photo.</p>
594	GX-B1423/20-Y-23136	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. The license plate number '2278' is visible on the side of the truck. Two workers in safety gear are standing near the front of the truck. A timestamp '2023/1/13' is visible in the bottom right corner of the photo.</p>

595	GX-B1423/20-Y-23137	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with license plate M-2277 is parked on a dirt surface. Two workers in safety gear are standing near the front. A traffic cone is visible. The date 2023/1/13 is printed in the bottom right corner of the photo.</p>
596	GX-B1423/20-Y-23138	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with license plate M-2275 is parked on a dirt surface. Two workers in safety gear are standing near the front. A traffic cone is visible. The date 2023/1/13 is printed in the bottom right corner of the photo.</p>

597	GX-B1423/20-Y-23139	2023年2月11日	综合判定：合格	
598	GX-B1423/20-Y-23140	2023年2月11日	综合判定：合格	

599	GX-B1423/20-Y-23141	2023年2月11日	综合判定：合格	
600	GX-B1423/20-Y-23142	2023年2月11日	综合判定：合格	

601	GX-B1423/20-Y-23143	2023年2月11日	综合判定：合格	
602	GX-B1423/20-Y-23144	2023年2月11日	综合判定：合格	

603	GX-B1423/20-Y-23145	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number 2296 on its side. Two workers in safety gear are standing next to it. The date 2023/1/13 is visible in the bottom right corner of the photo.</p>
604	GX-B1423/20-Y-23146	2023年2月11日	综合判定：合格	 <p>A yellow dump truck with the number 2270 on its side. Two workers in safety gear are standing next to it. The date 2023/1/13 is visible in the bottom right corner of the photo.</p>

605	GX-B1423/20-Y-23147	2023年2月11日	综合判定：合格	
606	GX-B1423/20-Y-23148	2023年2月11日	综合判定：合格	




607	GX-B1423/20-Y-23149	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. The side of the truck features the numbers '2 2 2 6' in white. Two people are standing near the front of the truck. A yellow timestamp '2023/2/11' is visible in the bottom right corner of the photo.
608	GX-B1423/20-Y-23150	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. The side of the truck features the numbers '2 2 1 7' in white. Two people are standing near the front of the truck. A yellow timestamp '2023/2/11' is visible in the bottom right corner of the photo.

609	GX-B1423/20-Y-23151	2023年2月11日	综合判定：合格	 A yellow heavy-duty truck with a dump body is parked on a dirt surface. Two people are standing near the front wheel. The truck has the license plate GX-B1423/20-Y-23151 and the number 2260 on its side. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.
610	GX-B1423/20-Y-23152	2023年2月11日	综合判定：合格	 A yellow heavy-duty truck with a dump body is parked on a dirt surface. Two people are standing near the front wheel. The truck has the license plate GX-B1423/20-Y-23152 and the number 2246 on its side. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.

611	GX-B1423/20-Y-23153	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. The truck has the numbers '2', '2', '3', and '3' painted on its side. Two people are standing in front of the truck. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.</p>
612	GX-B1423/20-Y-23154	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. The truck has the numbers '2', '3', '2', and '5' painted on its side. Two people are standing in front of the truck. A yellow timestamp '2023/1/14' is visible in the bottom right corner of the photo.</p>

613	GX-B1423/20-Y-23155	2023年2月11日	综合判定：合格	
614	GX-B1423/20-Y-23156	2023年2月11日	综合判定：合格	



615	GX-B1423/20-Y-23157	2023年2月11日	综合判定：合格	
616	GX-B1423/20-Y-23158	2023年2月11日	综合判定：合格	

617	GX-B1423/20-Y-23159	2023年2月11日	综合判定：合格	
618	GX-B1423/20-Y-23160	2023年2月11日	综合判定：合格	

619	GX-B1423/20-Y-23161	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the number '2' on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.
620	GX-B1423/20-Y-23162	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the number '2' on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.

621	GX-B1423/20-Y-23163	2023年2月11日	综合判定：合格	
622	GX-B1423/20-Y-23164	2023年2月11日	综合判定：合格	



623	GX-B1423/20-Y-23165	2023年2月11日	综合判定：合格	
624	GX-B1423/20-Y-23166	2023年2月11日	综合判定：合格	

625	GX-B1423/20-Y-23167	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in white protective suits and masks are standing near the front of the truck. The truck has the number '2' on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.
626	GX-B1423/20-Y-23168	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers, one in a red safety vest and one in a grey jacket, are standing near the front of the truck. The truck has the number '2' on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.

627	GX-B1423/20-Y-23169	2023年2月11日	综合判定：合格	 <p>A photograph of a yellow TONLY 2306 truck. Two workers wearing safety vests and hard hats are standing in front of the truck. The date 2023/1/10 is visible in the bottom right corner of the image.</p>
628	GX-B1423/20-Y-23170	2023年2月11日	综合判定：合格	 <p>A photograph of a yellow truck, likely a dump truck, with two workers in safety gear standing next to it. The date 2023/1/10 is visible in the bottom right corner of the image.</p>

629	GX-B1423/20-Y-23171	2023年2月11日	综合判定：合格	
630	GX-B1423/20-Y-23172	2023年2月11日	综合判定：合格	

631	GX-B1423/20-Y-23173	2023年2月11日	综合判定：合格	 A yellow MT980 dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The truck has 'MT980' and '2148' visible on its side. A yellow timestamp '2023/1/10' is in the bottom right corner.
632	GX-B1423/20-Y-23174	2023年2月11日	综合判定：合格	 A yellow MT980 dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The truck has 'MT980' visible on its side. A yellow timestamp '2023/1/11' is in the bottom right corner.

633	GX-B1423/20-Y-23175	2023年2月11日	综合判定：合格	
634	GX-B1423/20-Y-23176	2023年2月11日	综合判定：合格	

635	GX-B1423/20-Y-23177	2023年2月11日	综合判定：合格	
636	GX-B1423/20-Y-23178	2023年2月11日	综合判定：合格	

637	GX-B1423/20-Y-23179	2023年2月11日	综合判定：合格	
638	GX-B1423/20-Y-23180	2023年2月11日	综合判定：合格	



639	GX-B1423/20-Y-23181	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/1/11' is visible in the bottom right corner of the photo.
640	GX-B1423/20-Y-23182	2023年2月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/1/11' is visible in the bottom right corner of the photo.

641	GX-B1423/20-Y-23183	2023年2月11日	综合判定：合格	
642	GX-B1423/20-Y-23184	2023年2月11日	综合判定：合格	

643	GX-B1423/20-Y-23185	2023年2月11日	综合判定：合格	
644	GX-B1423/20-Y-23186	2023年2月11日	综合判定：合格	

645	GX-B1423/20-Y-23187	2023年2月11日	综合判定：合格	
646	GX-B1423/20-Y-23188	2023年2月11日	综合判定：合格	

647	GX-B1423/20-Y-23189	2023年2月11日	综合判定：合格	
648	GX-B1423/20-Y-23190	2023年2月11日	综合判定：合格	

649	GX-B1423/20-Y-23191	2023年2月11日	综合判定：合格	
650	GX-B1423/20-Y-23192	2023年2月11日	综合判定：合格	

651	GX-B1423/20-Y-23193	2023年2月11日	综合判定：合格	
652	GX-B1423/20-Y-23194	2023年2月11日	综合判定：合格	

653	GX-B1423/20-Y-23195	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is shown from a side-rear perspective. The truck has the identification number '2229' painted on its side. Two workers in safety gear are standing next to the truck. A date stamp '2023/1/12' is visible in the bottom right corner of the image.</p>
654	GX-B1423/20-Y-23196	2023年2月11日	综合判定：合格	 <p>A yellow dump truck is shown from a side-rear perspective. The truck has the identification number '2231' painted on its side. Two workers in safety gear are standing next to the truck. A date stamp '2023/1/12' is visible in the bottom right corner of the image.</p>



655	GX-B1423/20-Y-23197	2023年2月11日	综合判定：合格	
656	GX-B1423/20-Y-23198	2023年2月11日	综合判定：合格	

657	GX-B1423/20-Y-23199	2023年2月11日	综合判定：合格	
658	GX-B1423/20-Y-23200	2023年2月11日	综合判定：合格	

659	GX-B1423/20-Y-23201	2023年2月11日	综合判定：合格	
660	GX-B1423/20-Y-23202	2023年2月11日	综合判定：合格	

661	GX-B1423/20-Y-23203	2023年2月11日	综合判定：合格	
662	GX-B1423/20-Y-23204	2023年2月11日	综合判定：合格	

663	GX-B1423/20-Y-23205	2023年2月11日	综合判定：合格	
664	GX-B1423/20-Y-23206	2023年2月11日	综合判定：合格	

665	GX-B1423/20-Y-23207	2023年2月11日	综合判定：合格	
666	GX-B1423/20-Y-23208	2023年2月11日	综合判定：合格	

667	GX-B1423/20-Y-23209	2023年2月11日	综合判定：合格	
668	GX-B1423/20-Y-23210	2023年2月11日	综合判定：合格	

669	GX-B1423/20-Y-23211	2023年2月11日	综合判定：合格	
670	GX-B1423/20-Y-23212	2023年2月11日	综合判定：合格	



671	GX-B1423/20-Y-23213	2023年2月11日	综合判定：合格	
672	GX-B1423/20-Y-23214	2023年2月11日	综合判定：合格	

673	GX-B1423/20-Y-23215	2023年2月11日	综合判定：合格	
674	GX-B1423/20-Y-23216	2023年2月11日	综合判定：合格	

675	GX-B1423/20-Y-23217	2023年2月11日	综合判定：合格	 <p>A yellow XG105 dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has 'XG105' and 'M-112' visible on its side. A yellow timestamp '2023/1/15' is in the bottom right corner of the photo.</p>
676	GX-B1423/20-Y-23218	2023年2月11日	综合判定：合格	 <p>A yellow XG105 dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. Some equipment is on the ground in front of the truck. The truck has 'XG105' and 'M-112' visible on its side. A yellow timestamp '2023/1/15' is in the bottom right corner of the photo.</p>

677	GX-B1423/20-Y-23219	2023年2月11日	综合判定：合格	 A photograph showing a person wearing a light-colored jacket and a dark hat sitting in the driver's seat of a yellow vehicle. The person is looking down at something in their hands. The vehicle's door is open, and the interior is visible. A yellow timestamp "2023/1/15" is in the bottom right corner.
678	GX-B1423/20-Y-23220	2023年2月11日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. The truck has "XIS106" and "M-3331" visible on its side. Two workers in light-colored uniforms and hard hats are standing near the front of the truck. A yellow timestamp "2023/1/15" is in the bottom right corner.

679	GX-B1423/20-Y-23221	2023年2月11日	综合判定：合格	 A photograph showing a person wearing a light-colored uniform and a dark cap, sitting in the driver's seat of a vehicle. The person is looking forward, and their hands are on the steering wheel. The interior of the vehicle is visible, including the dashboard and steering wheel. A yellow timestamp "2023/1/19" is visible in the bottom right corner of the image.
680	GX-B1423/20-Y-23222	2023年2月11日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two people wearing safety gear (hard hats and high-visibility vests) are standing next to the truck. One person is closer to the front, and the other is further back. There are some equipment cases on the ground in the foreground. A yellow timestamp "2023/1/19" is visible in the bottom right corner of the image.

681	GX-B1423/20-Y-23223	2023年2月11日	综合判定：合格	
682	GX-B1423/20-Y-23224	2023年2月11日	综合判定：合格	

683	GX-B1423/20-Y-23225	2023年2月11日	综合判定：合格	 A photograph showing a person wearing a white protective suit and a black mask, sitting in the driver's seat of a yellow truck. The person is looking down, possibly at a device or document. The truck's door is open, and the interior of the cab is visible. A yellow timestamp "2023/1/15" is in the bottom right corner.
684	GX-B1423/20-Y-23226	2023年2月11日	综合判定：合格	 A photograph of a yellow truck parked in an open, flat, sandy area under a clear blue sky. A person in a blue uniform is standing to the left of the truck, looking towards it. The truck has "DW" and "W-101" visible on its side. A yellow timestamp "2023/1/15" is in the bottom right corner.

685	GX-B1423/20-Y-23227	2023年2月11日	综合判定：合格	 A yellow dump truck, model DW105A, is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has 'DW105A' and '解工機品' printed on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.
686	GX-B1423/20-Y-23228	2023年2月11日	综合判定：合格	 A yellow dump truck, model DW105A, is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has 'DW105A' and '解工機品' printed on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the photo.



687	GX-B1423/20-Y-23229	2023年2月11日	综合判定：合格	 A close-up photograph of a worker wearing a dark helmet and a light-colored jacket, sitting inside the yellow cab of a large vehicle. The worker is holding a small object in their hands. The date '2023/1/10' is visible in the bottom right corner of the image.
688	GX-B1423/20-Y-23230	2023年2月11日	综合判定：合格	 A photograph of a yellow dump truck, model DW105A, parked on a dirt surface. A worker in a light-colored uniform is standing next to the truck, and another worker is visible near the front. The date '2023/1/10' is visible in the bottom right corner of the image.

689	GX-B1423/20-Y-23231	2023年2月11日	综合判定：合格	
690	GX-B1423/20-Y-23232	2023年2月11日	综合判定：合格	

691	GX-B1423/20-Y-23233	2023年2月11日	综合判定：合格	 <p>A yellow DeWu DW105A dump truck is parked on a sandy surface. A person wearing a yellow safety vest and a white hard hat stands next to the truck. A toolbox is open on the ground in the foreground. The truck has 'DW105A' and '德工' written on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the image.</p>
692	GX-B1423/20-Y-23234	2023年2月11日	综合判定：合格	 <p>A yellow DeWu dump truck is parked on a sandy surface. A person is standing in the distance to the left of the truck. The truck has 'DW' visible on its side. A yellow timestamp '2023/1/10' is visible in the bottom right corner of the image.</p>

693	GX-B1423/20-Y-23235	2023年2月11日	综合判定：合格	 A yellow dump truck, model DW105A, is shown in a desert-like environment. Two people in safety gear are standing near the front of the truck. The truck has 'DW105A' and 'V-388' printed on it. A yellow timestamp '2023/2/11' is visible in the bottom right corner of the photo.
694	GX-B1423/20-Y-23236	2023年2月11日	综合判定：合格	 A yellow dump truck, model DW105A, is shown in a desert-like environment. Two people in safety gear are standing near the front of the truck. The truck has 'DW105A' and 'V-388' printed on it. A yellow timestamp '2023/2/11' is visible in the bottom right corner of the photo.

695	GX-B1423/20-Y-23237	2023年2月11日	综合判定：合格	
696	GX-B1423/20-Y-23238	2023年2月11日	综合判定：合格	

697	GX-B1423/20-Y-23239	2023年2月11日	综合判定：合格	 A yellow dump truck with license plate M-3282 is parked on a dirt surface. Two men in work clothes and hard hats are standing next to it. A date stamp '2023/1/14' is visible in the bottom right corner of the photo.
698	GX-B1423/20-Y-23240	2023年2月11日	综合判定：合格	 A yellow dump truck with license plate M-3283 is parked on a dirt surface. Two men in work clothes and hard hats are standing next to it. A date stamp '2023/1/14' is visible in the bottom right corner of the photo.

699	GX-B1423/20-Y-23241	2023年2月11日	综合判定：合格	 <p>A photograph showing a yellow dump truck in a quarry. A worker in a brown uniform and cap stands to the left of the truck, holding a clipboard. Another worker is visible in the driver's seat. The background shows a large pile of grey material. A yellow timestamp '2023/1/14' is in the bottom right corner.</p>
700	GX-B1423/20-Y-23242	2023年2月11日	综合判定：合格	 <p>A photograph of a yellow dump truck with its bed raised. Two workers in brown uniforms and caps stand in front of the truck. The truck has 'M-3271' on its side. A yellow timestamp '2023/1/14' is in the bottom right corner.</p>

701	GX-B1423/20-Y-23243	2023年2月11日	综合判定：合格	
702	GX-B1423/20-Y-23244	2023年2月11日	综合判定：合格	



703	GX-B1423/20-Y-23245	2023年2月11日	综合判定：合格	 A yellow XCMG M-3279 dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has "西力重工" (Xili Heavy Industry) written on its side and "M-3279" on the front. A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.
704	GX-B1423/20-Y-23246	2023年2月11日	综合判定：合格	 A worker wearing a white protective suit and a black helmet is sitting in the driver's seat of a yellow machine, operating it. The machine's interior and steering wheel are visible. A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.

705	GX-B1423/20-Y-23247	2023年2月11日	综合判定：合格	 A yellow dump truck with license plate M-3263 is parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/4/14 is visible in the bottom right corner of the photo.
706	GX-B1423/20-Y-23248	2023年2月11日	综合判定：合格	 A yellow dump truck with license plate M-3270 is parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/4/14 is visible in the bottom right corner of the photo.

707	GX-B1423/20-Y-23249	2023年2月11日	综合判定：合格	 A person wearing a white protective suit and a black hood is seated in the operator's seat of a yellow vehicle, likely a forklift or similar industrial machine. The person is looking forward, and their hands are on the controls. The interior of the vehicle is visible, showing a steering wheel and various instruments. A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.
708	GX-B1423/20-Y-23250	2023年2月11日	综合判定：合格	 A large yellow dump truck is parked on a dirt surface. Two people are standing in front of the truck: one in a red protective suit and another in a white protective suit. The truck has "M-3278" written on its side. A yellow timestamp "2023/1/14" is visible in the bottom right corner of the image.

709	GX-B1423/20-Y-23251	2023年2月11日	综合判定：合格	
710	GX-B1423/20-Y-23252	2023年2月11日	综合判定：合格	

711	GX-B1423/20-Y-23253	2023年2月11日	综合判定：合格	
712	GX-B1423/20-Y-23254	2023年2月11日	综合判定：合格	

713	GX-B1423/20-Y-23255	2023年2月11日	综合判定：合格	
714	GX-B1423/20-Y-23256	2023年2月10日	综合判定：合格	

715	GX-B1423/20-Y-23257	2023年2月10日	综合判定：合格	 A yellow dump truck with the identification number M-4025 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck.
716	GX-B1423/20-Y-23258	2023年2月10日	综合判定：合格	 A yellow dump truck with the identification number M-4032 is parked on a dirt surface. Two workers in safety gear are standing in front of the truck.

717	GX-B1423/20-Y-23259	2023年2月10日	综合判定：合格	 A yellow dump truck with the identification number M-4022 is parked on a dirt surface. Two workers wearing blue hard hats and high-visibility vests are standing next to the truck, one holding a clipboard. The truck's bed is raised.
718	GX-B1423/20-Y-23260	2023年2月10日	综合判定：合格	 A yellow dump truck with the identification number M-4011 is parked on a dirt surface. Two workers wearing blue hard hats and high-visibility vests are standing next to the truck, one holding a clipboard. The truck's bed is raised. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the photo.



719	GX-B1423/20-Y-23261	2023年2月10日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck's bed is raised. A date stamp '2023/1/17' is visible in the bottom right corner of the photo.
720	GX-B1423/20-Y-23262	2023年2月10日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck's bed is raised. A date stamp '2023/1/17' is visible in the bottom right corner of the photo.

721	GX-B1423/20-Y-23263	2023年2月10日	综合判定：合格	 A yellow dump truck with license plate M-4019 is parked on a dirt surface. Two workers in safety gear are standing next to it.
722	GX-B1423/20-Y-23264	2023年2月10日	综合判定：合格	 A yellow dump truck with license plate M-4023 is parked on a dirt surface. Two workers in safety gear are standing next to it.

723	GX-B1423/20-Y-23265	2023年2月10日	综合判定：合格	 A yellow truck with 'M-4001' on the front. Two workers in safety gear stand in front of it. A date stamp '2023/1/17' is in the bottom right corner.
724	GX-B1423/20-Y-23266	2023年2月10日	综合判定：合格	 A yellow truck with 'M-4001' on the side of the dump body. Two workers in safety gear stand in front of it. A date stamp '2023/1/17' is in the bottom right corner.

725	GX-B1423/20-Y-23267	2023年2月10日	综合判定：合格	 A photograph showing a person wearing a white protective suit and a black hood, sitting in the driver's seat of a yellow vehicle. The person is looking down, possibly at a control panel or instrument. The vehicle's interior is visible, including the steering wheel and dashboard. A yellow timestamp "2023/1/17" is visible in the bottom right corner of the image.
726	GX-B1423/20-Y-23268	2023年2月10日	综合判定：合格	 A photograph of a yellow truck parked in a desert environment. The truck is a large, heavy-duty vehicle with a yellow body and a white cab. A person wearing a white protective suit and a blue helmet is standing in the foreground, looking towards the truck. The ground is sandy and there are some small white cones or markers on the ground. The sky is clear and blue.

727	GX-B1423/20-Y-23269	2023年2月10日	综合判定：合格	
728	GX-B1423/20-Y-23270	2023年2月10日	综合判定：合格	



729	GX-B1423/20-Y-23271	2023年2月10日	综合判定：合格	 A yellow mining truck with the identification number M-4029 is parked on a dirt road. Two workers in safety gear are standing in front of the truck. The background shows a rocky hillside. A yellow timestamp '2023/1/15' is visible in the bottom right corner of the photo.
730	GX-B1423/20-Y-23272	2023年2月10日	综合判定：合格	 A yellow mining truck with the identification number M-4010 is parked on a dirt road. Two workers in safety gear are standing in front of the truck. The background shows a rocky hillside. A yellow timestamp '2023/1/15' is visible in the bottom right corner of the photo.

731	GX-B1423/20-Y-23273	2023年2月10日	综合判定：合格	
732	GX-B1423/20-Y-23274	2023年2月10日	综合判定：合格	

733	GX-B1423/20-Y-23275	2023年2月10日	综合判定：合格	
734	GX-B1423/20-Y-23276	2023年2月10日	综合判定：合格	




735	GX-B1423/20-Y-23277	2023年2月10日	综合判定：合格	 A yellow dump truck with the identification number M-4012 is parked on a dirt surface. Two workers in safety gear are standing next to it. The photo is dated 2023/1/15.
736	GX-B1423/20-Y-23278	2023年2月10日	综合判定：合格	 A yellow dump truck with the identification number M-4021 is parked on a dirt surface. Two workers in safety gear are standing next to it. The photo is dated 2023/1/15.

737	GX-B1423/20-Y-23279	2023年2月10日	综合判定：合格	
738	GX-B1423/20-Y-23280	2023年2月10日	综合判定：合格	

739	GX-B1423/20-Y-23281	2023年2月10日	综合判定：合格	
740	GX-B1423/20-Y-23282	2023年2月10日	综合判定：合格	

741	GX-B1423/20-Y-23283	2023年2月10日	综合判定：合格	
742	GX-B1423/20-Y-23284	2023年2月10日	综合判定：合格	

743	GX-B1310/21-Y-23009	2023年2月14日	符合标准要求。	
744	GX-B1428/21-Y-23009	2023年2月14日	无缺陷痕迹显示。	
745	GX-B1310/21-Y-23010	2023年2月14日	符合标准要求。	

746	GX-B1428/21-Y-23010	2023年2月14日	无缺陷迹痕显示。	
-----	---------------------	------------	----------	---