

序号	报告编号	发布日期	结论	影像资料
97	GX-B1598/21-5-22018	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为1.62%，小于5%为正常	
98	GX-B1598/21-5-22019	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为1.85%，小于5%为正常	
99	GX-B1598/21-5-22020	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为1.72%，小于5%为正常	
100	GX-B1598/21-5-22021	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为2.47%，小于5%为正常	

101	GX-B1598/21-5-22022	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为2.85%，小于5%为正常	
102	GX-B1598/21-5-22023	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为2.30%，小于5%为正常	
103	GX-B1598/21-5-22024	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为0.99%，小于5%为正常	
104	GX-B1598/21-5-22025	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为0.42%，小于5%为正常	
105	GX-B1598/21-5-22026	2023. 1. 11	实测钢丝绳有效截面积损失百分比最大为0.58%，小于5%为正常	