

序号	报告编号	发布日期	结论	影像资料
149	GX-B1365/20-A-23014	2023/2/16	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
150	GX-B1366/20-A-23011	2023/2/16	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
151	GX-B1365/20-A-23013	2023/2/16	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
152	GX-B1366/20-A-23010	2023/2/16	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
153	GX-B1365/20-A-23011	2023/2/16	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
154	GX-B1366/20-A-23008	2023/2/16	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
155	GX-B1363/22-A-23046	2023/2/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
156	GX-B1363/22-A-23047	2023/2/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
157	GX-B1363/22-A-23048	2023/2/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
158	GX-B1363/22-A-23049	2023/2/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
159	GX-B1363/22-A-23050	2023/2/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
160	GX-B1363/22-A-23051	2023/2/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
161	GX-B1509/20-A-23001	2023/2/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
162	GX-B1364/22-A-23082	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
163	GX-B1364/22-A-23087	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
164	GX-B1364/22-A-23088	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
165	GX-B1364/22-A-23083	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
166	GX-B1364/22-A-23084	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
167	GX-B1364/22-A-23085	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
168	GX-B1364/22-A-23086	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
169	GX-B1363/22-A-23040	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
170	GX-B1363/22-A-23039	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
171	GX-B1367/22-A-23022	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
172	GX-B1367/22-A-23021	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
173	GX-B1367/22-A-23023	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
174	GX-B1363/22-A-23041	2023/2/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
175	GX-B1363/22-A-23044	2023/2/22	所检项目合格	 <p>The photograph shows two individuals in white work uniforms with '中检公信' (Zhongjian Gongxin) printed on the back, working in an industrial setting. They are positioned in front of a large, grey metal piece of equipment with a prominent vertical pipe extending upwards. One of the equipment's doors is open, revealing internal components. To the left of the equipment is a green plastic trash bin. The scene is lit by natural light from a window on the right, which shows some outdoor foliage. A white date stamp '2023/02/15' is located in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
176	GX-B1363/22-A-23045	2023/2/22	所检项目合格	