







序号	报告编号	发布日期	结论	影像资料
174	GX-B1451/20-5-23043~23067	2023/2/16	本次共检高压开关柜25台，25台高压开关柜所检项目合格。	
175	GX-B1451/20-5-23068~23078	2023/2/16	本次共检高压开关柜11台，11台高压开关柜所检项目合格。	

176	GX-B1451/20-5-23092~23114	2023/2/16	<p>本次共检高压开关柜23台，23台高压开关柜所检项目合格。。</p>	
177	GX-B1319/21-5-23045~23072	2023/2/16	<p>本次共检高压交流断路器28台，28台高压交流断路器所检项目合格。</p>	
178	GX-B1319/21-5-23073~23083	2023/2/16	<p>本次共检高压交流断路器11台，11台高压交流断路器所检项目合格。</p>	

179	GX-B1319/21-5-23084~23096	2023/2/16	<p>本次共检高压交流断路器13台，13台高压交流断路器所检项目合格。</p>	
180	GX-B1319/21-5-23097~23119	2023/2/16	<p>本次共检高压交流断路器23台，23台高压交流断路器所检项目合格。</p>	

181	GX-B1322/21-5-23001~23005	2023/2/16	本次共检电力电缆5条，5条电力电缆所检项目合格。	
182	GX-B1322/21-5-23006~23025	2023/2/16	本次共检电力电缆20条，20条电力电缆所检项目合格。	
183	GX-B1322/21-5-23026~23030	2023/2/16	本次共检电力电缆5条，5条电力电缆所检项目合格。	


184	GX-B1321/20-5-23109~23119	2023. 2. 16	所检项目合格	
185	GX-B1321/20-5-23021~23032	2023. 2. 16	所检项目合格	
186	GX-B1321/20-5-23009~23020	2023. 2. 16	所检项目合格	
187	GX-B1321/20-5-23001~23008	2023. 2. 16	所检项目合格	

188	GX-B1321/20-5-23033~23046	2023. 2. 16	所检项目合格	
189	GX-B1321/20-5-23047~23057	2023. 2. 16	所检项目合格	
190	GX-B1321/20-5-23058~23065	2023. 2. 16	所检项目合格	
191	GX-B1321/20-5-23066~23079	2023. 2. 16	所检项目合格	


192	GX-B1321/20-5-23080~23090	2023. 2. 16	所检项目合格	
193	GX-B1321/20-5-23091~23096	2023. 2. 16	所检项目合格	
194	GX-B1321/20-5-23097~23108	2023. 2. 16	所检项目合格	

195	GX-B1321/20-5-23120~23128	2023. 2. 16	所检项目合格	
196	GX-B1323/21-5-23089~23090	2023. 2. 16	所检项目合格	
197	GX-B1416/22-5-23001	2023年2月16日	合格	

198	GX-B1416/22-5-23002	2023年2月16日	合格	
199	GX-B1383/21-5-23001	2023年2月16日	合格	
200	GX-B1499/21-5-23001	2023年2月16日	合格	
201	GX-B1499/21-5-23002	2023年2月16日	合格	


202	GX-B1499/21-5-23003	2023年2月16日	合格	 A photograph showing a close-up of electrical equipment, possibly a transformer or switchgear, with a person's hands visible near the components. The date "2023. 1. 10" is printed in the bottom right corner of the image.
203	GX-B1313-21-5-23001~23002	2023/2/17	本次共检电力变压器2台，2台电力变压器所检项目合格。	 A photograph of a worker wearing a blue jacket and a hard hat, standing in a narrow aisle next to a piece of electrical equipment. The worker is looking down at the equipment. The date "2023年1月15日" is printed in the bottom right corner of the image.

204	GX-B1313/21-5-23003~23004	2023/2/17	<p>本次共检电力变压器2台，2台所检项目合格。</p>	
205	GX-B1313/21-5-23005~23010	2023/2/17	<p>本次共检电力变压器6台，6台所检项目合格。</p>	

206	GX-B1313/21-5-23011~23018	2023/2/17	<p>本次共检电力变压器8台，8台所检项目合格。</p>	
207	GX-B1313/21-5-23030~23031	2023/2/17	<p>本次共检电力变压器2台，2台电力变压器所检项目合格。</p>	

208	GX-B1328/20-5-23011-23016	2023/2/17	合格	
209	GX-B1350/21-5-23016	2023. 2. 17	所检项目合格	
210	GX-B1495/20-5-23042~23057	2023. 2. 17	所检项目合格	

211	GX-B1495/20-5-23001~23019	2023. 2. 17	所检项目合格	
212	GX-B1495/20-5-23020~23041	2023. 2. 17	所检项目合格	
213	GX-B1495/20-5-23058~23083	2023. 2. 17	所检项目合格	

214	GX-B1495/20-5-23084~23103	2023. 2. 17	所检项目合格	
215	GX-B1495/20-5-23042~23057	2023. 2. 17	所检项目合格	
216	GX-B1495/20-5-23001~23019	2023. 2. 17	所检项目合格	

217	GX-B1495/20-5-23020~23041	2023. 2. 17	所检项目合格	
218	GX-B1495/20-5-23058~23083	2023. 2. 17	所检项目合格	
219	GX-B1495/20-5-23084~23103	2023. 2. 17	所检项目合格	

220	GX-B1495/20-5-23104~23125	2023. 2. 17	所检项目合格	
221	GX-B1495/20-5-23150~23165	2023. 2. 17	所检项目合格	
222	GX-B1495/20-5-23166~23181	2023. 2. 17	所检项目合格	

223	GX-B1495/20-5-23126~23149	2023. 2. 17	所检项目合格	
224	GX-B1495/20-5-23182~23212	2023. 2. 17	所检项目合格	