





序号	报告编号	发布日期	结论	影像资料
41	GX-B1520/20-2-23001	2023. 2. 14	综合判定：合格。	
42	GX-B1520/20-2-23002	2023. 2. 14	综合判定：合格。	
43	GX-B1520/20-2-23003	2023. 2. 14	综合判定：合格。	

44	GX-B1520/20-2-23004	2023. 2. 14	综合判定：合格。	
45	GX-B1520/20-2-23005	2023. 2. 14	综合判定：合格。	
46	GX-B1520/20-2-23006	2023. 2. 14	综合判定：合格。	

47	GX-B1323/21-23001~23003	2023/2/16	合格	
48	GX-B1323/21-23004~23007	2023/2/16	合格	
49	GX-B1328/20-2-23010	2023. 2. 16	<p>本次共检绝缘手套4只，4只所检项目合格。</p>	




50	GX-B1328/20-2-23011	2023. 2. 16	本次共检绝缘鞋 4只，4只所检项目 合格。			
51	GX-B1328/20-2-23005	2023. 2. 16	本次共检绝缘手套6 只，6只所检项目合 格。			
52	GX-B1328/20-2-23006	2023. 2. 16	本次共检绝缘鞋 5双，5双所检项目 合格。			

53	GX-B1328/20-2-23007	2023. 2. 16	本次共检验电器 3支，3支所检项目 合格	
54	GX-B1328/20-2-23008	2023. 2. 16	本次共检便携式接 地和接地短路装置2 组，2组所检项目合 格。	
55	GX-B1328/20-2-23009	2023. 2. 16	所检项目合格。	




56	GX-B1328/20-2-23012	2023. 2. 16	本次共检绝缘手套6只，6只所检项目合格。			
57	GX-B1328/20-2-23013	2023. 2. 16	本次共检绝缘鞋6只，6只所检项目合格。			
58	GX-B1328/20-2-23014	2023. 2. 16	本次共检验电器3只，3只所检项目合格。			

59	GX-B1328/20-2-23015	2023. 2. 16	所检项目合格。	
60	GX-B1328/20-2-23016	2023. 2. 16	所检项目合格。	
61	GX-B1328/20-2-23017	2023. 2. 16	所检项目合格	


62	GX-B1306/21-2-23009	2023. 2. 17	所检项目合格。		
63	GX-B1306/21-2-23010	2023. 2. 17	所检项目合格。		
64	GX-B1306/21-2-23011	2023. 2. 17	所检项目合格。		

65	GX-B1423/20-2-23010	2023. 2. 17	综合判定：合格		
66	GX-B1423/20-2-23011	2023. 2. 17	综合判定：合格		
67	GX-B1423/20-2-23012	2023. 2. 17	综合判定：合格		


68	GX-B1423/20-2-23013	2023. 2. 17	综合判定：合格	
69	GX-B1423/20-2-23014	2023. 2. 17	综合判定：合格	
70	GX-B1423/20-2-23015	2023. 2. 17	综合判定：合格	




71	GX-B1423/20-2-23016	2023. 2. 17	综合判定：合格	
72	GX-B1423/20-2-23017	2023. 2. 17	综合判定：合格	
73	GX-B1423/20-2-23018	2023. 2. 17	综合判定：合格	

74	GX-B1312/20-2-23017~23018	2023. 2. 20	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
75	GX-B1312/20-2-23039~23044	2023. 2. 20	本次共检电力变压器6台，6台电力变压器所检项目合格。 。	
76	GX-B1312/20-2-23019~23024	2023. 2. 20	本次共检电力变压器6台，6台电力变压器所检项目合格。 。	

77	GX-B1312/20-2-23025~23030	2023. 2. 20	本次共检电力变压器6台，6台电力变压器所检项目合格。 。		
78	GX-B1312/20-2-23031~23034	2023. 2. 20	本次共检电力变压器4台，4台电力变压器所检项目合格。 。		
79	GX-B1312/20-2-23035~23036	2023. 2. 20	本次共检电力变压器2台，2台电力变压器所检项目合格。 。		

80	GX-B1312/20-2-23037~23038	2023. 2. 20	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
81	GX-B1314/21-2-23001~23003	2023. 2. 20	本次共检干式电抗器3台，3台所检项目合格。	
82	GX-B1314/21-2-23004~23007	2023. 2. 20	本次共检干式电抗器4台，4台所检项目合格。	

83	GX-B1321/20-2-23001~23010	2023. 2. 20	本次共检电力电缆10条，10条电力电缆所检项目合格。	
84	GX-B1321/20-2-23011~23022	2023. 2. 20	本次共检电力电缆12条，12条电力电缆所检项目合格。	
85	GX-B1321/20-2-23023~23029	2023. 2. 20	本次共检电力电缆7条，7条电力电缆所检项目合格。	

86	GX-B1323/21-2-23008~23011	2023. 2. 20	本次共检三相交流电动机4台，4台所检项目合格。	
87	GX-B1495/20-2-23028~23031	2023. 2. 15	本次共检高压开关柜4台，4台所检项目合格。	
88	GX-B1495/20-2-23032~23037	2023. 2. 15	本次共检高压防爆开关4台，4台所检项目合格。	

89	GX-B1495/20-2-23038~23045	2023. 2. 15	本次共检高压防爆开关8台，8台所检项目合格。	
90	GX-B1495/20-2-23046~23049	2023. 2. 15	本次共检高压防爆开关4台，4台所检项目合格。	
91	GX-B1495/20-2-23050~23071	2023. 2. 15	本次共检高压开关柜22台，22台所检项目合格。	

92	GX-B1495/20-2-23072~23073	2023. 2. 15	本次共检高压开关柜2台，2台所检项目合格。	 <p>2023/02/09</p>	
93	GX-B1495/20-2-23091~23098	2023. 2. 15	本次共检高压防爆开关8台，8台所检项目合格。	 <p>2023/02/09</p>	
94	GX-B1495/20-2-23099~23101	2023. 2. 15	本次共检高压开关设备3台，3台所检项目合格。	 <p>2023/02/11</p>	

95	GX-B1495/20-2-23102~23113	2023. 2. 15	本次共检高压防爆开关12台，12台所检项目合格。	
96	GX-B1515/22-2-23004	2023. 2. 20	除上述问题外，其余所检项目合格。	
97	GX-B1416/22-2-23008	2023. 2. 21	综合判定：合格。	

98	GX-B1328/20-2-23018	2023. 2. 22	合格	 A photograph showing a room with white walls and a light-colored floor. In the center, there is a piece of electrical equipment on a stand. A person wearing a red hard hat and a dark jacket is standing near the equipment. To the right, there is a wooden chair. The date '2023/2/16' is visible in the bottom right corner of the photo.
99	GX-B1328/20-2-23019	2023. 2. 22	合格	 A photograph showing a room with white walls and a light-colored floor. A red safety net is set up in the foreground. In the background, there is a piece of electrical equipment on a stand. A person wearing a red hard hat and a dark jacket is standing near the equipment. To the right, there is a wooden chair. The date '2023/2/16' is visible in the bottom right corner of the photo.
100	GX-B1328/20-2-23020	2023. 2. 22	合格	 A photograph showing a room with white walls and a light-colored floor. In the center, there is a piece of electrical equipment on a stand. A person wearing a red hard hat and a dark jacket is standing near the equipment. To the left, there is a wooden chair. The date '2023/2/16' is visible in the bottom right corner of the photo.

101	GX-B1328/20-2-23021	2023. 2. 23	合格	
102	GX-B1328/20-2-23022	2023. 2. 23	合格	