


序号	报告编号	发布日期	结论	影像资料
58	GX-B1305/21-4-23001	2023. 3. 7	合格	
59	GX-B1305/21-4-23002	2023. 3. 7	合格	
60	GX-B1305/21-4-23004	2023. 3. 7	合格	

61	GX-B1598/21-4-23001	2023. 3. 7	损失百分比最大为	
62	GX-B1598/21-4-23002	2023. 3. 7	损失百分比最大为	
63	GX-B1598/21-4-23003	2023. 3. 7	<p>实测钢丝绳有效截面积损失百分比最大为3.11%，小于5%为正常。</p>	
64	GX-B1598/21-4-23004	2023. 3. 7	<p>实测钢丝绳有效截面积损失百分比最大为2.58%，小于5%为正常。</p>	

65	GX-B1598/21-4-23005	2023. 3. 7	实测钢丝绳有效截面积损失百分比最大为3.06%，小于5%为正常。			
66	GX-B1598/21-4-23006	2023. 3. 7	实测钢丝绳有效截面积损失百分比最大为4.39%，小于5%为正常。			
67	GX-B1598/21-4-23007	2023. 3. 7	实测钢丝绳有效截面积损失百分比最大为3.42%，小于5%为正常。			
68	GX-B1598/21-4-23008	2023. 3. 7	实测钢丝绳有效截面积损失百分比最大为4.64%，小于5%为正常。			

69	GX-B1598/21-4-23009	2023. 3. 7	实测钢丝绳有效截面积损失百分比最大为4.86%，小于5%为正常。	
70	GX-B1598/21-4-23010	2023. 3. 7	实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常。	
71	GX-B1598/21-4-23011	2023. 3. 7	实测钢丝绳有效截面积损失百分比最大为0.67%，小于5%为正常。	
72	GX-B1598/21-4-23012	2023. 3. 7	实测钢丝绳有效截面积损失百分比最大为0.78%，小于5%为正常。	

73	GX-B1495/20-4-23165~23166	2023. 3. 7	所检项目合格。 。	
74	GX-B1559/22-4-23012	2023. 3. 7	所检项目合格。 。	
75	GX-B1559/22-4-23013	2023. 3. 7	所检项目合格。 。	
76	GX-B1323/21-4-23019~23022	2023. 3. 7	所检项目合格。 。	

77	GX-B1495/20-4-23167~23169	2023. 3. 7	所检项目合格。 。	
78	GX-B1416/22-4-23002	2023. 3. 8	合格。	
79	GX-B1416/22-4-23003	2023. 3. 8	合格。	
80	GX-B1416/22-4-23004	2023. 3. 8	合格。	

81	GX-B1417/22-4-23028	2023. 3. 8	综合判定：合格。	 A white truck is parked on a construction site. Three workers wearing hard hats and work clothes are standing near the truck. A red date stamp '2023.2.2' is visible in the bottom right corner of the photo.
82	GX-B1417/22-4-23029	2023. 3. 8	综合判定：合格。	 A worker wearing a brown jacket and a red hard hat is operating a piece of machinery, possibly a generator or a pump, on a construction site. A red date stamp '2023.2.2' is visible in the bottom right corner of the photo.
83	GX-B1417/22-4-23030	2023. 3. 8	综合判定：合格。	 Two workers wearing hard hats and work clothes are standing in front of a white truck. One worker is wearing a blue jacket and the other is wearing a brown jacket. A red date stamp '2023.2.2' is visible in the bottom right corner of the photo.
84	GX-B1417/22-4-23031	2023. 3. 8	综合判定：合格。	 A worker wearing a brown jacket and a red hard hat is kneeling on the ground next to a piece of equipment, possibly a generator or a pump. Another worker is standing in the background. A red date stamp '2023.2.2' is visible in the bottom right corner of the photo.

85	GX-B1417/22-4-23032	2023. 3. 8	综合判定：合格。	
86	GX-B1417/22-4-23033	2023. 3. 8	综合判定：合格。	
87	GX-B1417/22-4-23034	2023. 3. 8	综合判定：合格。	
88	GX-B1417/22-4-23035	2023. 3. 8	综合判定：合格。	

89	GX-B1417/22-4-23036	2023. 3. 8	综合判定：合格。	
90	GX-B1417/22-4-23037	2023. 3. 8	综合判定：合格。	
91	GX-B1417/22-4-23039	2023. 3. 8	综合判定：合格。	
92	GX-B1417/22-4-23040	2023. 3. 8	综合判定：合格。	

93	GX-B1417/22-4-23041	2023. 3. 8	综合判定：合格。	
94	GX-B1417/22-4-23042	2023. 3. 8	综合判定：合格。	
95	GX-B1417/22-4-23043	2023. 3. 8	综合判定：合格。	
96	GX-B1417/22-4-23044	2023. 3. 8	综合判定：合格。	

97	GX-B1417/22-4-23045	2023. 3. 8	综合判定：合格。	
98	GX-B1417/22-4-23046	2023. 3. 8	综合判定：合格。	
99	GX-B1417/22-4-23047	2023. 3. 8	综合判定：合格。	
100	GX-B1417/22-4-23048	2023. 3. 8	综合判定：合格。	

