

序号	报告编号	发布日期	结论	影像资料
429	GX-B1312/20-Y-23036~23037	2023年3月26日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
430	GX-B1312/20-Y-23038~23039	2023年3月26日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
431	GX-B1312/20-Y-23040~23041	2023年3月26日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	

432	GX-B1312/20-Y-23042~23043	2023年3月26日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
433	GX-B1312/20-Y-23044~23045	2023年3月26日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
434	GX-B1312/20-Y-23046	2023年3月26日	所检项目合格。	

435	GX-B1312/20-Y-23047	2023年3月26日	所检项目合格。	
436	GX-B1312/20-Y-23048	2023年3月26日	所检项目合格。	
437	GX-B1312/20-Y-23049	2023年3月26日	所检项目合格。	

438	GX-B1312/20-Y-23050~23051	2023年3月26日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	 A worker in a red protective suit and helmet is working on electrical equipment. The worker is using a tool to inspect or adjust a component. The background shows a control room or a similar environment with various panels and equipment. The date 2023/2/19 is visible in the bottom right corner of the image.
439	GX-B1312/20-Y-23052~23054	2023年3月26日	本次共检电力变压器3台，3台电力变压器所检项目合格。 。	 A worker in a red protective suit and helmet is working on electrical equipment. The worker is using a tool to inspect or adjust a component. The background shows a control room or a similar environment with various panels and equipment. The date 2023/2/21 is visible in the bottom right corner of the image.
440	GX-B1312/20-Y-23055	2023年3月26日	所检项目合格。	 A worker in a red protective suit and helmet is working on electrical equipment. The worker is using a tool to inspect or adjust a component. The background shows a control room or a similar environment with various panels and equipment. The date 2023/2/21 is visible in the bottom right corner of the image.

441	GX-B1312/20-Y-23056	2023年3月26日	所检项目合格。	
442	GX-B1312/20-Y-23057	2023年3月26日	所检项目合格。	
443	GX-B1312/20-Y-23058~23061	2023年3月26日	本次共检电力变压器4台，4台电力变压器所检项目合格。 。	

444	GX-B1312/20-Y-23062	2023年3月26日	所检项目合格。	
445	GX-B1312/20-Y-23063	2023年3月26日	所检项目合格。	
446	GX-B1312/20-Y-23064~23065	2023年3月26日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	

447	GX-B1312/20-Y-23066~23067	2023年3月26日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
448	GX-B1321/20-Y-23008~23014	2023年3月24日	本次共检验电力电缆7条，7条电力电缆所检项目合格。	
449	GX-B1321/20-Y-23015~23023	2023年3月24日	本次共检验电力电缆9条，9条电力电缆所检项目合格。	

450	GX-B1321/20-Y-23024~23031	2023年3月24日	本次共检验电力电缆8条，8条电力电缆所检项目合格。	 A worker in a red protective suit and helmet is working on a cable in a dark environment. The worker is using a tool to inspect or work on the cable. The scene is illuminated by a bright light source, possibly a headlamp or a work light. The date 2023/2/19 is visible in the bottom right corner of the image.
451	GX-B1321/20-Y-23032~23042	2023年3月24日	本次共检验电力电缆11条，11条电力电缆所检项目合格。	 A worker in a red protective suit and helmet is working on a cable in a dark environment. The worker is using a tool to inspect or work on the cable. The scene is illuminated by a bright light source, possibly a headlamp or a work light. The date 2023/2/20 is visible in the bottom right corner of the image.
452	GX-B1321/20-Y-23043~23050	2023年3月24日	本次共检验电力电缆8条，8条电力电缆所检项目合格。	 A worker in a red protective suit and helmet is working on a cable in a dark environment. The worker is using a tool to inspect or work on the cable. The scene is illuminated by a bright light source, possibly a headlamp or a work light. The date 2023/2/21 is visible in the bottom right corner of the image.

453	GX-B1321/20-Y-23051~23056	2023年3月24日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	 2023/2/22
454	GX-B1321/20-Y-23057~23062	2023年3月24日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	 2023/2/22
455	GX-B1321/20-Y-23063~23066	2023年3月24日	本次共检单相电力电缆8条，8条所检项目合格。	 2023/2/22

456	GX-B1321/20-Y-23070~23071	2023年3月24日	本次共检验电力电缆2条，2条电力电缆所检项目合格。	
457	GX-B1359/21-Y-23011~23013	2023年3月27日	本次共检矿用隔爆型照明信号综合保护装置3台，3台所检项目合格。	
458	GX-B1359/21-Y-23014~23015	2023年3月27日	本次共检矿用隔爆型照明信号综合保护装置2台，2台所检项目合格。	

459	GX-B1359/21-Y-23016	2023年3月27日	所检项目合格。	
460	GX-B1359/21-Y-23017	2023年3月27日	所检项目合格。	
461	GX-B1359/21-Y-23018	2023年3月27日	所检项目合格。	

462	GX-B1359/21-Y-23019~23020	2023年3月27日	本次共检矿用隔爆型照明信号综合保护装置2台，2台所检项目合格。	
463	GX-B1359/21-Y-23021	2023年3月27日	所检项目合格。	
464	GX-B1359/21-Y-23022	2023年3月27日	所检项目合格。	

465	GX-B1359/21-Y-23023	2023年3月27日	所检项目合格。	
466	GX-B1359/21-Y-23024	2023年3月27日	所检项目合格。	
467	GX-B1359/21-Y-23025	2023年3月27日	所检项目合格。	

468	GX-B1359/21-Y-23026	2023年3月27日	所检项目合格。	
469	GX-B1359/21-Y-23027	2023年3月27日	所检项目合格。	
470	GX-B1359/21-Y-23028	2023年3月27日	所检项目合格。	

471	GX-B1359/21-Y-23029	2023年3月27日	所检项目合格。	
472	GX-B1359/21-Y-23030	2023年3月27日	所检项目合格。	
473	GX-B1359/21-Y-23031	2023年3月27日	所检项目合格。	

474	GX-B1359/21-Y-23032	2023年3月27日	所检项目合格。	
475	GX-B1359/21-Y-23033	2023年3月27日	所检项目合格。	
476	GX-B1359/21-Y-23034	2023年3月27日	所检项目合格。	

477	GX-B1423/20-Y-23696	2023年3月26日	综合判定：合格	
478	GX-B1423/20-Y-23697	2023年3月26日	综合判定：合格	
479	GX-B1423/20-Y-23698	2023年3月26日	综合判定：合格	

480	GX-B1423/20-Y-23699	2023年3月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety vests are standing near the front. The license plate is GX-B1423. A date stamp '2023/3/9' is visible in the bottom right corner.
481	GX-B1423/20-Y-23700	2023年3月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety vests are standing near the front. The license plate is GX-B1423. A date stamp '2023/3/9' is visible in the bottom right corner.
482	GX-B1423/20-Y-23701	2023年3月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety vests are standing near the front. The license plate is GX-B1423. A date stamp '2023/3/9' is visible in the bottom right corner.

483	GX-B1423/20-Y-23702	2023年3月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests are standing near the front of the truck. The truck has a license plate that reads 'GX1423'. A date stamp '2023/3/9' is visible in the bottom right corner of the photo.
484	GX-B1423/20-Y-23703	2023年3月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests are standing near the front of the truck. The truck has a license plate that reads 'GX1423'. A date stamp '2023/3/9' is visible in the bottom right corner of the photo.
485	GX-B1423/20-Y-23704	2023年3月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests are standing near the front of the truck. The truck has a license plate that reads 'GX1423'. A date stamp '2023/3/9' is visible in the bottom right corner of the photo.

486	GX-B1423/20-Y-23705	2023年3月26日	综合判定：合格	 A yellow dump truck with identification number 1206 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A laptop and other equipment are on the ground in front of the truck. The date 2023/3/9 is visible in the bottom right corner of the photo.
487	GX-B1423/20-Y-23706	2023年3月26日	综合判定：合格	 A yellow dump truck with identification number 1276 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A laptop and other equipment are on the ground in front of the truck. The date 2023/3/9 is visible in the bottom right corner of the photo.
488	GX-B1423/20-Y-23707	2023年3月26日	综合判定：合格	 A yellow dump truck with identification number 1282 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A laptop and other equipment are on the ground in front of the truck. The date 2023/3/9 is visible in the bottom right corner of the photo.

489	GX-B1423/20-Y-23708	2023年3月26日	综合判定：合格	 A yellow dump truck with license plate GX-B1423/20-Y-23708 is parked on a dirt surface. The truck has the number '1286' on its side. Two people are standing near the front, and a small device is on the ground. A date stamp '2023/3/9' is in the bottom right.
490	GX-B1423/20-Y-23709	2023年3月26日	综合判定：合格	 A yellow dump truck with license plate GX-B1423/20-Y-23709 is parked on a dirt surface. The truck has the number '1277' on its side. Two people are standing near the front, and a small device is on the ground. A date stamp '2023/3/9' is in the bottom right.
491	GX-B1423/20-Y-23710	2023年3月26日	综合判定：合格	 A yellow dump truck with license plate GX-B1423/20-Y-23710 is parked on a dirt surface. The truck has the number '1280' on its side. Two people are standing near the front, and a small device is on the ground. A date stamp '2023/3/9' is in the bottom right.

492	GX-B1423/20-Y-23711	2023年3月26日	综合判定：合格	 <p>A yellow XGMA truck with license plate GX-B1423 is shown in a desert environment. The truck has the numbers 1, 2, 8, and 3 on its side. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/3/9' is visible in the bottom right corner of the image.</p>
493	GX-B1423/20-Y-23712	2023年3月26日	综合判定：合格	 <p>A yellow XGMA truck with license plate GX-B1423 is shown in a desert environment. The truck has the numbers 1, 2, 7, and 9 on its side. Two workers in safety gear are standing near the front of the truck. A date stamp '2023/3/9' is visible in the bottom right corner of the image.</p>

494	GX-B1423/20-Y-23713	2023年3月26日	综合判定：合格	
495	GX-B1423/20-Y-23714	2023年3月26日	综合判定：合格	

496	GX-B1423/20-Y-23715	2023年3月26日	综合判定：合格	 A yellow dump truck with license plate Y1205 is parked on a dirt surface. Two workers in safety gear stand near the front. A date stamp '2023/3/9' is visible in the bottom right corner of the photo.
497	GX-B1423/20-Y-23716	2023年3月26日	综合判定：合格	 A yellow dump truck with license plate Y175 is parked on a dirt surface. Two workers in safety gear stand near the front. A date stamp '2023/3/9' is visible in the bottom right corner of the photo.

498	GX-B1423/20-Y-23717	2023年3月26日	综合判定：合格	
499	GX-B1423/20-Y-23718	2023年3月26日	综合判定：合格	

500	GX-B1423/20-Y-23719	2023年3月26日	综合判定：合格	
-----	---------------------	------------	---------	---