



序号	报告编号	发布日期	结论	影像资料
268	GX-B1312/20-3-23102~23104	2023. 3. 30	所检项目合格	 <p>A photograph showing a worker wearing a red hard hat and safety gear, performing an inspection on a transformer. The transformer is mounted on a structure, and the background shows trees and a building. A red timestamp '2023.3.13' is visible in the bottom right corner of the image.</p>
269	GX-B1312/20-3-23105~23106	2023. 3. 30	所检项目合格	 <p>A photograph showing a worker in a grey uniform and safety gear, inspecting a transformer. The transformer is located in an indoor setting, possibly a control room or a specialized area, with red railings in the foreground. A yellow timestamp '2023.3.13' is visible in the bottom right corner of the image.</p>

270	GX-B1312/20-3-23107~23117	2023. 3. 30	所检项目合格	
271	GX-B1312/20-3-23118~23119	2023. 3. 30	所检项目合格	

272	GX-B1312/20-3-23120~23137	2023. 3. 30	所检项目合格	 <p>2023.3.16</p>
273	GX-B1312/20-3-23138	2023. 3. 30	所检项目合格	 <p>2023.3.17</p>

274	GX-B1312/20-3-23139~23141	2023. 3. 30	所检项目合格	 A photograph showing a worker in a red hard hat and a white work jacket with a logo on the back. The worker is wearing yellow gloves and is focused on a piece of electrical equipment, possibly a transformer or a switchgear, which has a gauge and some wiring. The date '2023.3.18' is visible in the bottom right corner of the photo.
275	GX-B1312/20-3-23142~23143	2023. 3. 30	所检项目合格	 A photograph showing a worker on a high-voltage electrical structure, likely a substation. The worker is wearing a red hard hat and a white jacket. The structure consists of metal beams, insulators, and other electrical components. The date '2023.3.22' is visible in the bottom right corner of the photo.

276	GX-B1321/20-3-23481~23492	2023. 3. 30	所检项目合格	
277	GX-B1321/20-3-23493~23502	2023. 3. 30	所检项目合格	

278	GX-B1321/20-3-23503~23516	2023. 3. 30	所检项目合格	
279	GX-B1321/20-3-23517~23529	2023. 3. 30	所检项目合格	

280	GX-B1321/20-3-23530~23534	2023. 3. 30	所检项目合格	
281	GX-B1321/20-3-23535~23545	2023. 3. 30	所检项目合格	

282	GX-B1321/20-3-23546~23555	2023. 3. 30	所检项目合格	
283	GX-B1321/20-3-23556~23565	2023. 3. 30	所检项目合格	

284	GX-B1321/20-3-23566~23573	2023. 3. 30	所检项目合格	
285	GX-B1312/20-3-23182~23186	2023年3月31日	本次共检电力变压器5台，5台电力变压器所检项目合格。	
286	GX-B1312/20-3-23246~23249	2023年3月31日	本次共检电力变压器4台，4台电力变压器所检项目合格。	

287	GX-B1321/20-3-23653~23660	2023年3月31日	本次共检电力电缆8条，8条电力电缆所检项目合格。	
288	GX-B1321/20-3-23661~23672	2023年3月31日	本次共检电力电缆12条，12条电力电缆所检项目合格。	
289	GX-B1321/20-3-23673~23685	2023年3月31日	本次共检电力电缆13条，13条电力电缆所检项目合格。	

290	GX-B1321/20-3-23741~23751	2023年3月31日	本次共检电力电缆11条，11条电力电缆所检项目合格。	
291	GX-B1495/20-3-231701~231708	2023年3月30日	本次共检电压互感器8组，8组电压互感器所检项目合格。	
292	GX-B1495/20-3-231246~231273	2023年3月30日	本次共检电压互感器28组，28组电压互感器所检项目合格。	
293	GX-B1495/20-3-231274~231296	2023年3月30日	本次共检电压互感器23组，23组电压互感器所检项目合格。	

294	GX-B1495/20-3-231031~231071	2023年3月30日	本次共检电流互感器41只，41只电流互感器所检项目合格。	
295	GX-B1495/20-3-231072~231092	2023年3月30日	本次共检电流互感器21只，21只电流互感器所检项目合格。	
296	GX-B1495/20-3-231093~231130	2023年3月30日	本次共检电流互感器38只，38只电流互感器所检项目合格。	
297	GX-B1495/20-3-231131~231199	2023年3月30日	本次共检电流互感器69只，69只电流互感器所检项目合格。	

298	GX-B1495/20-3-231200~231245	2023年3月30日	本次共检电流互感器46只，46只电流互感器所检项目合格。	
299	GX-B1451/20-3-23065~23067	2023年3月30日	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	
300	GX-B1495/20-3-231456~231465	2023年3月30日	本次共检电压互感器10组，10组电压互感器所检项目合格。	
301	GX-B1495/20-3-231352~231375	2023年3月30日	本次共检电流互感器24只，24只电流互感器所检项目合格。	

302	GX-B1495/20-3-231408~231423	2023年3月30日	本次共检电流互感器16只，16只电流互感器所检项目合格。	
303	GX-B1495/20-3-231376~231407	2023年3月30日	本次共检电流互感器32只，32只电流互感器所检项目合格。	
304	GX-B1495/20-3-231424~231455	2023年3月30日	本次共检电流互感器32只，32只电流互感器所检项目合格。	
305	GX-B1495/20-3-231301~231334	2023年3月30日	本次共检电流互感器34只，34只电流互感器所检项目合格。	

306	GX-B1495/20-3-231335~231351	2023年3月30日	本次共检电流互感器17只，17只电流互感器所检项目合格。	
307	GX-B1495/20-3-23981~23984	2023年3月31日	本次共检电压互感器4组，4组电压互感器所检项目合格。	
308	GX-B149520-3-23985~231000	2023年3月31日	本次共检电压互感器16组，16组电压互感器所检项目合格。	

309	GX-B149520-3-231001~231013	2023年3月31日	本次共检电压互感器13组，13组电压互感器所检项目合格。	
310	GX-B149520-3-231014~231024	2023年3月31日	本次共检电压互感器11组，11组电压互感器所检项目合格。	
311	GX-B149520-3-23881~23899	2023年3月31日	本次共检电流互感器19只，19只电流互感器所检项目合格。	

312	GX-B149520-3-23900~23931	2023年3月31日	本次共检电流互感器32只，32只电流互感器所检项目合格。	
313	GX-B149520-3-23932~23957	2023年3月31日	本次共检电流互感器26只，26只电流互感器所检项目合格。	
314	GX-B149520-3-23958~23979	2023年3月31日	本次共检电流互感器22只，22只电流互感器所检项目合格。	