

序号	报告编号	发布日期	结论	影像资料
39	GX-B1600/21-F-23003	2023. 3. 29	为可不注水煤层	
40	GX-B1600/21-F-23004	2023. 3. 29	为可不注水煤层	
41	GX-B1377/22-F-23051	2023. 3. 31	所检项目合格	

42	GX-B1377/22-F-23052	2023. 3. 31	所检项目合格	
43	GX-B1377/22-F-23053	2023. 3. 31	所检项目合格	
44	GX-B1377/22-F-23054	2023. 3. 31	所检项目合格	

45	GX-B1377/22-F-23055	2023. 3. 31	所检项目合格	 A photograph showing two individuals in white lab coats and blue face masks working in a laboratory. They are positioned at a bench with a microscope. The person on the left is adjusting the microscope, while the person on the right looks on. A date stamp '2023/3/20' is visible in the bottom right corner of the image.
46	GX-B1377/22-F-23056	2023. 3. 31	所检项目合格	 A photograph showing two individuals in white lab coats and blue face masks working in a laboratory. They are positioned at a bench with a microscope. The person on the left is adjusting the microscope, while the person on the right looks on. A date stamp '2023/3/20' is visible in the bottom right corner of the image.
47	GX-B1377/22-F-23057	2023. 3. 31	所检项目合格	 A photograph showing two individuals in white lab coats and blue face masks working in a laboratory. They are positioned at a bench with a computer monitor and other equipment. The person on the left is pointing at the monitor, while the person on the right looks on. A date stamp '2023/3/21' is visible in the bottom right corner of the image.

48	GX-B1377/22-F-23058	2023. 3. 31	所检项目合格	 A photograph showing two technicians in a laboratory. The technician on the right is wearing a grey lab coat and a blue face mask, and is operating a piece of equipment with a red display. The technician on the left is also wearing a grey lab coat and a blue face mask, and is looking at the equipment. The date '2023/3/21' is visible in the bottom right corner of the image.
49	GX-B1377/22-F-23059	2023. 3. 31	所检项目合格	 A photograph showing two technicians in a laboratory. The technician on the right is wearing a grey lab coat and a blue face mask, and is operating a piece of equipment with a monitor. The technician on the left is also wearing a grey lab coat and a blue face mask, and is looking at the equipment. The date '2023/3/21' is visible in the bottom right corner of the image.
50	GX-B1377/22-F-23060	2023. 3. 31	所检项目合格	 A photograph showing two technicians in a laboratory. The technician on the right is wearing a grey lab coat and a blue face mask, and is operating a piece of equipment with a monitor. The technician on the left is also wearing a grey lab coat and a blue face mask, and is looking at the equipment. The date '2023/3/21' is visible in the bottom right corner of the image.