

序号	报告编号	发布日期	结论	影像资料
1	GX-B1416/22-2-23011	2023. 4. 3	综合判定：合格	
2	GX-B1416/22-2-23012	2023. 4. 3	综合判定：合格	

3	GX-B1495/20-2-23114~23127	2023. 4. 4	本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。	
4	GX-B1495/20-2-23128~23141	2023. 4. 6	本次共检高压开关设备14台，14台高压开关设备所检项目合格。	
5	GX-B1495/20-2-23142~23156	2023. 4. 6	本次共检高压防爆开关15台，15台高压防爆开关所检项目合格。	


6	GX-B1495/20-2-23157~23166	2023. 4. 6	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	
7	GX-B1423/20-2-23018	2023. 4. 7	综合判定：合格	
8	GX-B1423/20-2-23019	2023. 4. 7	综合判定：合格	

9	GX-B1423/20-2-23020	2023. 4. 7	综合判定：合格	 <p>2023/03/15</p>
10	GX-B1423/20-2-23021	2023. 4. 7	综合判定：合格	 <p>2023/03/15</p>
11	GX-B1309/21-2-23003	2023. 4. 7	所检项目合格	 <p>2023/03/15</p>

12	GX-B1500/21-2-23008	2023. 4. 7	综合判定：合格		
13	GX-B1500/21-2-23009	2023. 4. 7	综合判定：合格		
14	GX-B1500/21-2-23010	2023. 4. 7	综合判定：合格		

15	GX-B1309/21-2-23004	2023. 4. 7	所检项目合格	 <p>2023/03/15</p>	
16	GX-B1500/21-2-23011	2023. 4. 7	综合判定：合格	 <p>2023/03/15</p>	
17	GX-B1500/21-2-23012	2023. 4. 7	综合判定：合格	 <p>2023/03/15</p>	

18	GX-B1500/21-2-23013		综合判定：合格		
19	GX-B1534/20-2-23006	2023. 4. 7	所检项目合格		
20	GX-B1534/20-2-23007	2023. 4. 7	所检项目合格		

21	GX-B1308/21-2-23004	2023. 4. 7	所检项目合格	 <p>2023/3/13</p>	
22	GX-B1499/21-2-23016	2023. 4. 7	除吨水百米电耗不符合标准要求外，其余所检项目合格。	 <p>2023/3/13</p>	
23	GX-B1499/21-2-23017	2023. 4. 7	除吨水百米电耗不符合标准要求外，其余所检项目合格。	 <p>2023/3/13</p>	

24	GX-B1499/21-2-23018	2023. 4. 7	除吨水百米电耗不符合标准要求外，其余所检项目合格。	
25	GX-B1306/21-2-23017	2023. 4. 7	除容积流量和比功率不符合规定要求外，其余所检项目合格。	
26	GX-B1306/21-2-23018	2023. 4. 7	除容积流量和比功率不符合规定要求外，其余所检项目合格。	

27	GX-B1416/22-2-23009	2023. 4. 7	综合判定：合格	
28	GX-B1309/21-2-23002	2023. 4. 7	所检项目合格	
29	GX-B1500/21-2-23005	2023. 4. 7	综合判定：合格	

30	GX-B1500/21-2-23006	2023. 4. 7	综合判定：合格	
31	GX-B1500/21-2-23007	2023. 4. 7	综合判定：合格	
32	GX-B1307/20-2-23006	2023. 4. 5	综合判定：合格。	

33	GX-B1307/20-2-23007	2023. 4. 5	综合判定：合格。	 A photograph showing two workers wearing red hard hats and work clothes. They are standing in an industrial setting next to a large blue machine. One worker is kneeling and looking at something on the floor, while the other stands nearby. A date stamp '2023/03/25' is visible in the bottom right corner of the photo.
34	GX-B1307/20-2-23008	2023. 4. 5	综合判定：合格。	 A photograph showing two workers wearing red hard hats and work clothes. They are standing in an industrial setting next to a large blue machine. One worker is pointing at the machine, while the other stands nearby. A date stamp '2023/03/25' is visible in the bottom right corner of the photo.
35	GX-B1307/20-2-23009	2023. 4. 5	综合判定：合格。	 A photograph showing a worker wearing a red hard hat and work clothes. The worker is standing in an industrial setting next to a blue machine, looking at something on the floor. A date stamp '2023.03.17' is visible in the bottom right corner of the photo.

36	GX-B1307/20-2-23010	2023. 4. 5	综合判定：合格。	
37	GX-B1307/20-2-23011	2023. 4. 5	综合判定：合格。	
38	GX-B1307/20-2-23012	2023. 4. 5	综合判定：合格。	