




序号	报告编号	发布日期	结论	影像资料
618	GX-B1521/20-Y-23168	2023年4月7日	依据GB/T 9139-2018《土方机械 液压挖掘机 技术条件》GB/T7586-2018《土方机械 液压挖掘机 试验方法》，所检项目合格。	
619	GX-B1423/20-Y-232284	2023年4月7日	综合判定：合格	

620	GX-B1423/20-Y-232285	2023年4月7日	综合判定：合格	
621	GX-B1423/20-Y-232286	2023年4月7日	综合判定：合格	
622	GX-B1423/20-Y-232287	2023年4月7日	综合判定：合格	

623	GX-B1539/22-Y-23047	2023年4月7日	所检项目合格。	
624	GX-B1321/20-Y-23289~23293	2023年4月7日	本次共检验电力电缆5条，5条电力电缆所检项目合格。	
625	GX-B1321/20-Y-23294~23295	2023年4月7日	本次共检验电力电缆2条，2条电力电缆所检项目合格。	

626	GX-B1321/20-Y-23296~23298	2023年4月7日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	
627	GX-B1321/20-Y-23299	2023年4月7日	所检项目合格。	
628	GX-B1313/21-Y-23006	2023年4月7日	所检项目合格。	

629	GX-B1359/21-Y-23035~23041	2023年4月7日	本次共检矿用隔爆型照明信号综合保护装置7台，7台所检项目合格。	 A worker in a red uniform and helmet is working on a green electrical cabinet. The cabinet has a label that reads '1501-04'. The worker is using a tool to work on the internal components. A timestamp '2023/3/10' is visible in the bottom right corner of the image.
630	GX-B1359/21-Y-23042~23048	2023年4月7日	本次共检矿用隔爆型照明信号综合保护装置7台，7台所检项目合格。	 A worker in a red uniform and helmet is working on a green electrical cabinet. The worker is using a tool to work on the internal components. A timestamp '2023/3/12' is visible in the bottom right corner of the image.
631	GX-B1359/21-Y-23049~23054	2023年4月7日	本次共检矿用隔爆型照明信号综合保护装置6台，6台所检项目合格。	 A worker in a red uniform and helmet is working on a green electrical cabinet. The worker is using a tool to work on the internal components. A timestamp '2023/3/13' is visible in the bottom right corner of the image.

632	GX-B1359/21-Y-23055~23060	2023年4月7日	本次共检矿用隔爆型照明信号综合保护装置6台，6台所检项目合格。	
633	GX-B1359/21-Y-23061	2023年4月7日	所检项目合格。	
634	GX-B1423/20-Y-231895	2023年4月7日	综合判定：合格	

635	GX-B1423/20-Y-231896	2023年4月7日	综合判定：合格	
636	GX-B1423/20-Y-231897	2023年4月7日	综合判定：合格	

637	GX-B1423/20-Y-231898	2023年4月7日	综合判定：合格	
638	GX-B1559/22-Y-23005	2023年4月7日	所检项目合格。	



639	GX-B1559/22-Y-23006	2023年4月7日	所检项目合格。	
640	GX-B1559/22-Y-23007	2023年4月7日	所检项目合格。	

641	GX-B1417/22-Y-23036	2023年4月7日	综合判定：合格。	
642	GX-B1417/22-Y-23037	2023年4月7日	综合判定：合格。	

643

GX-B1417/22-Y-23038

2023年4月7日

综合判定：合格。

