



序号	报告编号	发布日期	结论	影像资料
39	GX-B1359/21-2-23030~23035	2023/4/10	所检项目合格	 A photograph showing an electrical control room or substation. Several large electrical cabinets are visible, and a person is standing in the center, possibly performing an inspection. The scene is dimly lit, with some lights on the cabinets. A timestamp "2023/03/06" is visible in the bottom right corner of the image.
40	GX-B1359/21-2-23027~23029	2023/4/10	所检项目合格	 A photograph showing a worker in a blue uniform and a hard hat using a laptop computer to inspect green electrical equipment. The worker is kneeling on the floor, and the laptop is open in front of them. The equipment is mounted on a wall. A timestamp "2023/03/05" is visible in the bottom right corner of the image.

41	GX-B1359/21-2-23023~23025	2023/4/10	所检项目合格	
42	GX-B1321/20-2-23086~23087	2023. 4. 4	本次共检电力电缆2条，2条电力电缆所检项目合格。	
43	GX-B1321/20-2-23088~23089	2023. 4. 4	本次共检电力电缆2条，2条电力电缆所检项目合格。	




44	GX-B1382/21-2-23001	2023. 4. 1	合格	
45	GX-B1382/21-2-23002	2023. 4. 1	合格	
46	GX-B1313/21-2-23042~23047	2023. 4. 1	本次共检电力变压器6台，6台所检项目合格。 。	




47	GX-B1313/21-2-23048~23053	2023. 4. 1	本次共检电力变压器6台，6台所检项目合格。 。	 A photograph showing three workers in blue uniforms and hard hats working on electrical equipment in a room. One worker is kneeling and using a laptop, while others stand nearby. A date stamp '2023/03/15' is visible in the bottom right corner.
48	GX-B1313/21-2-23054~23059	2023. 4. 1	本次共检电力变压器6台，6台所检项目合格。 。	 A photograph of a worker in a light blue uniform and red hard hat inspecting an outdoor transformer. The worker is holding a clipboard and looking towards the camera. A date stamp '2023/03/15' is visible in the bottom right corner.
49	GX-B1313/21-2-23060~23065	2023. 4. 1	本次共检电力变压器6台，6台所检项目合格。 。	 A photograph showing two workers in light blue uniforms and red hard hats inspecting a large outdoor transformer. One worker is standing and looking at the equipment, while the other is kneeling and using a laptop. A date stamp '2023/03/16' is visible in the bottom right corner.

50	GX-B1322/21-2-23016~23035	2023.4.4	本次共检验电力电缆20条，20条所检项目合格。	 2023/03/14
51	GX-B1322/21-2-23041~23051	2023.4.4	本次共检验电力电缆11条，11条所检项目合格。	 2023/03/15
52	GX-B1322/21-2-23052~23056	2023.4.4	本次共检验电力电缆5条，5条所检项目合格。	 2023/03/16

53	GX-B1322/21-2-23057~23058	2023. 4. 4	本次共检验电力电缆2条，2条所检项目合格。	 <p>2023/03/15</p>
54	GX-B1322/21-2-23059~23066	2023. 4. 4	本次共检验电力电缆8条，8条所检项目合格。	 <p>2023/03/16</p>
55	GX-B1313/21-2-23068~23077	2023. 4. 12	本次共检电力变压器10台，10台所检项目合格。	 <p>2023/04/08</p>

56	GX-B1451/20-2-23135~23144	2023. 4. 12	本次共检高压开关柜10台，10台所检项目合格。	
57	GX-B1322/21-2-23069~23072	2023. 4. 12	本次共检验电力电缆4条，4条所检项目合格。	
58	GX-B1416/22-2-23010	2023. 4. 12	综合判定：合格。	

59	GX-B1324/21-2-23001~23004	2023. 4. 12	本次共检验三相交流电动机4台，4台三相交流电动机所检项目合格。	
60	GX-B1300/20-2-23002	2023. 4. 12	综合判定：合格。	
61	GX-B1309/21-2-23006	2023. 4. 13	所检项目合格。	

62	GX-B1500/21-2-23023	2023. 4. 13	综合判定：合格。		
63	GX-B1500/21-2-23024	2023. 4. 13	综合判定：合格。		
64	GX-B1500/21-2-23025	2023. 4. 13	综合判定：合格。		

65	GX-B1500/21-2-23026	2023. 4. 13	综合判定：合格。	 2023/04/09	
66	GX-B1500/21-2-23027	2023. 4. 13	综合判定：合格。	 2023/04/09	
67	GX-B1500/21-2-23028	2023. 4. 13	综合判定：合格。	 2023/04/09	

68	GX-B1306/21-2-23019	2023. 4. 13	除上述问题外，其余所检项目合格。	
69	GX-B1306/21-2-23020	2023. 4. 13	除上述问题外，其余所检项目合格。	
70	GX-B1306/21-2-23021	2023. 4. 13	除上述问题外，其余所检项目合格。	

71	GX-B1300/20-2-23003	2023. 4. 12	综合判定：合格。	
----	---------------------	-------------	----------	---