


序号	报告编号	发布日期	结论	影像资料
28	GX-B1336/22-3-23041~23045	2023. 4. 7	本次共检母线5段， 5段所检项目合格。	
29	GX-B1336/22-3-23046~23052	2023. 4. 7	本次共检母线7段， 7段所检项目合格。	

30	GX-B1495/20-3-23785~23800	2023. 4. 7	本次共检电流互感器16只，16只电流互感器所检项目合格。	 A photograph showing two workers in a substation. One worker is wearing a red hard hat and a dark jacket, and is looking at a piece of equipment. The other worker is partially visible in the background. The equipment is red and blue. The date '2023.03.05' is visible in the bottom right corner of the photo.
31	GX-B1495/20-3-23863~23870	2023. 4. 7	本次共检电压互感器8组，8组电压互感器所检项目合格。 。	 A photograph showing two workers in a substation. One worker is wearing a red hard hat and a dark jacket, and is looking at a piece of equipment. The other worker is partially visible in the background. The equipment is red and blue. The date '2023.03.05' is visible in the bottom right corner of the photo.

32	GX-B1495/20-3-23801~23816	2023. 4. 7	本次共检电流互感器16只，16只电流互感器所检项目合格。	
33	GX-B1495/20-3-23871~23878	2023. 4. 7	本次共检电压互感器8组，8组电压互感器所检项目合格。	
34	GX-B1352/21-3-23105~23131	2023. 4. 7	本次共检矿用防爆低压交流真空馈电开关27台，27台矿用防爆低压交流真空馈电开关所检项目合格。	

35	GX-B1352/21-3-23132	2023. 4. 7	所检项目合格。	
36	GX-B1352/21-3-23133~23165	2023. 4. 7	本次共检矿用防爆低压交流真空馈电开关33台, 33台矿用防爆低压交流真空馈电开关所检项目合格。	
37	GX-B1352/21-3-23166~23173	2023. 4. 7	本次共检矿用防爆低压交流真空馈电开关8台, 8台矿用防爆低压交流真空馈电开关所检项目合格。	

38	GX-B1352/21-3-23174~23179	2023. 4. 7	<p>本次共检矿用防爆低压交流真空馈电开关6台,6台矿用防爆低压交流真空馈电开关所检项目合格。</p>	
39	GX-B1495/20-3-231786~231797	2023. 4. 7	<p>本次共检电压互感器12组, 12组电压互感器所检项目合格。</p>	
40	GX-B1495/20-3-231798~231801	2023. 4. 7	<p>本次共检电压互感器4组, 4组电压互感器所检项目合格。</p>	

41	GX-B1354/20-3-23004	2023. 4. 1	电网接地电容电流 符合规定。	
42	GX-B1354/20-3-23005	2023. 4. 1	电网接地电容电流 符合规定。	
43	GX-B1354/20-3-23006	2023. 4. 1	电网接地电容电流 符合规定。	

44	GX-B1354/20-3-23007	2023. 4. 1	电网接地电容电流 符合规定。	
45	GX-B1354/20-3-23008	2023. 4. 1	电网接地电容电流 符合规定。	
46	GX-B1548/20-3-23001	2023. 4. 10	所检项目合格	

47	GX-B1307/20-3-23003	2023. 4. 10	综合判定：合格	
48	GX-B1307/20-3-23004	2023. 4. 10	综合判定：合格	
49	GX-B1307/20-3-23005	2023. 4. 10	综合判定：合格	

50	GX-B1424/20-3-23001	2023年4月11日	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。	 A worker in an orange safety suit and helmet is inspecting the interior of a tunnel. The worker is holding a flashlight, and the tunnel walls are visible. A timestamp '2023.3.5' is visible in the bottom right corner of the image.
51	GX-B1427/21-3-23005	2023年4月11日	符合标准要求。	 A worker wearing a red helmet and a blue shirt is working on a piece of equipment. The worker is kneeling on the ground, and the equipment is a large, dark-colored box or container. A timestamp '2023.3.5' is visible in the bottom right corner of the image.
52	GX-B1428/21-3-23008	2023年4月11日	无缺陷迹痕显示。	 A worker in a blue safety suit and red helmet is inspecting the interior of a tunnel. The worker is holding a flashlight, and the tunnel walls are visible. A timestamp '2023.03.28' is visible in the bottom right corner of the image.

53	GX-B1428/21-3-23009	2023年4月11日	无缺陷迹痕显示。	
54	GX-B1310/21-3-23010	2023年4月11日	符合标准要求。	
55	GX-B1310/21-3-23011	2023年4月11日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

56	GX-B1310/21-3-23012	2023年4月11日	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
57	GX-B1324/21-3-23002~23007	2023. 4. 13	所检项目合格	
58	GX-B1324/21-3-23008~23013	2023. 4. 13	所检项目合格	

59	GX-B1324/21-3-23014~23019	2023. 4. 13	所检项目合格	
60	GX-B1310/21-3-23014	2023年4月11日	符合标准要求。	
61	GX-B1428/21-3-23010	2023年4月12日	无缺陷迹痕显示。	

62	GX-B1323/21-3-23132~23136	2023. 4. 14	本次共检三相交流电动机5台，5台三相交流电动机所检项目合格。	
63	GX-B1306/21-3-23001	2023. 4. 13	所检项目合格。	
64	GX-B1306/21-3-23002	2023. 4. 13	所检项目合格。	

65	GX-B1306/21-3-23003	2023. 4. 13	所检项目合格。	 A worker wearing a white jacket and a red helmet is working inside an open electrical cabinet. The worker is leaning over, and the interior of the cabinet is visible. A timestamp '2023.3.27' is visible in the bottom right corner of the photo.
66	GX-B1350/21-3-23004	2023. 4. 14	本次共检验接地装置3处，3处所检项目合格。	 A worker wearing a blue jacket and a red helmet is kneeling on the ground, using a testing device with red and black cables connected to a ground connection. A timestamp '2023.3.31' is visible in the bottom right corner of the photo.
67	GX-B1350/21-3-23003	2023. 4. 13	本次共检接地装置10处，10处接地装置所检项目合格。	 A worker wearing a red jacket with reflective stripes and a red helmet is kneeling on the ground at night, testing a ground connection. The worker is holding a testing device with red and black cables. A timestamp '2023.4.8' is visible in the bottom right corner of the photo.