










序号	报告编号	发布日期	结论	影像资料
130	GX-B1522/20-6-23001	2023/4/10	所检项目合格	
131	GX-B1522/20-6-23002	2023/4/10	所检项目合格	
132	GX-B1416/22-6-23001	2023/4/10	综合判定：合格	




133	GX-B1416/22-6-23002	2023/4/10	综合判定：合格	 <p>2023 02 22</p>
134	GX-B1416/22-6-23003	2023/4/10	综合判定：合格	 <p>2023 02 22</p>
135	GX-B1423/20-6-23254	2023/4/11	综合判定：合格	 <p>2023 4 11</p>

136	GX-B1423/20-6-23255	2023/4/11	综合判定：合格	
137	GX-B1423/20-6-23256	2023/4/11	综合判定：合格	
138	GX-B1423/20-6-23257	2023/4/11	综合判定：合格	

139	GX-B1423/20-6-23258	2023/4/11	综合判定：合格			
140	GX-B1423/20-6-23259	2023/4/11	综合判定：合格			
141	GX-B1423/20-6-23260	2023/4/11	综合判定：合格			

142	GX-B1423/20-6-23261	2023/4/11	综合判定：合格	
143	GX-B1423/20-6-23262	2023/4/11	综合判定：合格	
144	GX-B1423/20-6-23263	2023/4/11	综合判定：合格	

145	GX-B1423/20-6-23264	2023/4/11	综合判定：合格		
146	GX-B1423/20-6-23265	2023/4/11	综合判定：合格		
147	GX-B1423/20-6-23266	2023/4/11	综合判定：合格		

148	GX-B1423/20-6-23267	2023/4/11	综合判定：合格		
149	GX-B1423/20-6-23268	2023/4/11	综合判定：合格		
150	GX-B1423/20-6-23269	2023/4/11	综合判定：合格		

151	GX-B1423/20-6-23270	2023/4/11	综合判定：合格	
152	GX-B1423/20-6-23271	2023/4/11	综合判定：合格	
153	GX-B1423/20-6-23272	2023/4/11	综合判定：合格	



154	GX-B1423/20-6-23273	2023/4/11	综合判定：合格	
155	GX-B1313/21-6-23011~23012	2023/4/11	<p>本次共 检电力变压器 2台，2台电力变 压器所检项目合 格。</p>	
156	GX-B1423/20-6-23146	2023/4/12	综合判定：合格	

157	GX-B1423/20-6-23147	2023/4/12	综合判定：合格	 A red truck with a yellow license plate is parked on a dirt road. Two workers in blue uniforms and red hard hats stand in front of the truck. The date '2023 03 14' is visible in the bottom right corner of the photo.
158	GX-B1423/20-6-23148	2023/4/12	综合判定：合格	 A green truck with a yellow license plate is parked on a dirt road. Two workers in blue uniforms and red hard hats stand in front of the truck. The date '2023 03 14' is visible in the bottom right corner of the photo.
159	GX-B1423/20-6-23149	2023/4/12	综合判定：合格	 A green truck with a yellow license plate is parked on a dirt road. Three workers are standing in front of the truck. The date '2023 03 14' is visible in the bottom right corner of the photo.

160	GX-B1423/20-6-23150	2023/4/12	综合判定：合格	
161	GX-B1423/20-6-23151	2023/4/12	综合判定：合格	
162	GX-B1423/20-6-23152	2023/4/12	综合判定：合格	

163	GX-B1423/20-6-23153	2023/4/12	综合判定：合格	
164	GX-B1423/20-6-23154	2023/4/12	综合判定：合格	
165	GX-B1423/20-6-23155	2023/4/12	综合判定：合格	

166	GX-B1310/21-6-23035	2023/4/12	符合标准要求	
167	GX-B1310/21-6-23036	2023/4/12	符合标准要求	
168	GX-B1310/21-6-23037	2023/4/12	符合标准要求	

169	GX-B1427/21-6-23026	2023/4/12	符合标准要求	 A worker wearing a red hard hat and a blue safety vest is operating a vertical industrial machine. The machine has a red vertical column and various mechanical components. The worker is positioned to the left of the machine, and the background shows an industrial setting with metal structures.
170	GX-B1427/21-6-23027	2023/4/12	符合标准要求	 A worker wearing a red hard hat and a blue safety vest is working on a complex industrial structure. The worker is crouching and appears to be adjusting or inspecting a component. The structure consists of various metal beams and pipes. The background shows an industrial environment.
171	GX-B1427/21-6-23028	2023/4/12	符合标准要求	 A worker wearing a red hard hat and a blue safety vest is operating a vertical industrial machine. The worker is standing on a platform and looking at the machine. The machine has a red vertical column and various mechanical components. The background shows an industrial setting with metal structures.