


序号	报告编号	发布日期	结论	影像资料
202	GX-B1423/20-Y-221647	2022年5月7日	合格	

203	GX-B1423/20-Y-221648	2022年5月7日	合格	
-----	----------------------	-----------	----	---


204	GX-B1423/20-Y-221649	2022年5月7日	合格	
-----	----------------------	-----------	----	---

205 GX-B1423/20-Y-221650

2022年5月7日

合格



206	GX-B1423/20-Y-221651	2022年5月7日	合格	
-----	----------------------	-----------	----	---

207	GX-B1423/20-Y-221652	2022年5月7日	合格	
-----	----------------------	-----------	----	---

208	GX-B1423/20-Y-221653	2022年5月7日	合格	 A photograph showing two individuals wearing safety gear (hard hats and face masks) standing in front of a yellow excavator. The excavator has a white sign with the number '2145' on its side. A yellow timestamp '2022-5-17' is visible in the bottom left corner of the photo.
-----	----------------------	-----------	----	---

209	GX-B1423/20-Y-221654	2022年5月7日	合格	
-----	----------------------	-----------	----	---



210	GX-B1423/20-Y-221655	2022年5月7日	合格	
-----	----------------------	-----------	----	---

211	GX-B1423/20-Y-221656	2022年5月7日	合格	
-----	----------------------	-----------	----	---

212	GX-B1423/20-Y-221657	2022年5月7日	合格	
-----	----------------------	-----------	----	---

213	GX-B1423/20-Y-221658	2022年5月7日	合格	 <p>A photograph showing a yellow dump truck with license plate H-2177BGL. Two workers are standing in front of the truck. One worker is wearing a yellow hard hat, a grey shirt, black pants, and a high-visibility vest. The other worker is wearing a red hard hat and a camouflage jacket. The date 2022年5月7日 is visible in the bottom left corner of the photo.</p>
-----	----------------------	-----------	----	---

214	GX-B1423/20-Y-221659	2022年5月7日	合格	 A photograph of a yellow Komatsu 930L dump truck. Two workers are standing in front of the truck on a dirt surface. The worker on the left is wearing a yellow hard hat and a high-visibility vest. The worker on the right is wearing a red hard hat and a camouflage jacket. The truck has '930L' and 'KOMATSU' visible on its side. A yellow date stamp '2022.5.7' is visible in the bottom left corner of the photo.
-----	----------------------	-----------	----	--

215	GX-B1423/20-Y-221660	2022年5月7日	合格	
-----	----------------------	-----------	----	---

216 GX-B1423/20-Y-221661

2022年5月7日

合格



217	GX-B1423/20-Y-221662	2022年5月7日	合格	
-----	----------------------	-----------	----	---



218	GX-B1423/20-Y-221663	2022年5月7日	合格	
-----	----------------------	-----------	----	---

219	GX-B1423/20-Y-221664	2022年5月7日	合格	
-----	----------------------	-----------	----	---

220	GX-B1423/20-Y-221665	2022年5月7日	合格	
-----	----------------------	-----------	----	---

221	GX-B1423/20-Y-221666	2022年5月7日	合格	
-----	----------------------	-----------	----	---

222	GX-B1423/20-Y-221667	2022年5月7日	合格	 <p>A photograph showing a yellow MTB5H dump truck. The truck has a license plate that reads 'H-2017043'. Two workers are standing in front of the truck; one is wearing a yellow hard hat and a dark jacket, and the other is wearing a red hard hat and a camouflage jacket. The truck is parked on a dirt surface. A yellow timestamp '2022.5.7 16' is visible in the bottom left corner of the photo.</p>
-----	----------------------	-----------	----	--

223	GX-B1423/20-Y-221668	2022年5月7日	合格	
-----	----------------------	-----------	----	---

224	GX-B1423/20-Y-221694	2022年5月7日	合格	
-----	----------------------	-----------	----	---

225	GX-B1423/20-Y-221695	2022年5月7日	合格	
-----	----------------------	-----------	----	---



226	GX-B1423/20-Y-221696	2022年5月7日	合格	
-----	----------------------	-----------	----	---

227	GX-B1423/20-Y-221697	2022年5月7日	合格	
-----	----------------------	-----------	----	---

228	GX-B1423/20-Y-221698	2022年5月7日	合格	
-----	----------------------	-----------	----	---

229	GX-B1423/20-Y-221699	2022年5月7日	合格	 A photograph showing two individuals standing in front of a yellow truck. The person on the left is wearing a yellow hard hat, a high-visibility vest, and dark clothing. The person on the right is wearing a red hard hat, a camouflage jacket, and a face mask. The truck has the number '50' and 'M-117235H' visible on its side. A vertical yellow timestamp '2022/5/7 10:13' is visible on the left side of the photo.
-----	----------------------	-----------	----	--

230	GX-B1423/20-Y-221700	2022年5月7日	合格	 A photograph showing a yellow dump truck parked on a dirt surface. Two workers are standing in front of the truck. One worker is wearing a red jacket and a yellow hard hat, while the other is wearing a camouflage jacket and a red hard hat. The truck has a large dump body and multiple axles. The sky is clear and blue. A yellow timestamp '2022/5/7 8:15:22' is visible in the bottom left corner of the photo.
-----	----------------------	-----------	----	---

231	GX-B1423/20-Y-221701	2022年5月7日	合格	
-----	----------------------	-----------	----	---

232	GX-B1423/20-Y-221702	2022年5月7日	合格	
-----	----------------------	-----------	----	---

233	GX-B1423/20-Y-221703	2022年5月7日	合格	
-----	----------------------	-----------	----	---



234	GX-B1423/20-Y-221705	2022年5月7日	合格	 A photograph showing two men standing in front of a large yellow truck. The man on the left is wearing a dark blue long-sleeved shirt, dark trousers, and a yellow hard hat. The man on the right is wearing a camouflage jacket, dark trousers, a red hard hat, and a white face mask. The truck is yellow with a license plate that reads 'H-12786H'. The background is a clear blue sky and a dirt ground.
-----	----------------------	-----------	----	---

235	GX-B1423/20-Y-221706	2022年5月7日	合格	
-----	----------------------	-----------	----	---

236	GX-B1423/20-Y-221707	2022年5月7日	合格	
-----	----------------------	-----------	----	---

237	GX-B1423/20-Y-221708	2022年5月7日	合格	
-----	----------------------	-----------	----	---

238	GX-B1423/20-Y-221709	2022年5月7日	合格	 A photograph showing two individuals in camouflage jackets and hard hats (one white, one red) standing in front of a large yellow truck. The truck has '4108' written on its side. The ground is gravelly. A yellow vertical stamp '2022.5.7 13' is visible in the bottom left corner of the photo.
-----	----------------------	-----------	----	---

239	GX-B1423/20-Y-221710	2022年5月7日	合格	
-----	----------------------	-----------	----	---

240	GX-B1423/20-Y-221711	2022年5月7日	合格	
-----	----------------------	-----------	----	---

241	GX-B1423/20-Y-221712	2022年5月7日	合格	
-----	----------------------	-----------	----	---



242	GX-B1423/20-Y-221713	2022年5月7日	合格	
-----	----------------------	-----------	----	---

243	GX-B1423/20-Y-221714	2022年5月7日	合格	 <p>A photograph showing two workers standing in front of a yellow MTB6H truck. The worker on the left is wearing a yellow hard hat and a high-visibility vest. The worker on the right is wearing a red hard hat and a camouflage jacket. The truck has a license plate that reads 'H-1340'. A yellow timestamp '2022/3/19' is visible in the bottom right corner of the photo.</p>
-----	----------------------	-----------	----	---

244	GX-B1423/20-Y-221715	2022年5月7日	合格	
-----	----------------------	-----------	----	---

245	GX-B1423/20-Y-221716	2022年5月7日	合格	 A photograph showing two workers standing in front of a yellow truck. The worker on the left is wearing a yellow hard hat, a high-visibility yellow vest over a dark jacket, and dark pants. The worker on the right is wearing a red hard hat, a blue face mask, and a camouflage jacket. The truck is yellow with a license plate that reads 'H-1027 BSH'. A yellow timestamp '2022/5/20' is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	---

246	GX-B1423/20-Y-221717	2022年5月7日	合格	 A photograph showing a worker in a red hard hat and safety gear operating a piece of machinery, likely a forklift or similar equipment. The worker is seated and looking towards the camera. The date '2022/3/20' is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	---

247	GX-B1423/20-Y-221718	2022年5月7日	合格	
-----	----------------------	-----------	----	---

248	GX-B1423/20-Y-221719	2022年5月7日	合格	
-----	----------------------	-----------	----	---

249	GX-B1423/20-Y-221720	2022年5月7日	合格	
-----	----------------------	-----------	----	---



250	GX-B1423/20-Y-221721	2022年5月7日	合格	 A photograph showing two workers in safety gear standing in front of a yellow truck. The worker on the left is wearing a yellow hard hat and a high-visibility vest. The worker on the right is wearing a red hard hat and a camouflage jacket. The truck has "MTB" and "A-1335" visible on its side. A date stamp "2022/3/20" is present in the bottom right corner of the photo.
-----	----------------------	-----------	----	--

251	GX-B1423/20-Y-221722	2022年5月7日	合格	
-----	----------------------	-----------	----	---

252	GX-B1423/20-Y-221723	2022年5月7日	合格	
-----	----------------------	-----------	----	---

253	GX-B1423/20-Y-221724	2022年5月7日	合格	 A photograph showing two individuals standing in front of a large yellow truck. The person on the left is wearing a yellow hard hat, a black long-sleeved shirt, and dark pants. The person on the right is wearing a red hard hat, a blue face mask, and a camouflage jacket. The truck has 'H-610' and 'H-120' markings on its side. A yellow date stamp '2022/5/20' is visible in the bottom left corner of the photo.
-----	----------------------	-----------	----	---

254	GX-B1423/20-Y-221725	2022年5月7日	合格	
-----	----------------------	-----------	----	---

255	GX-B1423/20-Y-221726	2022年5月7日	合格	
-----	----------------------	-----------	----	---

256	GX-B1423/20-Y-221727	2022年5月7日	合格	 A photograph showing two workers standing in front of a yellow truck. The worker on the left is wearing a red jacket, a yellow hard hat, and dark pants. The worker on the right is wearing a camouflage jacket, a red hard hat, and a blue face mask. The truck has 'H-61' and '61 12 61' written on it. A vertical yellow timestamp '2022/5/7 11:11' is visible in the bottom left corner of the photo.
-----	----------------------	-----------	----	---

257	GX-B1423/20-Y-221728	2022年5月7日	合格	
-----	----------------------	-----------	----	---



258	GX-B1423/20-Y-221729	2022年5月7日	合格	
-----	----------------------	-----------	----	---

259	GX-B1423/20-Y-221730	2022年5月7日	合格	
-----	----------------------	-----------	----	---

260	GX-B1423/20-Y-221731	2022年5月7日	合格	
-----	----------------------	-----------	----	---

261	GX-B1423/20-Y-221732	2022年5月7日	合格	 A photograph of a yellow truck, likely a heavy-duty vehicle, with the identification number 'H-1253' visible on its side. A person wearing a red hard hat and a camouflage jacket stands next to the truck. The background shows an outdoor area with other vehicles and a clear blue sky. A yellow timestamp '2022/3/24' is visible in the bottom right corner of the image.
-----	----------------------	-----------	----	---

262	GX-B1423/20-Y-221733	2022年5月7日	合格	
-----	----------------------	-----------	----	---

263	GX-B1423/20-Y-221734	2022年5月7日	合格	
-----	----------------------	-----------	----	---

264	GX-B1423/20-Y-221735	2022年5月7日	合格	
-----	----------------------	-----------	----	---

265	GX-B1423/20-Y-221736	2022年5月7日	合格	
-----	----------------------	-----------	----	---



266	GX-B1423/20-Y-221737	2022年5月7日	合格	
-----	----------------------	-----------	----	---

267	GX-B1423/20-Y-221738	2022年5月7日	合格	
-----	----------------------	-----------	----	---

268	GX-B1423/20-Y-221739	2022年5月7日	合格	 A photograph showing a worker in a red hard hat and khaki uniform operating a piece of machinery. The worker is seated on a platform, looking down at a control panel. A yellow timestamp '2022/3/22' is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	---

269	GX-B1423/20-Y-221740	2022年5月7日	合格	
-----	----------------------	-----------	----	---

270 GX-B1423/20-Y-221741

2022年5月7日

合格



271	GX-B1423/20-Y-221742	2022年5月7日	合格	
-----	----------------------	-----------	----	---

272	GX-B1423/20-Y-221743	2022年5月7日	合格	
-----	----------------------	-----------	----	---

273	GX-B1423/20-Y-221744	2022年5月7日	合格	
-----	----------------------	-----------	----	---



274	GX-B1423/20-Y-221745	2022年5月7日	合格	
-----	----------------------	-----------	----	---

275 GX-B1423/20-Y-221746

2022年5月7日

合



276	GX-B1423/20-Y-221747	2022年5月7日	合格	 A photograph showing two individuals standing in front of a large yellow XCMG truck. The person on the left is wearing a yellow hard hat, a high-visibility vest, and dark pants. The person on the right is wearing a red hard hat, a camouflage jacket, and dark pants. The truck has 'XCMG' and '2' visible on its side. A yellow timestamp '2022/5/7' is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	---

277	GX-B1423/20-Y-221748	2022年5月7日	合格	
-----	----------------------	-----------	----	---

278	GX-B1423/20-Y-221749	2022年5月7日	合格	
-----	----------------------	-----------	----	---

279	GX-B1423/20-Y-221750	2022年5月7日	合格	 A photograph of a yellow dump truck parked on a dirt lot. Several workers in safety gear are visible in the background. A yellow timestamp '2022/5/23' is visible in the bottom right corner of the image.
-----	----------------------	-----------	----	--

280	GX-B1423/20-Y-221751	2022年5月7日	合格	 A photograph showing two workers standing in front of a large yellow XCMG XG105 truck. The worker on the left is wearing a yellow hard hat and a high-visibility vest. The worker on the right is wearing a red hard hat, a camouflage jacket, and a face mask. The truck has 'XCMG XG105' and the number '1303' visible on its side. The background is a clear blue sky and a dirt ground.
-----	----------------------	-----------	----	---

281	GX-B1423/20-Y-221752	2022年5月7日	合格	
-----	----------------------	-----------	----	---



282	GX-B1423/20-Y-221753	2022年5月7日	合格	 A photograph showing a person wearing a red safety helmet and a grey uniform, seated in the operator's seat of a piece of machinery. The person is looking towards the right side of the frame. The machinery is light-colored with a black steering wheel and various controls. A yellow timestamp '2022/3/21' is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	---

283	GX-B1423/20-Y-221754	2022年5月7日	合格	
-----	----------------------	-----------	----	---

284	GX-B1423/20-Y-221755	2022年5月7日	合格	
-----	----------------------	-----------	----	---

285	GX-B1423/20-Y-221756	2022年5月7日	合格	 A photograph showing two individuals in safety gear standing in front of a yellow truck. The person on the left is wearing a yellow hard hat, a high-visibility yellow vest over a dark jacket, and a white face mask. The person on the right is wearing a red hard hat, a camouflage jacket, and a white face mask. The truck is yellow and has large tires. The background shows a building with windows. A vertical yellow timestamp '2022/3/24' is visible on the left side of the photo.
-----	----------------------	-----------	----	--

286	GX-B1423/20-Y-221757	2022年5月7日	合格	
-----	----------------------	-----------	----	---

287	GX-B1423/20-Y-221758	2022年5月7日	合格	
-----	----------------------	-----------	----	---

288	GX-B1423/20-Y-221759	2022年5月7日	合格	 A photograph of a yellow dump truck parked in a dusty, open field under a clear blue sky. A person wearing a red hard hat and a camouflage jacket is standing next to the truck, looking at something in their hands. The truck has a license plate that reads "桂B1423" and a blue sign on the side with Chinese characters. A yellow timestamp "2022/5/23" is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	---

289

GX-B1423/20-Y-221760

2022年5月7日

合格





290	GX-B1423/20-Y-221761	2022年5月7日	合格	 A photograph showing two men standing in front of a large yellow truck. The man on the left is wearing a yellow hard hat, a high-visibility yellow safety vest over a dark jacket, and blue jeans. The man on the right is wearing a red hard hat, a camouflage jacket, and a white face mask. The truck is yellow with some blue markings. A vertical yellow timestamp '2022/3/24' is visible in the bottom left corner of the photo.
-----	----------------------	-----------	----	--

291	GX-B1423/20-Y-221762	2022年5月7日	合格	
-----	----------------------	-----------	----	---

292	GX-B1423/20-Y-221763	2022年5月7日	合格	 A photograph of a yellow dump truck at a construction site. The truck is the central focus, shown from a front-three-quarter view. In the background, several workers wearing hard hats and safety vests are visible, along with other yellow trucks. The ground is dirt, and the sky is clear blue. A yellow timestamp '2022/3/24' is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	---

293	GX-B1423/20-Y-221764	2022年5月7日	合格	
-----	----------------------	-----------	----	---

294	GX-B1423/20-Y-221765	2022年5月7日	合格	
-----	----------------------	-----------	----	---



295	GX-B1423/20-Y-221766	2022年5月7日	合格	
-----	----------------------	-----------	----	---



296	GX-B1423/20-Y-221767	2022年5月7日	合格	 A photograph showing a yellow dump truck with the number '430' on its side. Two workers wearing hard hats (one yellow, one red) and safety gear are standing in front of the truck. The date '2022/5/24' is visible in the bottom left corner of the photo.
-----	----------------------	-----------	----	---

297	GX-B1423/20-Y-221768	2022年5月7日	合格	
-----	----------------------	-----------	----	---





298	GX-B1423/20-Y-221769	2022年5月7日	合格	 <p>A photograph showing a yellow MTB truck with two workers standing in front of it. The workers are wearing hard hats and safety gear. The truck has 'MTB' written on the top. A date stamp '2022/5/24' is visible in the bottom right corner of the photo.</p>
-----	----------------------	-----------	----	--

299	GX-B1423/20-Y-221770	2022年5月7日	合格	
300	GX-B1423/20-Y-221387	2022年5月8日	合格	

301	GX-B1423/20-Y-221388	2022年5月8日	合格	 A photograph showing a yellow TONLY M6505 truck. Two workers are standing in front of the truck. One worker on the left is wearing a red hard hat, a white face mask, and a camouflage jacket. The other worker on the right is wearing a yellow hard hat, a white face mask, and a high-visibility yellow safety vest over a dark jacket. The truck has 'M6505' written on its front. A yellow timestamp '2022/3/11' is visible in the bottom left corner of the photo.
302	GX-B1423/20-Y-221389	2022年5月8日	合格	 A photograph showing a yellow TONLY M6608 truck. Two workers are standing in front of the truck. One worker on the left is wearing a yellow hard hat, a white face mask, and a high-visibility yellow safety vest over a dark jacket. The other worker on the right is wearing a red hard hat, a white face mask, and a camouflage jacket. The truck has 'TONLY' and 'M6608' written on its side. A yellow timestamp '2022/3/11' is visible in the bottom right corner of the photo.

303	GX-B1423/20-Y-221390	2022年5月8日	合格	 A photograph of a yellow TONLY M6609 truck. Two workers wearing safety gear (hard hats and high-visibility vests) are standing in front of the truck. The truck has 'TONLY' and 'M6609' visible on its side. A date stamp '2022/3/11' is in the bottom right corner.
304	GX-B1423/20-Y-221391	2022年5月8日	合格	 A photograph of a yellow TONLY M6610 truck. A worker wearing a red hard hat and a camouflage jacket is standing next to the truck. The truck has 'TONLY' and 'M6610' visible on its side. A date stamp '2022/3/11' is in the bottom right corner.

305	GX-B1423/20-Y-221392	2022年5月8日	合格	
306	GX-B1423/20-Y-221393	2022年5月8日	合格	

307	GX-B1423/20-Y-221394	2022年5月8日	合格	
308	GX-B1423/20-Y-221395	2022年5月8日	合格	

309	GX-B1423/20-Y-221396	2022年5月8日	合格	 A photograph showing a yellow TONY truck with license plate M6613. Two workers wearing red hard hats and safety gear are standing in front of the truck. The truck has 'TONLY' written on the side and 'M6613' on the front. A yellow timestamp '2022/3/11' is visible in the bottom right corner of the photo.
310	GX-B1423/20-Y-221397	2022年5月8日	合格	 A close-up photograph of a worker wearing a camouflage uniform and a red hard hat, operating a piece of heavy machinery. The worker is wearing blue gloves and is focused on the task. A yellow timestamp '2022/3/11' is visible in the bottom left corner of the photo.

311	GX-B1423/20-Y-221398	2022年5月8日	合格	
312	GX-B1423/20-Y-221399	2022年5月8日	合格	




313	GX-B1423/20-Y-221400	2022年5月8日	合格	
314	GX-B1423/20-Y-221401	2022年5月8日	合格	



315	GX-B1423/20-Y-221375	2022年5月8日	合格	
316	GX-B1423/20-Y-221376	2022年5月8日	合格	

317	GX-B1423/20-Y-221377	2022年5月8日	合格	
318	GX-B1423/20-Y-221378	2022年5月8日	合格	

319	GX-B1423/20-Y-221379	2022年5月8日	合格	
320	GX-B1423/20-Y-221380	2022年5月8日	合格	

321	GX-B1423/20-Y-221381	2022年5月8日	合格	
322	GX-B1423/20-Y-221382	2022年5月8日	合格	

323	GX-B1423/20-Y-221383	2022年5月8日	合格	
324	GX-B1423/20-Y-221384	2022年5月8日	合格	

325	GX-B1423/20-Y-221385	2022年5月8日	合格	 A photograph showing two workers standing next to a yellow truck. The worker on the left is wearing a red hard hat, a blue face mask, and a camouflage jacket. The worker on the right is wearing a yellow hard hat and a high-visibility yellow vest over a dark shirt. The truck has 'M-1047' written on its side. A yellow timestamp '2022/3/10' is visible in the bottom right corner of the photo.
326	GX-B1423/20-Y-221386	2022年5月8日	合格	 A photograph showing two workers standing next to a yellow truck. The worker on the left is wearing a yellow hard hat and a high-visibility yellow vest over a dark shirt. The worker on the right is wearing a red hard hat, a blue face mask, and a camouflage jacket. The truck has 'M-105' and 'TONLY' written on its side. A yellow timestamp '2022/3/10' is visible in the bottom right corner of the photo.

327	GX-B1423/20-Y-221404	2022年5月8日	合格	
328	GX-B1423/20-Y-221405	2022年5月8日	合格	



329	GX-B1423/20-Y-221406	2022年5月8日	合格	
330	GX-B1423/20-Y-221407	2022年5月8日	合格	

331	GX-B1423/20-Y-221408	2022年5月8日	合格	 <p>A photograph of a yellow TONLY dump truck with license plate M-2351. Two workers in safety gear (one in a red suit and yellow helmet, the other in a camouflage jacket and red helmet) stand in front of the truck. The truck has '2' and '8' on its side. A yellow timestamp '2022/3/12' is visible in the bottom right corner of the photo.</p>
332	GX-B1423/20-Y-221409	2022年5月8日	合格	 <p>A photograph of a yellow TONLY dump truck with license plate M-2350. Two workers in safety gear (one in a dark jacket and yellow helmet, the other in a camouflage jacket and red helmet) stand in front of the truck. The truck has '3' and '5' on its side. A yellow timestamp '2022/3/12' is visible in the bottom right corner of the photo.</p>

333	GX-B1423/20-Y-221410	2022年5月8日	合格	
334	GX-B1423/20-Y-221411	2022年5月8日	合格	

335	GX-B1423/20-Y-221412	2022年5月8日	合格	
336	GX-B1423/20-Y-221413	2022年5月8日	合格	

337	GX-B1423/20-Y-221414	2022年5月8日	合格	
338	GX-B1423/20-Y-221415	2022年5月8日	合格	

339	GX-B1423/20-Y-221416	2022年5月8日	合格	 A photograph of a yellow truck at a construction site. A person in a red hard hat and camouflage jacket is standing next to the truck, inspecting it. The truck has 'M-2006' on its side and '86' on the bumper. A yellow timestamp '2022/3/13' is in the bottom right corner.
340	GX-B1423/20-Y-221417	2022年5月8日	合格	 A photograph of a yellow truck at a construction site, similar to the one above. A person in a red hard hat and camouflage jacket is inspecting the truck. The truck has 'M-2267' on its side. A yellow timestamp '2022/3/13' is in the bottom right corner.

341	GX-B1423/20-Y-221418	2022年5月8日	合格	
342	GX-B1423/20-Y-221419	2022年5月8日	合格	

343	GX-B1423/20-Y-221420	2022年5月8日	合格	 <p>A photograph of a yellow TONLY truck with license plate M-2181. A worker in camouflage gear and a red helmet stands next to the truck. The date 2022/3/13 is visible in the bottom right corner of the photo.</p>
344	GX-B1423/20-Y-221421	2022年5月8日	合格	 <p>A photograph of a yellow TONLY truck with license plate M-2181. Two workers in safety gear (one in a yellow vest and one in camouflage) stand in front of the truck. The date 2022/3/13 is visible in the bottom right corner of the photo.</p>



345	GX-B1423/20-Y-221422	2022年5月8日	合格	
346	GX-B1423/20-Y-221423	2022年5月8日	合格	

347	GX-B1423/20-Y-221424	2022年5月8日	合格	
348	GX-B1423/20-Y-221425	2022年5月8日	合格	

349	GX-B1423/20-Y-221426	2022年5月8日	合格	
350	GX-B1423/20-Y-221427	2022年5月8日	合格	

351	GX-B1423/20-Y-221428	2022年5月8日	合格	 A yellow TONLY truck with the identification number M-2347 is shown in a construction or mining area. A person in a camouflage uniform and red helmet is standing next to the truck. The date stamp '2022/3/13' is visible in the bottom right corner of the photo.
352	GX-B1423/20-Y-221429	2022年5月8日	合格	 A yellow TONLY truck with the identification number M-2357 is shown. Two people are standing in front of the truck: one in a white shirt and yellow safety vest, and another in a camouflage uniform and red helmet. The date stamp '2022/3/14' is visible in the bottom right corner of the photo.

353	GX-B1423/20-Y-221430	2022年5月8日	合格	
354	GX-B1423/20-Y-221431	2022年5月8日	合格	

355	GX-B1423/20-Y-221432	2022年5月8日	合格	
356	GX-B1423/20-Y-221433	2022年5月8日	合格	

357	GX-B1423/20-Y-221434	2022年5月8日	合格	 <p>A yellow TONLY M-2343 truck is parked in a desert-like environment. Two workers are standing in front of the truck. One worker is wearing a blue jacket and a yellow hard hat, while the other is wearing a camouflage jacket and a red hard hat. The truck has 'TONLY' and 'M-2343' written on its side, and the numbers '2', '3', and '4' are visible on the side of the truck's body. A yellow timestamp '2022/3/14' is visible in the bottom right corner of the photo.</p>
358	GX-B1423/20-Y-221435	2022年5月8日	合格	 <p>A yellow TONLY M-2343 truck is parked in a desert-like environment. Two workers are standing in front of the truck. One worker is wearing a black jacket with a yellow reflective vest and a yellow hard hat, while the other is wearing a camouflage jacket and a red hard hat. The truck has 'TONLY' and 'M-2343' written on its side, and the numbers '2', '3', and '4' are visible on the side of the truck's body. A yellow timestamp '2022/3/14' is visible in the bottom right corner of the photo.</p>

359	GX-B1423/20-Y-221436	2022年5月8日	合格	 A yellow TONLY truck with a dump body is parked outdoors. The truck has "TONLY" and "M-2341" written on the side. A person in camouflage clothing is standing near the front. A yellow timestamp "2022/3/14" is visible in the bottom right corner of the photo.
360	GX-B1423/20-Y-221437	2022年5月8日	合格	 A view from the driver's side looking into the cab of a yellow truck. A person wearing a red hard hat and camouflage clothing is sitting in the driver's seat. A yellow timestamp "2022/3/14" is visible in the bottom left corner of the photo.



361	GX-B1423/20-Y-221438	2022年5月8日	合格	 A yellow heavy-duty truck with license plate M-2883 is parked on a dirt lot. Two workers are standing in front of it: one in a yellow safety vest and yellow hard hat, and another in a camouflage jacket and red hard hat. The truck has the number '2383' on its side. A yellow timestamp '2022/3/14' is visible in the bottom right corner of the photo.
362	GX-B1423/20-Y-221439	2022年5月8日	合格	 A yellow heavy-duty truck with license plate M-2883 is parked on a dirt lot. Two workers are standing in front of it: one in a yellow safety vest and yellow hard hat, and another in a camouflage jacket and red hard hat. The truck has the number '378' on its side. A yellow timestamp '2022/3/14' is visible in the bottom right corner of the photo.

363	GX-B1423/20-Y-221440	2022年5月8日	合格	 <p>A photograph showing a yellow truck with license plate M-2372. A person wearing a red helmet and camouflage jacket stands next to the truck. A yellow timestamp '2022/3/14' is visible in the bottom right corner of the image.</p>
364	GX-B1423/20-Y-221441	2022年5月8日	合格	 <p>A photograph showing two people standing in front of a yellow truck with license plate M-2261. One person is wearing a yellow safety vest and a yellow helmet, while the other is wearing a red helmet and camouflage jacket. A yellow timestamp '2022/3/14' is visible in the bottom right corner of the image.</p>

365	GX-B1423/20-Y-221442	2022年5月8日	合格	
366	GX-B1423/20-Y-221443	2022年5月8日	合格	

367	GX-B1423/20-Y-221444	2022年5月8日	合格	 A yellow dump truck with the identification number M-2363 is parked on a dirt surface. Two workers are standing in front of the truck: one wearing a yellow safety vest and a yellow hard hat, and the other wearing a camouflage jacket and a red hard hat. The truck's body has the numbers 2, 3, 6, and 3 on it. A yellow timestamp '2022/3/15' is visible in the bottom right corner of the photo.
368	GX-B1423/20-Y-221445	2022年5月8日	合格	 A yellow dump truck with the identification number M-2375 is parked on a dirt surface. Two workers are standing in front of the truck: one wearing a yellow safety vest and a yellow hard hat, and the other wearing a camouflage jacket and a red hard hat. The truck's body has the numbers 3, 7, and 5 on it. A yellow timestamp '2022/3/15' is visible in the bottom right corner of the photo.

369	GX-B1423/20-Y-221446	2022年5月8日	合格	
370	GX-B1423/20-Y-221447	2022年5月8日	合格	

371	GX-B1423/20-Y-221448	2022年5月8日	合格	
372	GX-B1423/20-Y-221449	2022年5月8日	合格	

373	GX-B1423/20-Y-221450	2022年5月8日	合格	
374	GX-B1423/20-Y-221451	2022年5月8日	合格	

375	GX-B1423/20-Y-221452	2022年5月8日	合格	
376	GX-B1423/20-Y-221453	2022年5月8日	合格	



377	GX-B1423/20-Y-221454	2022年5月8日	合格	
378	GX-B1423/20-Y-221455	2022年5月8日	合格	

379	GX-B1423/20-Y-221456	2022年5月8日	合格	
380	GX-B1423/20-Y-221457	2022年5月8日	合格	

381	GX-B1423/20-Y-221458	2022年5月8日	合格	
382	GX-B1423/20-Y-221459	2022年5月8日	合格	

383	GX-B1423/20-Y-221460	2022年5月8日	合格	
384	GX-B1423/20-Y-221461	2022年5月8日	合格	

385 GX-B1423/20-Y-221462

2022年5月8日

合格

