


109	报告编号	发布日期	结论	影像资料
110	GX-B1306/21-2-23015	2023. 3. 28	所检项目合格。	
111	GX-B1306/21-2-23016	2023. 3. 28	所检项目合格。	
112	GX-B1307/20-2-23013	2023. 3. 28	综合判定：合格。	

113	GX-B1307/20-2-23014	2023. 3. 28	综合判定：合格。	 A worker wearing a grey jacket, black pants, and a yellow hard hat is standing next to a large, open grey metal cabinet. The worker is looking into the cabinet, possibly inspecting or working on its internal components. The date '2023/03/25' is visible in the bottom right corner of the photo.
114	GX-B1307/20-2-23015	2023. 3. 28	综合判定：合格。	 A worker wearing a grey jacket, black pants, and a yellow hard hat is kneeling on the ground next to a large, open grey metal cabinet. The worker is focused on a task, possibly inspecting or working on the cabinet's base. The date '2023/03/25' is visible in the bottom right corner of the photo.
115	GX-B1307/20-2-23016	2023. 3. 28	综合判定：合格。	 Two workers wearing grey jackets and yellow hard hats are working on a large, open grey metal cabinet. One worker is standing and looking into the cabinet, while the other is kneeling on the ground next to it. The date '2023/03/25' is visible in the bottom right corner of the photo.


116	GX-B1307/20-2-23017	2023. 3. 29	综合判定：合格	 A worker in a grey jacket and yellow hard hat is working on a large white electrical cabinet. The worker is wearing blue gloves and is focused on the task. The date stamp in the bottom right corner of the photo reads "2023/03/25".
117	GX-B1307/20-2-23018	2023. 3. 29	综合判定：合格	 A worker in a grey jacket and yellow hard hat is working on a large white electrical cabinet. The worker is wearing blue gloves and is focused on the task. The date stamp in the bottom right corner of the photo reads "2023/03/25".
118	GX-B1307/20-2-23019	2023. 3. 29	综合判定：合格	 Two workers in grey jackets and yellow hard hats are working on a large white electrical cabinet. One worker is wearing blue gloves and is focused on the task. The date stamp in the bottom right corner of the photo reads "2023/03/25".



119	GX-B1307/20-2-23020	2023. 3. 29	综合判定：合格	
120	GX-B1307/20-2-23021	2023. 3. 29	综合判定：合格	
121	GX-B1307/20-2-23022	2023. 3. 29	综合判定：合格	


122	GX-B1307/20-2-23023	2023. 3. 29	综合判定：合格	 <p>2023/03/25</p>
123	GX-B1451/20-2-23103~23121	2023. 3. 30	所检项目合格	 <p>2023/03/15</p>
124	GX-B1451/20-2-23122~23126	2023. 3. 30	所检项目合格	 <p>2023/03/15</p>

125	GX-B1451/20-2-23127~23132	2023. 3. 30	所检项目合格	 2023/03/16
126	GX-B1329/21-2-23037~23062	2023. 3. 30	所检项目合格	 2023/03/16
128	GX-B1321/20-2-23081~23085	2023. 3. 30	所检项目合格	 2023/03/06

129	GX-B1321/20-2-23075~23078	2023. 3. 31	本次共检电力电缆4条，4条电力电缆所检项目合格。			
130	GX-B1312/20-2-23060~23070	2023. 3. 31	本次共检电力变压器11台，11台电力变压器所检项目合格。			
131						

132	GX-B1312/20-2-23071~23075	2023. 3. 31	本次共检电力变压器5台，5台电力变压器所检项目合格。			
133	GX-B1312/20-2-23076~23077	2023. 3. 31	本次共检电力变压器2台，2台电力变压器所检项目合格。			
134	GX-B1328/20-2-23051	2023. 3. 31	本次共检绝缘手套2双，2双所检项目合格。			

135	GX-B1328/20-2-23052	2023. 3. 31	本次共检绝缘鞋1双, 1双所检项目合格。			
136	GX-B1328/20-2-23053	2023. 3. 31	本次共检验电器1支, 所检项目合格。			
137	GX-B1328/20-2-23054	2023. 3. 31	本次共检绝缘杆1组, 1组所检项目合格。			

138	GX-B1312/20-2-23078~23081	2023. 3. 31	本次共检电力变压器4台，4台电力变压器所检项目合格。			
139						
140	GX-B1328/20-2-23055	2023. 3. 31	本次共检携带式接地和接地短路装置3组，3组所检项目合格。			


141	GX-B1328/20-2-23056	2023. 3. 31	本次共检验电器5支，5支所检项目合格。	
142	GX-B1310/21-2-23036	2023. 3. 30	未发现超过Φ2mm当量直径的缺陷。	
143	GX-B1415/22-2-23004	2023. 3. 30	综合判定：合格。	

144	GX-B1313/21-2-23041	2023. 3. 30	所检项目合格。	
145	GX-B1350/21-2-23005	2023. 3. 29	所检项目合格	
146	GX-B1350/21-2-23006	2023. 3. 29	所检项目合格	

147	GX-B1350/21-2-23007	2023. 3. 29	所检项目合格		
148	GX-B1350/21-2-23008	2023. 3. 29	所检项目合格		
149	GX-B1310/21-2-23037	2023. 3. 29	符合标准要求		

150	GX-B1310/21-2-23038	2023. 3. 29	符合标准要求	 2023/03/14	
151	GX-B1350/21-2-23011	2023. 3. 31	所检项目合格	 2023/03/14	
152	GX-B1350/21-2-23014	2023. 3. 31	所检项目合格	 2023/03/16	

153	GX-B1350/21-2-23015	2023. 3. 31	所检项目合格		
154	GX-B1350/21-2-23012	2023. 3. 31	所检项目合格		
155	GX-B1350/21-2-23013	2023. 3. 31	所检项目合格		

156	GX-B1329/21-2-23063~23070	2023. 3. 31	所检项目合格	
157	GX-B1354/20-2-23003	2023. 3. 31	符合规定	
158	GX-B1310/21-2-23034	2023/3/30	未发现超过 $\phi 2\text{mm}$ 当量直径的缺陷	

159	GX-B1310/21-2-23035	2023/3/30	未发现超过 $\phi 2\text{mm}$ 当量直径的缺陷		
160	GX-B1428/21-2-23034	2023/3/30	无缺陷痕迹显示		
161	GX-B1428/21-2-23035	2023/3/30	无缺陷痕迹显示		

162	GX-B1380/20-2-23003	2023/3/31	所检项目合格	
163	GX-B1380/20-2-23004	2023/3/31	所检项目合格	